



Kay Ivey  
GOVERNOR

**ALABAMA**  
**DEPARTMENT OF TRANSPORTATION**

**AERONAUTICS BUREAU**  
**1409 COLISEUM BOULEVARD**  
**MONTGOMERY, ALABAMA 36130**

PHONE (334) 242-6820  
FAX (334) 353-6540



John R. Cooper  
TRANSPORTATION DIRECTOR

October 19, 2017

Mr. Clint Shelton, Chairman  
Decatur-Athens Airport Authority  
P.O. Box 1182  
Decatur, Alabama 35612

**Subject: Annual Inspection Report**  
**Pryor Field Regional Airport (DCU)**

Dear Mr. Shelton:

An inspection of the Pryor Field Regional Airport was conducted by personnel of the Alabama Department of Transportation Aeronautics Bureau on October 16, 2017. The purpose of the inspection was to update the information currently on file regarding the airport and to ascertain compliance with the rules and regulations of the Alabama Department of Transportation governing licensed public-use airports within the State of Alabama.

Attached you will find a copy of the Annual Inspection Report for the airport. As noted in the report, the airport **meets** the requirements for the issuance of an operating license. However, there are several maintenance items that should be addressed as soon as possible. A signed license certificate will be mailed separately within several weeks.

If you should have any questions concerning the inspection or corrective actions, please do not hesitate to contact the Aeronautics Bureau at (334) 242-6820.

Sincerely,

John C. Eagerton IV, D.P.A.  
Chief, Aeronautics Bureau

Copy: Mr. Rans Black, FAA ADO  
Mr. Wes Mittlesteadt, FAA ADO  
Ms. Courtney Tomberlin, Garver

# Annual Inspection Report

## October 16, 2017



***Pryor Field Regional Airport (DCU)  
Decatur, Alabama***

**Annual Inspection Report  
Pryor Field Regional Airport (DCU)  
Decatur, Alabama**

October 16, 2017

**TABLE OF CONTENTS**

<b>INTRODUCTION</b>	<b>PAGE 1</b>
<b>INSPECTION METHODOLOGY</b>	<b>PAGE 1</b>
<b>LICENSE STATUS</b>	<b>PAGE 1</b>
<b>APPROACH &amp; DEPARTURE PATHS</b>	<b>PAGE 2</b>
<b>PRIMARY SURFACE</b>	<b>PAGE 3</b>
<b>RUNWAY SAFETY AREA</b>	<b>PAGE 4</b>
<b>AIRPORT MARKINGS</b>	<b>PAGE 4</b>
<b>WIND DIRECTION INDICATOR</b>	<b>PAGE 5</b>
<b>AIRPORT LIGHTING</b>	<b>PAGE 6</b>
<b>RUNWAY, TAXIWAY AND APRON CONDITIONS</b>	<b>PAGE 7</b>
<b>FUELING AREA REQUIREMENTS</b>	<b>PAGE 8</b>
<b>PROHIBITED ACTIVITIES</b>	<b>PAGE 9</b>
<b>SUMMARY</b>	<b>PAGE 10</b>
<b>APPENDIX 1</b>	<b>PAGE 11</b>

# Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama

October 16, 2017

## **Introduction:**

**Code of Alabama 23-1-357(c).** The department may perform such acts, issue and amend such orders and make, promulgate, or amend general or special rules, regulations, and procedures and establish minimum standards, consistent with the provisions of this article as it shall deem necessary to carry out the provisions of this article and to perform its duties hereunder, all commensurate with and for protecting and insuring the public interest, health, welfare, and safety. (Act 2000-220, 10.)

In accordance with the provisions of the Code of Alabama 23-1-357(c) an inspection of the Pryor Field Regional Airport was conducted by Mr. Adam Foutz of the Alabama Department of Transportation Aeronautics Bureau on October 16, 2017.

The corrective actions that may be prescribed in this inspection report do not relieve the airport owner from compliance with any other Federal, State or local laws, ordinances or regulations that may be applicable. It is the responsibility of the airport owner to be aware of and obey all Federal, State or local laws, ordinances or regulations that may have a bearing on the corrective actions that may be specified in this report.

## **Inspection Methodology:**

The inspection of the required State Approach/Departure Path and Federal Runway Protection Zones was accomplished using approved engineering methods and equipment. The angles, locations and heights of trees or other objects within these areas were derived using a Theodolite and electronic distance measuring device.

All other areas of the inspection were conducted visually and photographed for reference purposes.

## **License Status:**

**Code of Alabama 23-1-375(a).** ...a person or municipality may not operate an airport, restricted landing area, or other air navigation facility without a license issued by the department.

Based upon the findings of the inspection conducted on October 16, 2017, it was determined that the airport **meets** the requirements for the issuance of an operating license.



# Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama

October 16, 2017

*The inspection was conducted on the airport under the provisions of the Administrative Code for the following areas:*

## **1. Approach and Departure Paths** **Administrative Code 450-9-1-.12(1)** (See Appendix 1)

### **State Licensing Standards:**

- For all hard surface runways, the approach and departure path begins 200 feet from the runway end (runway threshold).
- For all hard surface runways with a displaced threshold, the approach and departure path begins at the point of displacement (See Appendix 2).
- The approach and departure path for all runways slopes up at a ratio of 20:1.
- All penetrations of the approach and departure paths, whether natural or manmade, constitute an obstruction to navigation and must be removed.
- The land beneath the approach and departure path must be controlled by the airport owner. This is accomplished by ownership of the property in fee simple or by written perpetual agreement with the owner of the land.

### **Inspection Results:**

- Runway 18 - No obstructions (See Photo #1).
- Runway 36 - No obstructions (See Photo #2).

**Photo #1 – Runway 18 Approach Path**



**Annual Inspection Report  
Pryor Field Regional Airport (DCU)  
Decatur, Alabama**

October 16, 2017

**Photo #2 – Runway 36 Approach Path**



**2. Primary Surface  
Administrative Code 450-9-1-.12(2)**

**State Licensing Standards:**

- Primary Surface (See Appendix 1): The primary surface is 250 feet wide, centered on the runway centerline and extends 200 feet past the end of the marked runway. The primary surface is required to be free of all obstructions, manmade or natural. The only allowable objects are runway lights, guidance signs, or navigation equipment that by function is required to be within the primary surface boundaries.

**Inspection Results:**

- The primary surface meets state licensing requirements.

**Annual Inspection Report  
Pryor Field Regional Airport (DCU)  
Decatur, Alabama**

October 16, 2017

**3. Runway Safety Area  
Administrative Code 450-9-1-.12(3)**

**State Licensing Standards:**

- Runway Safety Area (Appendix 1): All runways are required to maintain an obstruction free area adjacent to each runway. This area is 120 feet wide, centered on the runway centerline, and extends for a distance of 200 feet past the runway end. The area must be compacted and graded smooth with no ruts, humps, depressions or other potentially hazardous surface variations. The slope along the longitudinal centerline shall not exceed a rise or fall of three percent in elevation relative to the runway end elevation. The lip from the top of the pavement to the grade adjacent to the runway should not exceed 3 inches.

**Inspection Results:**

- The runway safety area meets state licensing requirements.

**4. Airport Markings  
Administrative Code 450-9-1-.12(4)**

**State Licensing Standards:**

- Airport Markings: All runways are required to be marked in a manner identifying the boundaries of the landing areas. The runway markings must be painted white and be maintained in a legible condition.

**Inspection Results:**

- The runway markings are in **FAIR** condition (See Photo #3).



**Annual Inspection Report  
Pryor Field Regional Airport (DCU)  
Decatur, Alabama**

October 16, 2017

**Photo #3 – Runway 18 PIR Markings**



**Required Action:**

- The current markings could possibly be cleaned with a water and bleach mixture followed by power washing. If the markings are unable to be cleaned, new markings should be applied in accordance with FAA AC 150/5340-1L.

**5. Wind Direction Indicator  
Administrative Code 450-9-1-.12(5)**

**State Licensing Standards:**

- Wind Direction Indicators: All airports are required to have an operational wind direction indicator. It must be installed in a highly visible area and free from obstructions to ensure true wind direction and velocity. Night operations require the indicator be lighted.



# Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama

October 16, 2017

## **Inspection Results:**

- The wind direction indicator (wind sock) is in GOOD condition (See Photo #4).

**Photo #4 – Wind Direction Indicator**



## **6. Airport Lighting Administrative Code 450-9-1-.12(6)**

### **State Licensing Standards:**

- Airport Lighting: Runway lights and a lighted wind direction indicator are required for night operations. A rotating beacon is suggested. All runway, threshold, and taxiway lighting shall be maintained in operational condition and shall not be obscured by natural growth such as grass and/or weeds.

# Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama

October 16, 2017

## **Inspection Results:**

- An inspection of the lighting system had the following results:

Runway Lights	0 inoperable
Taxiway Lights	0 inoperable
Threshold Lights	0 inoperable
REIL	RWY 36 inoperable
PAPI	RWY 36 inoperable

## **Required Action:**

- Repair/replace all inoperable lighting components.

## **7. Runway, Taxiway and Apron Conditions** **Administrative Code 450-9-1-.12(7)**

### **State Licensing Standards:**

- Runway, Taxiway and Apron Conditions: All airport pavement surfaces associated with aircraft operations must be kept smooth and free of any defect or obstruction that could damage an aircraft. The lip of the airport pavement surfaces must not exceed three (3) inches in elevation from the top of the pavement to the shoulder. The drop should only be enough to allow sufficient drainage and not pose a control problem for aircraft exiting the runway. The aircraft parking apron is for the operation and parking of aircraft only and should be smooth and free of obstructions or defects that could cause damage to aircraft during operations.

### **Inspection Results:**

- An inspection of the airport pavement surfaces had the following results:

<b>Ramp</b>	<b>GOOD</b>
<b>Taxiways</b>	<b>GOOD</b>
<b>Taxilanes</b>	<b>POOR.</b> The taxilanes are experiencing cracking, rutting, and raveling with vegetation appearing through the cracks (See Photo #5).
<b>Runway</b>	<b>GOOD</b>

# Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama

October 16, 2017

**Photo #5 – Taxilane Cracking and Vegetation**



**Required Action:**

- The airport should contact their airport consultant to plan future pavement rehabilitation in this area.

## **8. Fueling Area Requirements** **Administrative Code 450-9-1-.12(8)**

**State Licensing Standards:**

- Signs should be posted prohibiting open flames or smoking in fueling areas. The fueling facility must be labeled indicating the type fuel being dispensed.
- Grounding cables must be available.
- A fire extinguisher approved for the purpose of extinguishing petroleum product fires available during all fueling operations.
- Serviceable hoses and connections that would preclude a rupture or leaking of fuel.



# **Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama**

October 16, 2017

## **Inspection Results:**

- The fuel system meets the requirements established by the Alabama Department of Transportation. However, the State of Alabama Department of Agriculture and Industries may have additional requirements for fueling systems that were not considered during this inspection.

## **9. Prohibited Activities Administrative Code 450-9-1-.16**

### **State Licensing Standards:**

- Prohibited Activities: The use of any portion of the aircraft operations area, or airport property within the boundaries of the imaginary surfaces of a licensed airport for any purpose other than the operation of aircraft shall be deemed a non-aeronautical activity and is prohibited.

## **Inspection Results:**

- No prohibited activities were observed at the time of inspection.

**Annual Inspection Report  
Pryor Field Regional Airport (DCU)  
Decatur, Alabama**

October 16, 2017

**Summary**

The table below summarizes items noted in this report.

**INSPECTION SUMMARY**


<b>Inspection Area</b>	<b>Violation/Maintenance</b>	<b>Corrective Action</b>
Airport Markings	Maintenance	Clean or replace markings in accordance with FAA AC 150/5340-1L.
Airport Lighting	Maintenance	Replace/repair inoperable lights.
Airport Surfaces	Maintenance	Contact airport consultant.

Please contact the Aeronautics Bureau of the Alabama Department of Transportation at (334) 242-6820 with questions concerning the Annual Inspection Report.

# Annual Inspection Report Pryor Field Regional Airport (DCU) Decatur, Alabama

October 16, 2017

Approach and Departure Path Dimensions			
Inner Width	Outer Width	Length	Acreage
250 Feet	450 Feet	1,000 Feet	8.04 Acres
Primary Surface Dimensions			
250 Feet Wide Centered Along Runway Centerline			
Extending 200 Feet Past the Runway End			
Runway Safety Area Dimensions			
120 Feet Wide Centered Along Runway Centerline			
Extending 200 Feet Past the Runway End			



## APPENDIX 1