

# Alabama Statewide Airport Pavement Management Program Update



**Robbins Field (20A)**

**Final Report**

**February 2022**



Submitted to

**Alabama Aeronautics Bureau**

Submitted by



**All About Pavements, Inc (API)**  
[www.allaboutpavements.com](http://www.allaboutpavements.com)

Pavement Management – Evaluation – Testing – Design

**ALABAMA STATEWIDE AIRPORT PAVEMENT MANAGEMENT  
PROGRAM UPDATE**

**Robbins Field (20A)**

FINAL REPORT

Prepared For:

Alabama Aeronautics Bureau  
1409 Coliseum Blvd.  
Montgomery, AL 36110

Prepared By:

ALL ABOUT PAVEMENTS, INC.  
205 Ramblewood Drive  
Chatham, Illinois 62629

February 2022

This Page Intentionally Left Blank



## Executive Summary

The Aviation Inc. team, which included All About Pavements, Inc., (API) was awarded a contract by the Alabama Department of Transportation's Aeronautics Bureau (ALDOT) in 2018 to update the existing Alabama Statewide Airport Pavement Management Program (APMP). The scope of this project includes the airside pavement network at Robbins Field (20A).


The following APMP tasks were completed to achieve the project objectives at 20A:

- Ø Update the PAVER work history with records review information provided by ALDOT
- Ø Conduct a visual pavement condition survey of the airfield pavements
- Ø Update the PAVER database with inventory and condition data
- Ø Update Maintenance and Rehabilitation (M&R) policies and unit costs
- Ø Develop a 7-Year Pavement Capital Improvement Program (PCIP) with associated cost estimates

### ES.1 Pavement Inventory

There are 6 branches and 7 sections within 20A's pavement network with a total surface area of approximately 0.47 million square feet (sf). Figure ES-1 shows the distribution of the pavement network by surface type and branch use.

**Figure ES-1: Pavement Area (sf) by Surface Type and Branch Use.**



### ES.2 Pavement Condition

Visual pavement inspections were conducted in October 2018 using the Pavement Condition Index (PCI) method as specified in ASTM D5340-12 and FAA AC 150/5380-6C. The PCI is a numerical rating scale from 0 to 100 that provides a measure of the pavement's functional surface condition. The overall area-

weighted network PCI (AW PCI) for the 20A pavement network is 76, representing a “Satisfactory” condition. The network area-weighted pavement age (AW Age) is 13 years.

Table ES-1 is a listing of the section PCI values and ratings.


**Table ES-1: 20A Section PCI Values and Ratings.**

Branch ID	Name	Section ID	Surface	Area (sf)	PCI	PCI Category
A01	Apron 01	01	AC	55,473	68	Fair
RW0624	Runway 06-24	01	AC	327,600	78	Satisfactory
RW0624	Runway 06-24	02	AC	8,640	78	Satisfactory
TC01	Taxiway Connector 01	01	AC	8,563	75	Satisfactory
TC02	Taxiway Connector 02	01	AC	7,014	72	Satisfactory
THANG01	Taxiway Hangar 01	01	AC	57,374	71	Satisfactory
TTRW05	Taxiway Turnaround RW 05	01	AC	4,415	86	Good

### ES.3 Pavement Maintenance and Repair Funding Levels

The PAVER database was updated with 2018 condition data, maintenance and repair (M&R) policies, and unit costs; which were then used to evaluate the effect of multiple funding levels on the overall future pavement condition. Figure ES-2 presents the forecasted 20A network PCI values for each funding level.

**Figure ES-2: M&R Funding Levels.**





### ES.4 Pavement Capital Improvement Program (PCIP)

The analysis output from the unlimited funding budget scenario was used as a starting point in developing the PCIP. For this scenario, sections were grouped into projects to allow for a logical construction sequence. Table ES-2 summarizes the 7-year PCIP, which has an estimated total cost of approximately \$2.6 million. These recommendations are based on a network-level evaluation. Project-level evaluations should be conducted prior to developing design and bid package documents.

**Table ES-2: Summary of Pavement Capital Improvement Program.**

Project Year	CIP Project	Total Project Cost	Total Project Area (sf)	AWPCI Before	AWPCI After
2025	20A_25-01_Runway 06-24 Rehabilitation	\$1,801,736	340,655	70	100
2026	20A_26-01_Apron & TW Hangar Rehabilitation	\$783,718	128,424	57	100
<b>Total</b>		<b>\$2,585,454</b>			

In addition to the major rehabilitation needs that are identified in the PCIP, PAVER was used to develop maintenance activities to repair specific PCI distresses in Year 1. The estimated costs for these maintenance activities are \$14,881 as summarized in Table ES-3.

**Table ES-3: Summary of Localized Maintenance Plan.**

Policy	Work Description	Work Quantity	Work Unit	Work Cost
Preventive	Crack Sealing - AC	3,169	Ft	\$12,517
	Patching - AC Full-Depth	94	SqFt	\$2,364
<b>Total</b>				<b>\$14,881</b>

## TABLE OF CONTENTS

<b>1</b>	<b>INTRODUCTION .....</b>	<b>1-1</b>
1.1.	OVERVIEW .....	1-1
1.2.	WORK SCOPE .....	1-1
1.3.	PAVEMENT MANAGEMENT CONCEPT .....	1-2
<b>2</b>	<b>AIRFIELD PAVEMENT INVENTORY .....</b>	<b>2-1</b>
2.1.	INTRODUCTION .....	2-1
2.2.	PAVEMENT INVENTORY .....	2-1
2.3.	CLIMATIC CONDITIONS.....	2-1
2.4.	PAVEMENT NETWORK DEFINITION .....	2-2
2.5.	INVENTORY SUMMARY.....	2-3
<b>3</b>	<b>PAVEMENT CONDITION.....</b>	<b>3-1</b>
3.1.	INTRODUCTION .....	3-1
3.2.	PAVEMENT CONDITION RATING METHODOLOGY.....	3-1
3.3.	DISTRESS TYPES .....	3-2
3.4.	ADDITIONAL PCI-BASED INDICES.....	3-3
3.5.	PCI SURVEY RESULTS.....	3-4
3.6.	PCC PAVEMENTS .....	3-5
<b>4</b>	<b>PAVEMENT CAPITAL IMPROVEMENT PROGRAM.....</b>	<b>4-1</b>
4.1.	INTRODUCTION .....	4-1
4.2.	PERFORMANCE MODELING .....	4-1
4.3.	CRITICAL PCI VALUES.....	4-3
4.4.	M&R POLICIES AND UNIT COSTS.....	4-3
4.5.	PAVEMENT CIP DEVELOPMENT .....	4-4
4.6.	PAVEMENT CAPITAL IMPROVEMENT PROGRAM.....	4-6



## LIST OF TABLES

Table 2.1: Average Annual Temperatures and Rainfall for 20A.....	2-2
Table 2.2: PCI Sampling Rate for AC Surfaces.....	2-3
Table 2.3: 20A Pavement Branches.....	2-3
Table 2.4: 20A Pavement Age.....	2-3
Table 3.1: Pavement Condition Index Rating Scale.....	3-2
Table 3.2: Section PCI.....	3-5
Table 4.1: M&R Activities and Unit Costs.....	4-4
Table 4.2: Summary of M&R Funding Level Analyses.....	4-6
Table 4.3: Summary of 7-Year PCIP by Project.....	4-7
Table 4.4: Summary of 7-Year PCIP by Project and Section.....	4-7
Table 4.5: Summary of Year-1 Maintenance Plan.....	4-8

## LIST OF FIGURES

Figure 1.1: Pavement Management Concept.....	1-2
Figure 2.1: Robbins Field.....	2-1
Figure 2.2: 20A Pavement Area by Surface Type.....	2-4
Figure 2.3: 20A Pavement Area by Branch Use.....	2-4
Figure 3.1: FOD Potential Rating Scale.....	3-3
Figure 3.2: Pavement Condition by Branch Use.....	3-4
Figure 3.3: Pavement Condition by Percent of Area.....	3-4
Figure 4.1: PCI Forecasting.....	4-2
Figure 4.2: Family Curves.....	4-2
Figure 4.3: Budget Analysis Process.....	4-5
Figure 4.4: M&R Funding Levels.....	4-5



## APPENDICES

- Appendix A:** Pavement Inventory Report
- Appendix B:** PMP Maps
- B1: Inventory Maps
    - B1A: Branch Identification
    - B1B: Section Identification
    - B1C: Sample Unit Layout
    - B1D: Pavement Type
    - B1E: Branch Use
    - B1F: Pavement Age
  - B2: Surface Condition Maps
    - B2A: 7-Color PCI
    - B2B: 3-Color PCI
    - B2C: FOD Rating
    - B2D: Survey Photo Locations
  - B3: Pavement Capital Improvement Program (PCIP) Maps
    - B3A: 2027 Forecasted PCI without PCIP
    - B3B: Repair Type
    - B3C: PCIP Recommendations
- Appendix C:** Overview of Pavement Distresses
- Appendix D:** Detailed Pavement Condition Data (electronic version only)
- Appendix E:** Distress Summary Report
- Appendix F:** Pavement Condition Reports
- F1: Section Forecasted Pavement Condition Rating
  - F2: Branch PCI Rating
  - F3: Branch FOD Rating
- Appendix G:** Safety and Preventive Maintenance Policies
- Appendix H:** M&R Unit Costs
- Appendix I:** Pavement Capital Improvement Program (PCIP)
- I1: CIP Summary
  - I2: Year 1 Maintenance Plan
- Appendix J:** USB Thumb Drive – FINAL ONLY
- Final Report in PDF format
  - Geo-referenced Field Photos

# 1 Introduction

## 1.1. Overview

The Alabama Department of Transportation's Aeronautics Bureau (ALDOT) is responsible for preserving and enhancing Alabama's air transportation system, which consists of 72 airports throughout the State. ALDOT implemented an Airport Pavement Management Program (APMP) in 2008 using the PAVER system. ALDOT awarded a project in 2018 to Jviation Inc. (Jviation) to update the System Plan and conduct an Economic Analysis for the Alabama airports. The scope of work also included an update of the APMP for 59 airports, which was conducted by All About Pavements, Inc., (API), a Jviation team member.

With this update of the APMP, the Alabama airports continue to be eligible for FAA funding for major pavement rehabilitation work under the Airport Improvement Program (AIP) since an APMP meets the pavement maintenance management requirements described in Appendix A of AC 150/5380-6C.

This report discusses the evaluation of the airside pavements at Robbins Field (20A), the current and forecasted pavement condition, and the development of the Pavement Capital Improvement Program (PCIP).

## 1.2. Work Scope

The goals of the Alabama Statewide Airport Pavement Management Update program are as follows:

- Ø Conduct a visual pavement inspection of the asphalt surfaced pavements for 59 of the 72 public use airports in Alabama.
- Ø Based on the visual inspection analysis results, develop a 7-year PCIP for each airport.

The scope of work is as shown below:

- Ø Conduct a Records Review
- Ø Update Pavement Network Definition
- Ø Conduct Pavement Condition Surveys
- Ø Update and customize existing APMP PAVER database
- Ø Develop PCIP and associated project cost estimates
- Ø Prepare Draft and Final Reports
- Ø Develop a web-based viewer for reporting APMP data

As required in the Scope of Work, a detailed pavement condition survey was not conducted for any Portland Cement Concrete (PCC) aprons and PCC taxiways longer than 2,000 ft. Instead, a condition rating of "Good", "Fair", or "Poor" was assigned based on the overall pavement condition.

The deliverable products include a PAVER 7.0 database, individual airport evaluation reports, a statewide summary report, and the web viewer. The 20A report will be one of the 59 individual airport reports that will be available on ALDOT's website.




### 1.3. Pavement Management Concept

An APMP provides an integrated framework for comprehensive evaluation and decision making for managing airfield pavements. The essential components of an effective APMP provide for an objective evaluation of the condition of existing pavements, identification of short-term and long-range major rehabilitation work, necessary improvements in the pavement structural capacity, and the recurring maintenance work that should be completed each year. The APMP will also provide a budget for each of these types of pavement construction.

Historically, most organizations have made maintenance decisions based on past experience, without the benefit of documented data or analysis. This practice does not encourage life cycle cost analysis, nor the evaluation of cost effectiveness of alternate scenarios, and can lead to the inefficient use of funds. With limited allocated funding for Maintenance and Repair (M&R) Program projects, a defined procedure for setting priorities and schedules that will maximize the funds available is more important than ever.

In examining the lifespan of a 20-year pavement, a “Good” to “Fair” condition rating may last only 5 to 15 years. After that point, the rate of deterioration of pavements accelerates sharply as the age of the pavement increases, and within five years, the pavement may deteriorate to the point of failure. In order to extend pavement life, maintenance and repairs need to be scheduled and performed before the pavement surface declines to a “fair” condition. The point at which rehabilitation can be done before the steep decline occurs is called the “critical PCI”, and is generally considered to occur when the Pavement Condition Index (PCI) is between 60 and 70 for general aviation airports. If the work is done before deterioration accelerates, the cost of rehabilitation can be reduced as shown in Figure 1.1.

Figure 1.1: Pavement Management Concept.



## 2 Airfield Pavement Inventory

### 2.1. Introduction

20A is a General Aviation (GA) airport located approximately 5 miles north east of Oneonta. The airport and is owned and operated by the City of Oneonta and Blount City. Figure 2.1 shows an aerial image of the airport.

**Figure 2.1: Robbins Field.**



(Source: Google Earth)

### 2.2. Pavement Inventory

20A consists of one runway, a parallel taxiway, two connector taxiways, and an apron. The total pavement area is approximately 0.47 million square feet. All pavements at 20A are Asphalt Concrete (AC) surfaced. A complete listing of the pavement sections is included in Appendix A. Runway 06-24 is 4,203 ft. long and 80 ft. wide.

A records search was undertaken to identify any preservation or rehabilitation work that has occurred at 20A since the last APMP update in 2009. The following records that were provided by ALDOT were reviewed, and the PAVER database was updated with work history information:

- Ø Runway 06-24 Seal Coat, 2019
- Ø Taxiway and Apron Slurry Seal, 2019

### 2.3. Climatic Conditions

Table 3.1 provides a summary of the climatic data for the geographic region that includes 20A. As the table shows, the pavements at 20A are exposed to freeze-thaw cycles in January. The mean air temperature for January ranges from an average low of 31 degrees °F to an average high of 50 degrees °F. The average annual rainfall at 20A is near 58 inches.



**Table 2.1: Average Annual Temperatures and Rainfall for 20A.**

	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
High Temp (°F )	50	55	63	71	78	85	89	88	83	73	63	54
Low Temp (°F )	31	34	41	47	56	64	68	67	61	48	40	33
Precip. (in )	6.1	5.2	6.3	5.2	4.8	4.6	5.2	3.2	4.5	3.5	4.6	4.8

Source: [www.intellicast.com](http://www.intellicast.com)

#### 2.4. Pavement Network Definition

A key element in developing an APMP system is defining the pavement network, which is the process of dividing an agency’s pavements into a hierarchical order that facilitates inspection and M&R planning. The 20A network (e.g. all airside pavements) is then divided into branches, which are a readily identifiable part of the pavement system and have distinct functions. For airports, branches typically consist of individual runways, taxiways and aprons. Figure B1A in Appendix B shows the branches at 20A.

Once branches have been defined, pavement evaluation and analysis techniques require the airfield pavement system to be broken up into discrete sections. A pavement “section” is the smallest management unit that is used when considering the application and selection of maintenance and rehabilitation (M&R) treatments, and is defined in Section 2.1.8 of ASTM D 5340-12 as *“a contiguous pavement area having uniform construction, maintenance, usage history, and condition. A section should also have the same traffic volume and load intensity.”* A complete list of the pavement inventory and the corresponding section designations are included in Appendix A. Figure B1B presents the section layout.

To facilitate the visual survey of the airside pavement, each section is further subdivided into conveniently defined sub-section areas, or sample units. Similar sizing is critical as studies have found that maintaining the size of the sample units to within 40 percent of the established norm may reduce the standard error of the average PCI values. To meet that criteria, ASTM recommends that sample units for asphalt pavements be 5,000 square feet ( $\pm 2,000$ ).

Table 2.2 was used as a guideline in developing sampling rates that reflect typical rates that are used for other large pavement networks. In general, this sampling rate will not provide a 95% confidence level with a standard error of 5 PCI points. A higher level of sampling is recommended before a project-level rehabilitation design is developed for a pavement section or facility.

Sample units that include a one-time occurrence of a distress (i.e. a large patch) or an unusual severity or quantity of a distress seen elsewhere, were designated as “additional” sample units as described in the ASTM D5340 PCI procedure. This allows the PCI to be calculated without extrapolating the aberrant distress throughout the section as a whole. In Appendix B, Figure B1C shows the sample unit layout for 20A.

**Table 2.2: PCI Sampling Rate for AC Surfaces.**

Total Samples	Samples to Inspect
1	1
2	2
3 – 6	3
7 – 13	4
14 – 39	5
> 39	15 percent, but less than 12

## 2.5. Inventory Summary

There are 6 branches (facilities) at 20A that include 7 pavement sections and a total area of approximately 0.47 million square feet of paved surfaces, as shown in Table 2.3.

**Table 2.3: 20A Pavement Branches.**

Branch ID	Branch Name	Branch Use	Area, sf	Number of Sections
A01	Apron 01	APRON	55,473	1
RW0523	Runway 06-24	RUNWAY	336,240	2
TC01	Taxiway Connector 01	APRON	8,563	1
TC02	Taxiway Connector 02	APRON	7,014	1
THANG01	Taxiway Hangar 01	TAXIWAY	57,374	1
TTRW05	Taxiway Turnaround RW 05	RUNWAY	4,415	1
<b>Total</b>			<b>469,079</b>	<b>7</b>

Table 2.4 shows the distribution of airfield pavement by age with the area-weighted age being 13 years for all airside pavements at 20A.

**Table 2.4: 20A Pavement Age.**

Age (Years)	Number of Sections	Percent of Area	Area, sf
0 – 5	0	0	0
6 – 10	3	73	340,655
11 – 15	2	13	62,487
16 – 20	0	0	0
> 20	2	14	65,937

Figure 2.2 shows the distribution by surface type. Figure 2.3 presents the distribution by pavement use (e.g. runway, taxiway, and apron).



Figure 2.2: 20A Pavement Area by Surface Type.





Figure 2.3: 20A Pavement Area by Branch Use.



Maps B1D, B1E, and B1F show the pavement type, branch use, and pavement age, respectively.

## 3 Pavement Condition

### 3.1. Introduction

A visual PCI survey of the airside pavements at 20A was conducted in order to assist in the development of a realistic PCIP. The PCI survey measures and records pavement distresses that exist within each of the inspected sample units. This survey was conducted in October 2018 by a two 2-person team. The survey was performed in accordance with the methods described in ASTM D 5340-12 and FAA AC 150/5380-7B, using the sampling rates from Chapter 2 of this API report.

During the pavement survey, Quality Control (QC) and data verification were performed on both the individual distresses and the calculated section PCI values. QC included the following activities;

- Ø Review of distress quantities to identify data entry errors (100% review at the sample unit level). General guidance was used from ASTM D5340-12, section 13, which addresses the precision of distress quantities that are recorded during PCI surveys.
- Ø Duplicate surveys were performed to ensure consistency between each of the inspectors in a 2-person PCI survey team.

### 3.2. Pavement Condition Rating Methodology

The PCI is a measure of the pavement's functional surface condition. It provides insight into the causes of each distress, and whether the distress is primarily caused by load, climatic conditions, and other material related deficiencies. The PCI is a numerical rating (on a scale of 0 to 100) that is based on the type, severity and quantity of each distress that is found in an inspected sample unit.

The PCI survey results are displayed using seven categories and ratings in accordance with the ASTM, but can also be presented using a simplified 3-category rating system for use in comparing with other distress related indices, as shown in Table 3.1.





**Table 3.1: Pavement Condition Index Rating Scale.**

	Simplified PCI Color Legend	ASTM PCI Color Legend	PCI Range	PCI Ratings and Definition
GOOD	[Green]	[Green]	86-100	<u>GOOD</u> : Pavement has minor or no distresses and should require only routine maintenance.
		[Light Green]	71-85	<u>SATISFACTORY</u> : Pavement has scattered low-severity distresses that should require only routine maintenance.
FAIR	[Yellow]	[Yellow]	56-70	<u>FAIR</u> : Pavement has a combination of generally low- and medium-severity distresses. Near-term maintenance and repair needs may range from routine to major.
POOR	[Red]	[Pink]	41-55	<u>POOR</u> : Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. Near-term M&R needs range from routine to major. requirement for
		[Red]	26-40	<u>VERY POOR</u> : Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance & operational problems. Near-term M&R needs will be major.
		[Dark Red]	11-25	<u>SERIOUS</u> : Pavement has mainly high-severity distresses that cause operational restrictions; immediate repairs are needed.
		[Grey]	0-10	<u>FAILED</u> : Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.

### 3.3. Distress Types

The ASTM D5340 standard considers 17 distresses, which tend to fall into one of the following four cause categories:

- Ø Load related: AC distresses include alligator cracking, corrugation, depression, polished aggregate, rutting and slippage cracking; PCC distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping and joint spalling.
- Ø Climate and durability related: AC distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, raveling, and weathering; PCC distresses include blow-ups, “D” cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint and corner spalling.
- Ø Moisture & Drainage related: AC distresses include alligator cracking, depressions, potholes and swelling; PCC distresses include corner breaks, divided slabs and pumping.
- Ø Other factors: Oil spillage, jet blast erosion, bleeding, patching and concrete slab joint faulting.

As described above, distress may have more than one cause. For example, depressions may be caused by incorrect compaction during construction, or by subgrade softening due to environmental factors. In addition, a distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual causes of the distress.


Distress descriptions provided in Appendix C were taken from the “PCI Field Manual,” developed by the U.S. Army Construction Engineering Research Lab (CERL), latest edition. Appendix C provides a detailed explanation of each type of AC and PCC surface distress.

### 3.4. Additional PCI-based Indices

The distress data used to compute PCI can also be used to calculate additional indices that are helpful in understanding the condition of the pavement and developing PCIP recommendations. One additional index that was computed is the Foreign Object Damage (FOD) potential index.

The FOD index was developed by the US Air Force and is described in detail in the US Army Corp of Engineers Engineering Technical Letter (ETL) 04-09, Pavement Engineering Assessment (EA) Standards. Loose objects on an airfield pavement surface resulting from pavement distresses can be detrimental to aircraft engines, specifically engines that are low to the ground. The objects are ingested into the engines causing costly damage and presenting a safety hazard. Not all pavement distresses create a FOD potential. Therefore, an additional index was identified that uses the results of the PCI distress survey. As shown in Figure 3.1, the scale ranges from 0 to 100 with 0 being no FOD potential. Note that the FOD index uses a simplified three color scale.

Figure 3.1: FOD Potential Rating Scale.





### 3.5. PCI Survey Results

The airside pavements at 20A include 7 sections with 98 sample units. The sample number of sample units that were surveyed in the field is 28, which is 29 percent of the total samples. Data from the inspected sample units were input into the PAVER database and a resultant PCI for each section was computed.

Figure 3.2 presents the area-weighted PCI by use and the overall airside network.

**Figure 3.2: Pavement Condition by Branch Use.**




Figure 3.3 shows the distribution of the 20A pavement network by condition. None of the network is in “Poor” or worse condition.

**Figure 3.3: Pavement Condition by Percent of Area.**




Table 3.2 is a listing of the section PCI.

**Table 3.2: Section PCI.**

Branch ID	Name	Section ID	Surface	Area (sf)	PCI	PCI Category	FOD
A01	Apron 01	01	AC	55,473	68	Fair	46
RW0624	Runway 06-24	01	AC	327,600	78	Satisfactory	34
RW0624	Runway 06-24	02	AC	8,640	78	Satisfactory	34
TC01	Taxiway Connector 01	01	AC	8,563	75	Satisfactory	38
TC02	Taxiway Connector 02	01	AC	7,014	72	Satisfactory	41
THANG01	Taxiway Hangar 01	01	AC	57,374	71	Satisfactory	42
TTRW05	Taxiway Turnaround RW 05	01	AC	4,415	86	Good	25

Figure B2A and B2B in Appendix B are maps of the section PCI in 7- and 3-scale categories, respectively. Figures B2C is a map of the FOD rating. Appendix D contains a detailed report of the PCI values and distress type, quantity, and severity data for each sample unit that was surveyed in a section. Appendix E is a summary report of the extrapolated distress data at the section level.

Appendix F contains current section and branch PCI data and forecasted section PCI values. FOD values by section and branch are also presented. Figure B2D in Appendix B shows the locations of the photos that were taken during the survey. Photos are included in Appendix J.

### 3.6. PCC Pavements

As stated earlier, the project scope did not include a detailed pavement condition survey for any Portland Cement Concrete (PCC) aprons. For these pavements, a rating of “Good”, “Fair”, or “Poor” was assigned based on the overall pavement condition. There are no PCC aprons at 20A.

This Page Intentionally Left Blank

## 4 Pavement Capital Improvement Program

### 4.1. Introduction

PCI data were collected and entered into the PAVER database. In addition, the database customization included the following components, which are described in detail in this chapter.

1. Performance Modeling
2. Maintenance & Repair (M&R) Triggers (Critical PCI)
3. M&R Policies
4. Unit Costs

Once the database was customized, it was used to run budget analysis scenarios and develop a 7-year PCIP.

### 4.2. Performance Modeling

To determine long-term M&R needs, a APMP must be able to predict future pavement condition. Future pavement condition is predicted using equation models that are generated from current and historical PCI data. Equation models are developed by grouping pavements based on similar performance characteristics such as region, construction history, surface type, traffic, priority and use. Mathematical techniques such as straight-line extrapolation and regression that include boundary and outlier filters are used to develop models that provide the best fit equation for the pavement condition data. PAVER's Prediction Modeling module was used to develop pavement performance models that are commonly referred to as 'Family Curves'.

Prediction models are used at the section level to compute future conditions based on the typical performance of the pavement sections that are included in each model. Future condition is computed by defining its position relative to the prediction model. The section prediction curve, or equation, is drawn through the current PCI-age point for each specific section. Since the shifted curve will run parallel to the computed prediction model, the predicted condition can be computed for any future age. Figure 4.1 is an illustration of this process.

Prediction models provide an effective way to compute future pavement performance based on past and current conditions, and pavement maintenance and rehabilitation practices. As new PCI inspection surveys are conducted, these models should be updated accordingly. In the case of the Alabama statewide airport pavement network, the best fit family curves were developed for each region by grouping pavements according to branch use (e.g. runway, taxiway) and surface type (e.g. AC, AAC, and APC). The family curves for ALDOT were developed based on branch use and are presented in Figure 4.2.



Figure 4.1: PCI Forecasting.





Figure 4.2: Family Curves.



### 4.3. Critical PCI Values

The Critical PCI value is defined as *“the PCI value at which the rate of PCI loss increases with time, or the cost of applying localized preventive maintenance increases significantly.”* This definition is incorporated into PAVER in defining and measuring the critical PCI values. These values, or M&R triggers, are assigned for each prediction model. As such, the critical PCI values are directly related to the branch use.

These critical PCI levels are selected based on several factors including a review of performance models; experience; other airport triggers; and acknowledge that time is required for funding approval and design. Note that preventive maintenance is recommended, and it should generally be performed above the critical PCI (trigger) values and Major M&R is generally performed below them. The critical PCI (CP) values were set at 70 for runways and taxiways, and 65 for other pavements.

### 4.4. M&R Policies and Unit Costs

M&R policies refer to the activities that are applied at different condition levels to maintain and repair a pavement section.

Maintenance activities are localized activities which are typically assigned in the first year of the M&R plan based on the observed distresses. Safety (stopgap) maintenance addresses distresses that would affect operational safety if left unrepaired and is applied to pavements below the critical PCI. Preventive maintenance activities are aimed at slowing the rate of deterioration through consistent maintenance of existing pavements and are generally applied to pavements above the critical PCI. Appendix G presents the policies for preventive and safety maintenance.

Repair activities are conducted for larger areas, typically at the section level and are assigned based on the critical PCI. Repair activities broadly consist of three categories: preservation, rehabilitation, and reconstruction. Pavement preservation involves activities like surface treatments that are used to extend pavement service life and to delay more expensive rehabilitation work. These are applied when the pavement is in relatively good condition and does not exhibit any structural distress. Rehabilitation activities are used to repair pavements below or around the critical PCI and typically include mill and overlay. Reconstruction is recommended when the pavement has deteriorated to a level where rehabilitation is no longer cost effective.

Table 4.1 lists the pavement activity types, the individual activities within each type, and their associated 2020 unit costs. A more detailed description of the M&R activities and the development of the M&R unit costs is presented in Appendix H.

In accordance with ALDOT’s focus on preservation, surface treatment is applied to all resurfaced and reconstructed runways, taxiways, and aprons three years after construction work is complete. Taxilanes and T-Hangar pavements are excluded from this requirement. This policy is applicable for projects in the PCIP between 2021 and 2024. For cost estimating, this surface treatment is assumed to have the same cost as the runway surface treatment.





**Table 4.1: M&R Activities and Unit Costs.**

Activity Type	PCI	Activity	Cost/sf
Maintenance	Note 1	Seal Cracks – AC (\$/lf)	\$3.95
		AC Full-Depth Patching	\$25.05
		AC Partial-Depth Patching	\$16.28
Preservation	75-90	Runway Surface Treatment	\$0.57
		Taxiway and Apron Surface Treatment	\$0.85
Rehabilitation	> CP	2" AC OL <sup>2</sup>	\$4.19
	55 - CP	Mill 2" & 2" AC OL	\$4.56
	45 - 55	Mill 2" & 3" AC OL	\$5.79
Reconstruction	0 - 45	AC Reconstruction	\$10.91

<sup>1</sup> Preventive > CP; Safety (Stopgap) < CP

<sup>2</sup> For sections with structural distress and PCI > CP

#### 4.5. Pavement CIP Development

The PAVER database, updated with condition data and customized with condition performance priorities, policies, and costs; was used to evaluate the effect of multiple funding levels on the overall future pavement condition. This output was further used to develop the PCIP. Figure 4.3 illustrates the process that PAVER uses in the funding analysis.

The following M&R funding levels were used for the 20A pavement network to help establish the 7-Year PCIP. Figure 4.4 presents the network area-weighted average PCI for each of the following funding scenarios at the end of the analysis period:

- ∅ Unlimited Funding: Unlimited funding is available for all pavement needs. The PCI increases to 97 by 2027.
- ∅ Maintain PCI: Maintain existing PCI of 76.
- ∅ Constrained Funding: This scenario constrains the funding to \$1 million each year (total of \$7 million). The PCI decreases to 76 in 2027.
- ∅ Do Nothing: Performing no M&R would reduce the network PCI from 76 to 64 by 2027.

Figure 4.3: Budget Analysis Process.




Figure 4.4: M&R Funding Levels.




Table 4.2 summarizes the annual funding required for the above analyses. For the unlimited analysis, all pavement needs are funded in the year they are required. Therefore, the unfunded costs are zero. The total funded amount over the 7-year period is approximately \$2.4 million. For the annual funding level of \$1 million per year, funding is prioritized based on the prioritization matrix. When the needs exceed the funding for any year, the remaining sections are transferred to the succeeding year and the amount



for these activities are represented as “unfunded”. The “unfunded” repairs in 2027 for this funding level is approximately \$1.8 million.

**Table 4.2: Summary of M&R Funding Level Analyses.**

Year	Unlimited	Maintain PCI	Constrained \$1M/year	Do Nothing
2021	\$11,000	\$11,000	\$11,000	\$0
2022	\$14,000	\$14,000	\$14,000	\$0
2023	\$50,000	\$50,000	\$50,000	\$0
2024	\$616,000	\$616,000	\$616,000	\$0
2025	\$1,730,000	\$53,000	\$53,000	\$0
2026	\$1,000	\$5,000	\$5,000	\$0
2027	\$2,000	\$6,000	\$6,000	\$0
<b>Total</b>	<b>\$2,424,000</b>	<b>\$754,000</b>	<b>\$754,000</b>	<b>\$0</b>
<b>2027 Backlog</b>	<b>-</b>	<b>\$1,784,000</b>	<b>\$1,784,000</b>	<b>\$2,674,000</b>

Map B3A in Appendix B presents the 2027 forecasted PCI by section when the M&R activities recommended in the CIP are not conducted.

#### 4.6. Pavement Capital Improvement Program

The unlimited funding analysis contains rehabilitation activities for sections from the same branch spread out over the seven-year period, which is not always operationally feasible to construct. The analysis output was treated as a starting point in developing the CIP. Sections were often integrated together to account for construction feasibility and other factors, resulting in larger projects which were more realistic. In addition, each project could contain sections whose condition did not trigger rehabilitation but were included to provide a logical plan which would avoid creating “islands” of newer pavement within a particular feature. For example, if the PAVER analysis showed rehabilitation was required for eight out of 10 sections on a runway, the entire runway would be recommended for rehabilitation to provide a continuous new pavement surface.

Table 4.3 shows the projects and the associated costs for the recommended 7-year PCIP. Table 4.4 is a more detailed view of the PCIP. This table lists the individual pavement section, section level M&R work, section repair cost, surface area and the PCI before the M&R is applied. The costs that are presented represent an annual escalation rate of 3% for the unit costs. The total 7-year PCIP cost is approximately \$2.6 million. Map B3B shows the recommended repair types, while Map B3C presents the recommended projects and activities in the PCIP. Appendix I1 presents a summary of the recommended activities and cost by year for each section at 20A.

Chapter 4, Pavement Capital Improvement Program

Table 4.3: Summary of 7-Year PCIP by Project.

Project Year	CIP Project	Total Project Cost	Total Project Area (sf)	AWPCI Before	AWPCI After
2025	20A_25-01_Runway 06-24 Rehabilitation	\$1,801,736	340,655	70	100
2026	20A_26-01_Apron & TW Hangar Rehabilitation	\$783,718	128,424	57	100
<b>Total</b>		<b>\$2,585,454</b>			

Table 4.4: Summary of 7-Year PCIP by Project and Section.

Branch	Section	Area, sf	PCI Before Rehab	Activity	Activity Type	Cost
<b>20A_25-01_Runway 06-24 Rehabilitation</b>						<b>\$1,801,736</b>
R0624	01	327,600	70	Mill 2" & 2" AC OL	Rehabilitation	\$1,732,688
R0624	02	8,640	70	Mill 2" & 2" AC OL	Rehabilitation	\$45,697
TTRW05	01	4,415	77	Mill 2" & 2" AC OL	Rehabilitation	\$23,351
<b>20A_26-01_Apron &amp; TW Hangar Rehabilitation</b>						<b>\$783,718</b>
A01	01	55,473	59	Mill 2" & 2" AC OL	Rehabilitation	\$302,201
TC01	01	8,563	62	Mill 2" & 2" AC OL	Rehabilitation	\$46,649
TC02	01	7,014	56	Mill 2" & 2" AC OL	Rehabilitation	\$38,210
THANG01	01	57,374	54	Mill 2" & 3" AC OL	Rehabilitation	\$396,659
<b>Total</b>						<b>\$2,585,454</b>

The FAA, under the Airport Improvement Program (AIP) provides approximately 90 percent of eligible costs for planning and development of public-use airports included in the NPIAS as grants. The remaining 10 percent of costs are shared between ALDOT and the airport sponsor. The following is the distribution of the 7-yr PCIP cost of \$2.6 million for 20A:

- Ø FAA (90%): \$2.3 million
- Ø ALDOT (5%): \$0.13 million
- Ø Airport Sponsor (5%): \$0.13 million

The recommendations within the PCIP are based on a network-level study and should be used for planning purposes only. A detailed project-level assessment should be conducted for each project to determine the appropriate repair activities and develop more accurate cost estimates.

Table 4.5 summarizes the maintenance activities that are recommended for Year 1 (2021). The estimated cost is approximately \$14,881. A complete listing of the maintenance activities by section is presented in Appendix I2. This may be used as a basis for establishing an annual maintenance budget for the 20A pavements.



**Table 4.5: Summary of Year-1 Maintenance Plan.**

Policy	Work Description	Work Quantity	Work Unit	Work Cost
Preventive	Crack Sealing - AC	3,169	Ft	\$12,517
	Patching - AC Full-Depth	94	SqFt	\$2,364
			<b>Total</b>	<b>\$14,881</b>

**APPENDIX A**

**INVENTORY**



**Appendix A**  
**Pavement Inventory Report**  
 Robbins Field (20A)

Branch ID	Name	Branch Use	Section ID	Rank <sup>1</sup>	Length (ft)	Width (ft)	Area (sf)	LCD <sup>2</sup>	Surface <sup>3</sup>
A01	Apron 01 Oneonta	APRON	01	S	300	185	55,473	3/16/2006	AC
RW0624	Runway 06-24 Oneonta	RUNWAY	01	P	4,095	80	327,600	9/22/2008	AC
RW0624	Runway 06-24 Oneonta	RUNWAY	02	P	108	80	8,640	9/22/2008	AC
TC01	Taxiway Connector 01 Oneonta	TAXIWAY	01	S	230	30	8,563	6/14/2006	AC
TC02	Taxiway Connector 02 Oneonta	TAXIWAY	01	S	142	35	7,014	3/16/2006	AC
THANG01	Taxiway Hangar 01 Oneonta	TAXIWAY	01	T	272	200	57,374	10/7/2004	AC
TTRW05	Taxiway Turnaround RW 05 Oneonta	TAXIWAY	01	P	50	77	4,415	9/22/2008	AC

<sup>1</sup> P = Primary pavement, S = Secondary pavement, T = Tertiary pavement

<sup>2</sup> LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)

<sup>3</sup> AC = Asphalt Cement Concrete, AAC = Asphalt Overlay AC, PCC = Portland cement Concrete, APC = Asphalt Overlay PCC

## **APPENDIX B**

### **PMP Maps**

#### **B1: Inventory Maps**

B1A: Branch Identification

B1B: Section Identification

B1C: Sample Unit Layout

B1D: Pavement Type

B1E: Branch Use

B1F: Pavement Age

#### **B2: Surface Condition Maps**

B2A: 7-Color PCI

B2B: 3-Color PCI

B2C: FOD Rating

B2D: Survey Photo Locations

#### **B3: Pavement Capital Improvement Plan (PCIP) Maps**



B3A: 2027 Forecasted PCI without PCIP

B3B: M&R Needs







B3C: PCIP Recommendations




**Legend**

-  Section Boundary
-  PCC Aprons

**Branch Identification**

-  Apron 01 Oneonta
-  Runway 05-23 Oneonta
-  Taxiway Connector 01 Oneonta
-  Taxiway Connector 02 Oneonta
-  Taxiway Hangar 01 Oneonta
-  Taxiway Turnaround RW 05 Oneonta



Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL


**Figure B1A**

**Branch Identification**

<p><b>All About Pavements, Inc. (API)</b> <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small></p>	ENGINEER	DATE	MAP NUMBER
	KP/MR	May 2021	Page 1
REVISED	SCALE	<b>FINAL</b>	
JMA	1 in = 300 ft		

**Legend**

- Section Boundary
- PCC Aprons





**Figure B1B**



<b>Alabama Statewide Pavement Management Program Update Robbins Field (20A) Oneonta, AL</b>		
<b>Section Identification</b>		
ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 2
REVISOR <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>


**All About  
Pavements, Inc. (API)**  
www.allaboutpavements.com  
Telephone: 217-586-2765 FAX: 217-586-1967

**Legend**

-  Section Boundary
-  PCC Aprons

**Sample Unit Layout**

-  SU Boundary
-  Inspected



**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**


**Figure B1C**

**Sample Unit Layout**

<p><b>All About Pavements, Inc. (API)</b> <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small></p>	ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 3
	REVISOR <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>

**Legend**

- Section Boundary
- PCC Aprons
- Pavement Type**
- Asphalt Concrete (AC)



Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL


**Figure B1D**

**Pavement Type**

<p><b>All About Pavements, Inc. (API)</b> <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small></p>	ENGINEER	DATE	MAP NUMBER
	KP/MR	May 2021	Page 4
	REVISOR	SCALE	
	JMA	1 in = 300 ft	<b>FINAL</b>

**Legend**

- Section Boundary
- PCC Aprons
- Branch Use**
- APRON
- RUNWAY
- TAXIWAY



**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**

**Figure B1E**

**Branch Use**


<p style="font-size: small;">All About Pavements, Inc. (API) <a href="http://www.allaboutpavements.com">www.allaboutpavements.com</a> Telephone: 217-586-2765 FAX: 217-586-1967</p>	ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 5
	REVISED <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>

**Legend**

- Section Boundary
- PCC Aprons

**Pavement Age (Yrs)**

- 0 - 10
- 11 - 15
- 16 - 25
- 26 - 50
- >50



**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**

**Figure B1F**

**Pavement Age**


	ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 6
<small>All About Pavements, Inc. (API) www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small>	REVISED <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>

**Legend**

- Section Boundary
- PCC Aprons

**PCI (7 Color)**

- Good (86-100)
- Satisfactory (71-85)
- Fair (56-70)
- Poor (41-55)
- Very Poor (26-40)
- Serious (11-25)
- Failed (0-10)



**Figure B2A**

Alabama Statewide Pavement Management Program Update Robbins Field (20A) Oneonta, AL		
<b>7-Color PCI</b>		
ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 7
REVISED <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>

All About  
Pavements, Inc. (API)  
www.allaboutpavements.com  
Telephone: 217-586-2765 FAX: 217-586-1967

**Legend**

□ Section Boundary

▨ PCC Aprons

**PCI (3 Color)**

■ Good (71-100)

■ Fair (56-70)

■ Poor (0-55)



**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**






**Figure B2B**


**3-Color PCI**

<p><b>All About Pavements, Inc. (API)</b> <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small></p>	ENGINEER	DATE	MAP NUMBER
	KP/MR	May 2021	Page 8
REVISED	SCALE	<b>FINAL</b>	
JMA	1 in = 300 ft		



**Legend**

-  Section Boundary
-  PCC Aprons
- FOD Rating**
-  Good (0 - 45)
-  Fair (46 - 60)
-  Poor (61 - 100)




**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**

**Figure B2C**


FOD Rating		
ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 9
REVISED <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>

  
**JVIATION**  
 ENGINEERING & PLANNING

  
**All About  
Pavements, Inc. (API)**  
www.allaboutpavements.com  
Telephone: 217-586-2765 FAX: 217-586-1967

**Legend**

- Section Boundary
- PCC Aprons
- | Survey Photo Locations



**Figure B2D**

**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**

**Survey Photo Locations**


<p style="font-size: 8px;">All About Pavements, Inc. (API) <a href="http://www.allaboutpavements.com">www.allaboutpavements.com</a> Telephone: 217-586-2765 FAX: 217-586-1967</p>	ENGINEER	DATE	MAP NUMBER
	KP/MR	May 2021	Page 10
REVISED	SCALE	FINAL	
JMA	1 in = 300 ft		

**Legend**

- Section Boundary
- PCC Aprons

**Forecasted PCI without PCIP**

- Good (86-100)
- Satisfactory (71-85)
- Fair (56-70)
- Poor (41-55)
- Very Poor (26-40)
- Serious (11-25)
- Failed (0-10)



RW052302

RW0523-01

Runway 05-23

TC01-01

TWC01

THANG01-01

TWC02

TC02-01

T-Hangar 01

Apron 01

A01-01

T-TRN 05

TTRW05-01



Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL

**Figure B3A**

**2027 Forecasted PCI without PCIP**

<p><b>All About Pavements, Inc. (API)</b> <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small></p>	ENGINEER	DATE	MAP NUMBER
	KP/MR	May 2021	Page 11
REVISED	SCALE	<b>FINAL</b>	
JMA	1 in = 300 ft		

All sections recommended for Rehabilitation or Reconstruction between 2021 and 2024 also receive Surface Treatment in the 3rd year of paving.


**Legend**

□ Section Boundary

▨ PCC Aprons

**Repair Type**

■ Rehabilitation



Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL

**Figure B3B**

**Repair Type**

<p><b>All About Pavements, Inc. (API)</b> www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</p>	ENGINEER	DATE	MAP NUMBER
	KP/MR	May 2021	Page 12
REVISOR	SCALE	<b>FINAL</b>	
JMA	1 in = 300 ft		

All sections recommended for Mill & AC Overlay or AC Reconstruction between 2021 and 2024 also receive Surface Treatment in the 3rd year of paving


**Legend**

**Project Name**

- 20A\_25-01\_Runway 05-23 Rehabilitation
- 20A\_26-01\_Apron & TW Hangar Rehabilitation

**M&R Activity**

- Mill 2" & 2" AC OL
- Mill 2" & 2" AC OLP



**Alabama Statewide  
Pavement Management Program Update  
Robbins Field (20A)  
Oneonta, AL**

**Figure B3C**

**PCIP Recommendations**

All About Pavements, Inc. (API) <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small>	ENGINEER <b>KP/MR</b>	DATE May 2021	MAP NUMBER Page 13
	REVISED <b>JMA</b>	SCALE 1 in = 300 ft	<b>FINAL</b>

## **APPENDIX C**

### **OVERVIEW OF PAVEMENT DISTRESSES**



% 5~|| Ucf7fUWb| f57L

5~|| UcfVUWb| lgUg|YgcZ|HfVbBbWb| VUWgUgXVnZ|| iYZ|ifYcZhY  
Ug|UHfVbWYg|fZWk\YfYhg|Yg|Yg|Uxg|U|b|g|\| \Ygi bWk\Y~cUg'HY  
VUWgdcd|U|Ylc|hYg|fZW|b|U|n|g|Ug|Ygc|Zd|U|Y|VUWg'5Zf|fYUfX  
H|Z|W|c|U|h| hYVUWg|Vb|W|Z|f|a| |'a|U|ng|X|X|g|U|f|U| |'X|d|W|g|h|U|f|Y|c|d|  
U|d|U|b|f|n|g|a|V| |W|W|b|k|f|Y|c|f|h|Y|g| |b|c|Z|U| || Ucf" HYd|Wg|U|Y|Y|g|h|U|b|&  
Z|Y|h|c| |'c|b|h|Y|c|h| Y|g|X" 5~|| UcfVUWb| |c|W|g|c|b|n|b|U|f|g|h|U|f|Y|g| V|U|X|c|'  
f|Y|U|f|X|H|Z|W|c|U|h| |z|g| W|g|k| \Y' d|h|g|Z|U|X|g|W|g|X|Y|X|U|a|U|c|f|g| V|U|X|g|Y|g|'

Gj Yf|ng

- ◆ @k! aUXi dcZ|bz\Uf|\_ YUWg|i|b| |'d|f|U|Y|c| X|W|c|h|Y|k|h| b|b|Y  
c|f|c|b|n|U|Z|k| |H|f|V|b|B|b|W|b| VUWg' H|Y|V|U|W|g|U|f|Y|b|c|g|U|Y|X'
- ◆ A Y|a !: i|f|h|Y|X|Y|Y|c|d|a|Y|h|Z| | \H|U| | UcfVUWb| |b|c| U|d|U|b|f|c|f  
b|k|c|f| |c|Z|U|W|g|h|U|a|U|h|Y| | \h|g|U|Y|X|A|Y|a|!g|j|Y|f|n|U| | UcfVUWb| |'  
|g|X|b|X|V|n|U|k|Y|!X|b|X|d|U|b|c|Z|H|f|V|b|B|b|W|b| VUWg|k| \Y|Y|U|'d|W|g|  
U|Y|g|U|f|Y|m|Y|X| |b|d|U|W| |c|c|X|U| |f|U|Y| |b|f|c|W|W|k|Y|b|d|W|g|/
- ◆ < | \! \Ug|d|c|f|Y|g|X|g| h|U|h|Y|d|W|g|U|f|Y|k|Y| X|b|X|U|X|g|U|Y|X|U|h|Y|X|Y|g|"  
G|a|Y|c|h|Y|d|W|g|a|U|h|c|W|i|b|W|f|H|Z|W|b|X|a|U|h|U|g|: CS'd|b|H|U|'

FYU|f|cd|cbg

- ◆ @k! Bc U|f|b|z|g|f|Z|W|g|U|c|f|g|Y|U|h|Z|f|~|c|k|g|j|Y|f|n|g|Y|g|/
- ◆ A Y|a ! d|f|U|c|f|Z|~|X|h|d|U|W|z|g|Y|U|h|c|f|f|W|b|g|i|W|
- ◆ < | \! d|f|U|c|f|Z|~|X|h|d|U|W|z|g|Y|U|h|c|f|f|W|b|g|i|W|



**& 6 YXh| B57L**

6 YXh| lgU4a cZVlia ]rci ga UMjU'cbhYdj Ya Vhg fAWhUAMNYgUg ]bn  
[ 'Ug ] YfZNMh | g fAWhUi g UmVWA Ygi ]Yg]Mh6 YXh| lgU gXVn  
YWg] YUaci hgcZig\ U]WA YhcfRfg]bhYa ] 'c`dk!Ufj c]XWbHhcfVch"  
-hcWAgk\ YUg\UH`ghYj c]XgZhYa ] Xfh| \dkYhYUkXhYbYdbXgci h  
dle hYg fAWcZhYdj Ya YhQBWhYVYXh| dcWg]gbcifY YgVYXfh| WX  
kYhYZig\ UicfRfk ]` UWAi` UYcbhYg fAW

Gj YfNg BcX] fYgcZg] Y]mifYX]bX'6 YXh| 'gci` XWbdXk\ Y]hg  
YfNg] Yhci [ \ lc fXWg ]XNg]dW

FYUFD`Mg`Scbch| /g]XVd hYXg]g]XifUv]dth| \YU]Xc`g]X  
]de hYUf]gUZM]k]h VYXh| zfa c] YhYVWga UMjU/dW





3" 6cW7fUWb] 157L

6cWVWgUY]bWbNEXWVghUHj]XhYdjYaYH]bcfVW]iUfgUdX  
d]Wg"HYVcVgaUuU]Y]bgrKZca %An?Zc]c %6Vn?6Z]P'6cWVW]d'  
lgW]gXaU]bn]ng]fb\_U]YcZhYUg]U]H]M]N]Y]U]X]g]b]d]c]U]X]g]c]V]W]X]H]Y  
c]W]f]b]W]c]Z]c]W]V]W]d]i]g]U]n]b]X]U]V]g]h]U]h]Y]U]g]U]H]g]U]X]b]X]g]l]h]Z]U]h]f]i'  
6cWVW]d] b]c]a]U]n]c]W]V]g]j]Y]U]U]f]Y]d]c]d]f]l]b]c]Z]h]Y]d]j]Y]a]Y]H]f]N]Z]i]h]k]j]''  
g]a]V]j]a]Y]g]c]W]f]c]b]n]j]b]h]Y]c]b]l]l]Z]V]W]V]g'

GjYf]N]g

- ◆ @ck! X]b]X]V]n]M]W]g]h]U]f]Y]U]a]c]g]i]l]h]n]g]U]Y]Z]V]i]g]h] b]c]Z]f]N]l]b]c]V]W]i  
X]a]U]Y]E]C]S]E]d]h]f]i]U]'I]h]Z]'X]M]W]g]'U]j]Y]%' ]b]W]c]'Y]g]a]Y]b]k]X]h]Z]b]X  
Z]'X]M]W]g]'U]j]Y]Z]'Y]f]b]g]l]g]U]f]n]M]b]X]l]c]b/
- ◆ A]Y]i]a]! X]b]X]V]n]M]W]g]h]U]f]Y]a]c]X]U]Y]n]g]U]Y]X]i]g]a]Y:]C]S]'d]h]f]i]U]Z  
i]h]Z]'X]M]W]g]h]U]f]Y]U]a]c]g]i]l]h]n]g]U]Y]Z]V]i]h]U]j]Y]U]a]Y]b]k]X]h]l]f]U]f  
h]U]b]%' ]b]W]c]Z]'X]M]W]g]h]U]f]Y]U]a]c]g]i]l]h]n]g]U]Y]X]V]i]h]U]j]Y]Z]'Y]f]b]  
i]h]g]l]g]U]f]n]M]b]X]l]c]b/
- ◆ <]l]!\]! X]b]X]V]n]M]W]g]h]U]f]Y]g]j]Y]f]n]g]U]Y]Z]V]i]g]h] U]X]b]h]Y:]C]S'  
d]h]f]i]U]'

F]Y]U]f]D:]M]g

- ◆ @ck! B]c]U]l]c]b/
- ◆ A]Y]i]a]! g]U]V]W]g]U]d]n]f]i]j]Y]U]c]Z]f]N]W]g]f]Z]W]c]'Y]h]g]U]f]Z]h]b]X  
c]j]Y]U]h
- ◆ <]l]!\]! f]N]W]g]f]Z]W]c]'Y]h]g]U]f]Z]h]b]X]c]j]Y]U]h




## Corrugation

### Description

Corrugation is a series of closely spaced ridges and valleys (ripples) occurring at fairly regular intervals, usually less than 5 feet (1.5 meters) along the pavement. The ridges are perpendicular to the traffic direction. Traffic action combined with an unstable pavement surface or base usually causes this type of distress.

### Severity Levels

- @** 7cffi [ U]d gUfYa ]bc fUXXc bcdg] b]VUbn iZWN]Xe i U]m gYa Vg fYa Yh V]N]UYckE'
- A** 7cffi [ U]d gUfYbd ]MVYUkXg] b]VUbn iZWN]Xe i U]m gYa Vg fYa Yh V]N]UYckE'
- <** 7cffi [ U]d gUfYVg ]nbc ]VXUkXg] Ym iZWN]Xe i U]m gYa Vg fYa Yh V]N]UYckE'



)" SYFYgcbiB7L

SYFYgcbgUfYcWlnXdj Ya YHj fZWFNg Uj h Yy Uhdggll \hmckYhUb  
hcgYcZhYgffci bNj 'dj Ya YH-ba UnhgUBWg' ll \hSYFYgcbgUfYhdi  
bdMVYi bU UFUUbZk\ YdbbNj kUFVUNgUfVXWHI UNg VihY  
XfYgcbgUbUg YcWfXk]hci hfUvWU gYcZgUhgWfXVndbNj 'cZ  
kUF"SYFYgcbgUbVWU gXVngNia YhcZHYzi bNjdbg] cfUbVWU]hi  
Xfj] WbgU Vdb"SYFYgcbgUfYgfi [ \bgUUbZk\ YbZ`Ykjh kUFcZ  
gZVfHhXhZwI`XWUg\`nfcUbj] cZUfVZFI

GjYfNg

- ◆ @k! SYFYgcbWbVcVgY Ycf`cWfXVngUfVXUNgcbngll \hm  
UZWgdj Ya YHfNj 'ei UlnUBXa UnUg\`nfcUbj] ddbU'db  
fi kUg'AU]aia Xh`%#`lc`%&]bWZffi kUg`%&lc`%&]bWZfU]kUg  
UbXUfcbg/
- ◆ AYa! HYXfYgcbWbVcVgY YzacWfUynUZWgdj Ya YHfNj '  
ei UlnUBXW g\`nfcUbj] ddbU'dbfi kUg'AU]aia Xh`%&lc`%  
]bWZffi kUg`%&lc`%&]bWZfU]kUgUbXUfcbg/
- ◆ <ll\! HYXfYgcbWbVfUd]ncVgY YZgY YnUZWgdj Ya YHfNj '  
ei UlnUBXW g\`Nj]Y\`nfcUbj] ddbU'/SYh [fUfHUb%]bWZf  
fi kUg] fUfHUb&]bWZfU]kUgUbXUfcbg'

FYUfDe`Vg

- ◆ @k! BcUfcb/
- ◆ AYa! GUckzdUfU'cfZ`Xh`dUW
- ◆ <ll\! GUckzdUfU'cfZ`Xh`dUW



\*" >Yi6UjB7L

8YqJdjb

>Yi/UgMfgcbWiggXf\_YbXifNgdbhYdjYaYhijfZVMk\YbVhaJbci gVbXf  
\UgVYbVi fbXcfWVchX~cUjXVi fbXifNg Uij UinjbXth idlc'  
Uhd jaUYn%&|bWf%a|`jaYfg!

GjYfh@jYg

BcXifYgZejYfhifYXZbX'figjZMfhcJbXUYhUiyWUgMfgcbYlg'



+!">chfYZWcb7fUWb] f57L

8YgAd]cb

HlgYgYgcWfcdnibbdj Ya Ylg\Uj]d UbUg\UicfUf g fAWcj YUD7'gU'  
HlgWU] cfmKYgch]bWXYZM]cbVWU] Zca UnichYfhdYcZUgM] YZ  
Va YhgU] hXZ]a YgU] hXZ]g WUWgUfY] gYX]g'ch] jhXbU UbXUhg YgY  
WUWg'>chfYZWcbVWU] ]gU] gXa Ub`nna c] Ya YhcZh YD7'gUWbN'h'  
hY57'g fAWWU] gYcZh Ya U UbXac] g fYWU] Yg ]hghch cUXYUXX'<ckY YZ  
hZ]WcU] a UuU] gUfU XkbcZh Y57 bmfhYUWU] Yg ]h] ]bgU]d UbX  
: CS'ddH]U' ZhYdj Ya YhgU] a YfXUd] U WUZh YUW] g] ]Xle VY  
gU'X'5' bck Y] YcZgU] a YgchgVbN'h hY57'g fAWk]``\ Ydle ]Xb]n  
hYgUWg'

GjYf]h@jYg

@ 7UWg\Uj Ycbm]] \hgU]d ]h]hYcfc: CS dH]U]cfc'gU]d UbXU]bY  
Z'YcfbcdZ'YX =ZchZ'YzhYUWg'Uj YUa Ubk]h'cZ%# ]bWf'  
a] ]a Yf]c'Yg': ]'XUWgUfYcZUbk]hZi hYfZ' Y a Uf]U ]g]b'  
g]hgUWfm]b]cb'

A CbYcZhYZ`ck]d Wb]hdgY ]gg fUWUgUfYacXUfYngU'X]ga Y: CS  
dH]U]U]bXU]bY]hYfZ' YcfbcdZ' YcZUbk]h/]hZ' XUWgUfYbch  
gU'YcfUfYcbm]] \hngUYXV]hYfZ' Y]g]bi hg]hgUWfm]b]cb/]h  
bcdZ' XUWgUfYbch]gU'YcfUfYcbm]] \hngUYXV]hYa Ub WUW  
k]h ]g] fU]f]hU]b%# ]bWf' a] ]a Yf]c'f]h]] \hU]Xa WUW] Y ]gg  
bmfhYUWU]cU]hYU]b]f'cZ]h]gU]d WUWg'

< 7UWgUfYg] YfYngU'YXV]h]hY: CS dH]U]U]bXU]bY]hYfZ' YcfbcdZ'  
Z'YcZUbk]h''



, " @cb|JiXpUUbXHfUbgYfgY7fUWb| 157L

@cb|JiXpUUbXfUbgYfgY7fUWb| HEMWgUfYdUUYlc hYdj Ya YHqWfHf|bYcf  
'UxkbXfWfcb' H Yna UhVYVgXVm%Udcbf mWbJf VxXdj|H "Uy'chz&  
gfb UyCzhY57'g fAWX Yc\UxXb| 'cZhYUg UZ'cf' EufZMj YMW  
WgXVmMWgVbXh hYg fAWXi fg' HUbj YgVWgY HbXUWghY  
dj Ya YHfMcbXWUfnlc hYdj Ya YHqWfHf|bYcf UxkbXfWfcbzUxa UhY  
WgXVmHAg&cf' EfgHfXUvj Y'HYgHmNgZMWgUfYbchi gUmçX  
fYUX'

**GjYfng**

- ◆ @k!\jYfYfa|bcfgU|h'cfbcgU|h"HYWVgVbVZ'Xcfih  
Z'XTI bZ'XWVg\jYUa Ybk|X'cZ%#|bWcf'Yg': j'XWVgUfY  
Ubk|X v|hYfZ'Yfgb|gUfWfmbX|cb/
- ◆ A Wia !cbXzhYZ`ck|h| Wb|hdgYlgg'%EMWgUfYacXUym  
gdUYXUxUvVYfYfZ'XcfibZ'XczUbk|X/'&Z'XWVgUfYbchi  
gdUYXcfdbm||\hngUYXZVihYfZ'Yfgbi|gUfWfmbX|cb' Eib  
Z'XWVgUfYbchi gdUYXcfdbm||\hngUYXZVihYWVWk|X YWVg  
%#|bWcf(E||\HUXa VVWb| Ylgg|XfHYWVWcfUH YWbYf'cZHY  
HfGm|h VVWg/
- ◆ <||\!gjYfngUYXk|h UXZ|H: C7cbH|U"HYmUvVYfYfZ'X  
cfibZ'X'

**FYUFD:MG**

- ◆ @k! BcUfcb/
- ◆ A Wia !gUWVg/
- ◆ <||\!gUWVgcfmZfa UZ'Xh'dW'



9" Cj' Gd' UYB7L

Cj' gd' UYghYXWjcdUjbcfgZbh' cZhYdjYa Yhg fZWWgXVnhY  
gd' h' cZc' ZYzcfchYfg' j Ylg'

Gj YfNg Bc Xj fYg' Zgj Yj mifYXWjbx' Hgg ZYVhlc' jYUyhUic' gd' UY  
Ylgg'

**FYUFD' MNg**

- ◆ Scbchj' /
- ◆ DffU'cfZ' Xh' dUW'



%8' DUWb]

FYUfDUWb] UXi f]mWidUWb] ]gWbg]NYXUXZUWf] UXYgcZck kY' ]h  
dMzfa gcfkUgWbgi WXX

Gj YfING

- ◆ @ck! ]b[ ccXWb] ]cbUX]gdMzfa ]h ]g]g]UWf] m'
- ◆ A Y]i a ! ]gga Yk\ U]NYf]cU]XU]XU]ZU]Wg]f] ]h ]ei U] ]m]c' ga Y] ]f]h
- ◆ < ] ] \ ! ]gU]X]m] ]f]cU] ]XU]XU]ZU]Wg]f] ]h ]ei U] ]m]g] ]h ]ZU]W]h ]c]f \ U] ] \ \ ' : CS' d]h ]U'

FYUfcd]cbg

- ◆ @ck! BcU] ]cb/
- ◆ A Y]i a ! g]U]V]W]g]f]YU]f]hYX]g]Y]g]g] ]h ]YdU]W]c]f]f]dU]W]h ]YdU]W
- ◆ < ] ] \ ! f]dU]W]h ]YdU]W'



: ] ] ifY7'4. "5g]U]H]DUWb]"



%Dc'lg X5[[fY\te f57L

8YAd]db

5[[fY\UYdc'lg]h'lgW'gXvifdNFXIQUWd]W]db'g'Dc'lg XQU[[fY\UY]g  
dYgHk\YbWgYUa]b]bcZUdjYaYhfyYUghUhYdb]bcZU[[fY\UY  
YHbXh]UvjYhYUg\UHgYhYjYfingU'cfhYfYfbc'fi[\cfU]i'f  
U[[fY\UYd]f]Wg'c'dj]X]ccXg]XfYg]BW'9]g]bWcZ]g]hd'cZ]g]Yg]g'  
Ug]b]X]X]k\Yb]h]Y]i]a]V]f]cb]U]g]X]f]Y]g]B]W]f]U]h]f]g]i]g'ck'cf\U]g]cd]X  
g]h]b]Z]U]h]n]z]ca'd]y]j]ci]g]f]U]h]g'

GjY]h]e]y]Yg

BcX]f]Y]g]c]Z]g]Y]h]m]f]Y]X]b]X<ck]y]Y]z]h]Y]X]f]Y]c]Z]c'lg]h]g'ci'X]Y  
g]h]b]Z]U]h]n]z]ca'd]y]j]ci]g]f]U]h]g'



%&FUJYH 157L

8YbHdb

FUJYH lghNYXgcXlH'cZMUGYU[fUUYdUfMwZca hYdJYa YHj fAW'

8YgYA| 'GjYfmi@jYg'


5gi gX\YfZMUGYU[fUUYWgfc:dFXa]HUMUGYU[fUUYgngcZHY  
UgUha]"5[[fUUYWgMgfZfck\YbacfYhUdbYUc]h] WUGYU[fUUY  
d]Wga]ggH"-ZbXi ViUdi HUGj YfmiY YzhfYfYfYgHuj YfngcZ%gi UY  
nFXf%gi UfYa YfLNUWgci XYYUa]bXlXhYbi a VfCza]ggH WUGY  
U[fUUYdUfMwZca hYX'

@ ck'gj YfmiWfG[ZUrbYcZhYgWbN]dgY lgh fE:bUgi UYnFXgi Uf  
a YfLNUWgci YfngcZ%gi UfYa YfLNU-b`ck'gj YfmiY Yh]zhYYlg'fYcf  
bc: CS'ddHJU'


A Yfi a'gj YfmiWfG[ZUrbYcZhYgWbN]dgY lgh fE:bUgi UYnFX  
fgi UfYa YfLNUWgci YfngcZ%gi UfYa YfLNU-b`ck'gj YfmiY Yh]zhYYlg'  
gaY: CS'ddHJU'

< [| \ 'gj YfmiWfG[ZUrbYcZhYgWbN]dgY lgh fE:bUgi UYnFX  
fgi UfYa YfLNUWgci YfngcZ%gi UfYa YfLNU-b`ck'gj YfmiY Yh]zhYYlg'  
ggYf(S' fEA]ggH U[fUUYWgMgfca]fYhU%'SdMWh:zhYYUa]bX  
gi UYnFXgi UfYa YfLNU-b` [| \ 'gj YfmiY Yh]zhYYlg']b]WbH CS'  
ddHJU'

BdY h]lgUbk XgYggbWbYSS+ 'g fj Ym



Gi ffrGU#7cUHfCjY8YgA| GYf|n@Yg



@

f2H YgUyXlfUlg YghU% dVfHfE-bhYwGcZAUrk\YYdUMB  
VWWh \UgXjYcdXzhYgfZWWUgUfY YghU%# ]wfl'aaIk]X'

A

f2H YgUyXlfUlg VlkYb% dX'S dVfHfE-bhYwGcZAUrk\YY  
dUMB VWWh \UgXjYcdXzhYwUgUfY%# ]wfl'aaIk]Xcf[ fUP'

<


f2H YgUyXlfUlgj Y%\$ dVfHfE-bhYwGcZAUrk hYgfZWWg  
dY]h 'cZ

Dfci g: fMkb7ci fgYGjYfhi@jYg

**@** ÷bU%gi UYZdfl#Sgi UYa YffFYGHUj YgãdYhYbi aWfçZ  
U[[fYUYd]Wgãlgg] lgVlkYb) Ux&SUX#chYbi aWfçZãlgg]`  
U[[fYUYWg]Gg]g]fYUfhub%ãihçYgch] VWX%`

**A** ÷bU%gi UYZdfl#Sgi UYa YffFYGHUj YgãdYhYbi aWfçZ  
U[[fYUYd]Wgãlgg] lgVlkYb&ãUX(SUX#chYbi aWfçZãlgg]`  
U[[fYUYWg]Gg]g]fYUfhub%ãihçYgch] VWX&`ãVWihçZYfU

**<** ÷bU%gi UYZdfl#Sgi UYa YffFYGHUj YgãdYhYbi aWfçZ  
U[[fYUYd]Wgãlgg] lgjYf(SUX#chYbi aWfçZãlgg] U[[fYUYWg]Gg]g]fYUfhub&`ãVWihçZYfU



%" Fi Hh] 157L

5 fi hg Ug fZWXfYgcb]bhYk\Y'dh^\ckYVZ]ba Un]g]bWgfi lgUY  
bc]MUYcbn]ZfUQb]U'k\Y'hYk\Y'dhgUYZ`Yk]h kUM" Dj Ya Yh  
id]Zia UicWfUch] hYgXgcZhYfi H'Fi Hh] g]hagZca Uda UbhXZcaU]cb  
]bUicZhYdj Ya YhUm]gcf g V[ fUXZi g Un]W gXV]M]gc`XU]bcf`UMU'  
agj Ya Yh'ZhYa Un]UgX Yc]hZ]WdUg`Q[ h]Z]W]h] Hh] Wb`YX]c'a Ucf  
g]i WfUZ]i fycZhYdj Ya Yh

Gj Yf]g]UgXcbfi hXchL

- ◆ @ck! YghUb' ]bW]bXch/
- ◆ A Y]a! WkYb' Ux%]bW]bXch/
- ◆ <||\! YW]g%]bW]bXch"

FYU]fcd]cbg

- ◆ @ck! BcU]cb/
- ◆ A Y]a! d]WU]bXcfj YU]h
- ◆ <||\! d]WU]bXcfj YU]h



: ||ifY7!. "57Fi Hh]"

**%"G|dd|Y7fUW|b| B57L**

**G|dd|Y7fUW|b|** from the direction of traffic. They are produced when braking or turning wheels cause the **dj Ya Yhg fAWc:g|XUXXZfa"H|g|g|U|ncW|fgk\YbhY|g|U|ck:g|h'g|fAWa||'cf|dcfV|bXV|k|YbhYg|fAWU|X|b|h|U|f|cZdj Ya Yhg|V|fY'**

**GjY|f|g** No degrees of severity are defined. It is sufficient to indicate that a slippage **VWY|g|g'**

**FYU|f|D|V|g**

- ◆ **Sc|b|h|d|/'**
- ◆ **D|f|U|c|Z|~|X|h|d|U|'**



**:||ifY7% G|dd|Y7fUW|b|"**

%"GkY]h] 157L

8Yg]d]b

5'gkY'lgWfUW]h]XVn]bi dkUfXV' [Y]bhYdj Ya YH]g]fZW'5'gkY'aUn  
cWf]g]f]dn]ej YUgaU' f]Ucf]g]U]d]h] YZ]f]U]U]k]j Y9]h]Y]h]n]c]z]g]k]Y' Wb]W  
UW]a]d]h]Y]X]V]g]j f]Z]W]W]U]h] "5'gkY'lg]g]U]m]U]g]X]V]n]c]g]U]h]b]h]Y  
g]V]f]U]X]c]f]V]n]g]k]Y' ]h] ]g]c]Z]V]h]U]g]a]U' g]k]Y' Wb]U]g]c]W]f]c]b]h]Y]g]j f]Z]W]c]Z]b]g]d]U]h  
c]j Y]U]h]h]j YD7]H]g]U]F]j ]h]c]Z]U]V]c]k! i]d]h]b]h]YD7]g]U'

GjY]h]n]@]j]Y]g

GkY'lgWfYnj]lgVYU]X]U]g]U]a] ]h]c]f]Z]W]c]b]h]Y]d]j Ya YH]g]f]X]e]i]U]h]m]g]  
X]h]f]a] ]b]X]U]h]Y]b]c]f]a]U]U]f]U]Z]ig]h]X]Z]f]h]Y]d]j Ya Yh]g]U]h]b]i]b]X]  
@ W]h]g]X]U]h]b]i]f]c]k!g]j Y]h]n]g]k]Y'g]a]U]h]c]h]U]k]U]g]V]c]V]g]j U]V]Z]V]h]Y]f]  
Y] ]g]b]W]W]b]V]W]h]f]a] X]V]n]c]g]j ]h] ]U]j X] ]W]c]j Y]h]Y]g]U]h]b]U]h]Y]b]c]f]a]U'  
U]f]U]Z]ig]h]X]Z]f]h]Y]d]j ]h]c]W]f] ]Z]h]Y]g]k]Y' ]g]d]f]g]h]!

GkY'Wb]V]c]V]g]j Y]k] ]h]c]i]h]Z]V]h]n]b]X]U]g]U]g] ]h]Z]W]h]Z]W]c]b]h]Y  
A d]j Ya YH]g]f]X]e]i]U]h]m]g]X]h]f]a] ]b]X]U]h]Y]b]c]f]a]U]U]f]U]Z]ig]h]X]Z]f]h]Y]d]j Ya Yh]  
g]U]h]b]i]b]X]W]h]g]X]U]h]b]i]

GkY'Wb]V]f]U]d]n]c]V]g]j Y]X]U]X]g]j Y]Y]n]Z]Z]U]g]h]Y]d]j Ya YH]g]f]X]e]i]U]h]m]h]Y  
< ]h]c]f]a]U]U]f]U]Z]ig]h]X]Z]f]h]Y]d]j Ya Yh]g]U]h]b]i]b]X]W]h]g]X]U]h]b]i]





%"KXhYb 157L

8Ygldjb

H YkVfb UkUicZhYUgUHMpXfUXZBYU [f]UYaUqI Zca hYdj Ya Yhi  
gfAW

GjYlmejYg

5glUhg fAWW]bb] le'g'ck'g]bgcZU]b] k\]WaUuYUWYUUXVn  
V]aU]WbY]dg' @cg]ghYZBYU [f]UYaUqI ]gd]MVYUbxUuY  
@ UW]d]h]XVnZ]h] cZhYUgUHWc" 9N]YgczhYWUgYU [f]UYgUY  
V] ]bb] leVY]dgXfng]h]b]\$\$ ]bW]gcf%aaE' DjYaYhaUuY  
fYUj Ynbk flgbk Ug\* 'ad]hg'X!

A @cg]cZ]BYU [f]UYaUqI ]gd]MVYUbxY]gczWUgYU [f]UY]jYVb'  
Y]dgXi]d]c%# k]X ]Z]h]Y]c] Y]g]X]c]Z]h]Y]W]U]g]Y]U [f]UYX]Y]c]h]Y]cg]  
cZ]BYU [f]UYaUqI "

< 9N]YgczWUgYU [f]UY]jYVb]Y]dg]X]f]M]h]b]#% k]X ]Z]h]Y]c] Y]g]  
]X]c]Z]h]Y]W]U]g]Y]U [f]UY]h]Y]Y]g]W]g]X]M]V]Y]cg]cZ]BYU [f]UYaUqI  
Y]h] le'd]h]U'cf]gaY]cg]cZ]W]U]g]Y]U [f]UY'



%!"6dk!I d!D77L

8YgAd!db


6'dki dg'cWf' b\dkYhYzi gUmHUMhg YgVWcf'c!hHUhgbdk!X  
Yci [\ lc'dMa ]h! dlhgdbVihYWBWYgUG'H Y!hgZ!W!k!Xh lgi gUm  
V!gXVr!bZ!U!bcZ!W!dYg!VYaUm!Ug!bc hY'c!hg!W!K\Y!Y dlhgdb'  
W!hcfY!Y Yci [\ dYg!fZU'cW!n!X!k!t!X!a!j!Y!Y!h!Z!h!Y!g!U!V!X!Y!  
f!i!W!h!E!c!f!g!U!M!h!k!`'cWf' b!h!Y!j!M!h!c!Z!h!Y'c!h!H!6'dki dg'W!b!U!g!c!W!f!U!h  
i!h!h!m!W!g!U!X!U!b!Y!b!Y!g!H!g!h!d!Y!c!Z!h!g!Y!g!g!U!a!c!h!U!k!U!g!f!Y!U!f!X  
!a!a!Y!U!Y!m!W!W!g!c!Z!g!Y!Y!X!a!U!Y!d!h!H!U!c!U!M!Z!H!6'dki dg'U!Y!b!W!X!X!Z!f  
f!Z!f!W!k\Y!b!W!g!X!g!W!h!g!f!Y!V!h! Y!U!U!X!Z!f!f!Y!c!h!h!"

GjY!h!c!j!Yg

@ 6i W!h' cf g'UM!h \Ug!h!f!W!X!h!Y!d!j!Y!Y!h!b!c!d!M!U!j!Y!Z!U!X!c!b!n!U!g![\!h!  
!a!c!i!h!c!Z!i[\!b!g!Y!g!g'

A 6i W!h' cf g'UM!h \Ug!h!f!W!X!h!Y!d!j!Y!Y!h!b!c!d!M!U!j!Y!Z!U!h!U!g![\!h!W!h!  
!a!c!i!h!c!Z!i[\!b!g!Y!g!g'

< 6i W!h' cf g'UM!h \Ug!h!f!W!X!h!Y!d!j!Y!Y!h!b!c!d!M!U!j!Y'



%! 7cbf6fU\_gfD77L

5 wbfvU\_lgUWWhUfhgNghY'chgUUXgUWYghUbcfYiUlc'cbY  
\UzhYgUVY[h'cbVch'gXgaYgJfXZca hYWbfcZhYgU': cfYUadYZU  
gUkjhXaYgdcgZ&Vri&ZfhUhgUWWhgNgh hY'ch)Zfhca'  
hYWbfc'cbYgYUX%ZYdbhYchYfgWlg'chUhgXfXUWbYVU/Thg  
UXU'cbUWV' <ckYYZUWWhUfhgNgh+ZYdbhYgYUX%SZYdbhY  
chYlgWbgXfXUWbYVU" 5 wbfvU\_XZgZca UWbfgU'bhUHY  
WVYhNgjYU'nhci[\hYhYgUVh]Wbgk\]YUWbfgU'fhgNgh  
hY'chUhbU'Y@cXfYh]cbWaVbXkjh`cggZgdbfUWf'h'gYggg  
igUmUgWbYVU\_g'

**GjYfNg**

- ◆ @ck! 7UW\lgYhYfbc'gU'h'cfajbcfgU'h'fbcZfY[bcVWNaUY  
fIC8f'dfHUE'Zch filled, it has a mean width less than approximately 1 #'  
inch (3 millimeters); a filled crack can be of any width, but the filler material  
aigWYbgJgUWf'WbYh'cb'HYUfUWkYb hYWbYVU\_UXhY  
^'cbg'g'chUWVX
- ◆ AYa! One of the following conditions exists: (1) filled or non-filled c'fUWlg'  
acXUfYngU'XhgaY: C8'dfHUE/fhUch filled crack has a mean  
width between 1/8 inch (3 millimeters) and 1 inch (25 millimeters); (3) a filled  
crack is not spalled or only lightly spalled, but the filler is in unsatisfactory  
WbYh'cb'f'f'HYUfUWkYb hYWbYVU\_UXhY'cbg'g'[\h'WVX  
kjh`ccY'cfajgg' 'd'f'Wg
- ◆ <ll! One of the following conditions exists: (1) filled or non-filled crack is  
severely spalled, causing definite FOD potential; (2) a non-filled crack ha'gU  
a'Wbk]h [fUf'hU'U'hd]aUfYm'f'WVf) 'a]'a'YgZ'WU'h'U'fY  
XaU'Y'd'f'f'U/'c'f'f'HYUfUWkYb hYWbYVU\_UXhY'cbg'g'  
g'Y'Y'm'WVX'

**FYU'fcdhcg**

- ◆ @ck! BcUW'bcf'gU'WVg
- ◆ AYa! gU'WVg
- ◆ <ll! gU'WVg'U'hmU'~  
cfYUW'hYgU'



Xh'dW

: llifY7%&'D777cbf6fU''

%" 7fUWg"@cb|JiXpUZHFUbgYgYUbxS|UcbU'fD77L

H YgVWwXj |XhYgU|bc lkc'cfhfYd|WgZUXIfYigUmWgXVhU  
Wá VhU|bcZcdXfYh|cbZf|H' gYgZUXgfb\_UYgYgG"@ck'gYVlnh  
VWgUfYbdhWgXfXaUcfgiVfUXgYgG'A Yfi a'cf||\ 'gYVlnWgUfY  
igUnkcf\_H| VWgUXIfYVhgXfXaUcfgiVfUXgYgG'

**GjYfng**

- ◆ @ck!%i hZ`YXWwG%#`bWlc%&|bWk|Xk|h bcZi`Hd'cf gU|h/ &E  
VWwG`YghU%&|bWk|Xk|h`ck'gYVlnhU|h/`cf' EZ`YXWwGcZ  
Unk|Xk|h ZfYcfZfa|H|`bUgU|VfinaUbfUx|bcZi`Hd'cf  
gU|h/
- ◆ A Yfi a !%i hZ`YXWwGVkYb%&lc%|bWk|Xk|h bcZi`Hd'cf  
gU|h'cf &Z`YXWwGcZUnk|Xk|h Zi`Hd'`YghU%#`bWcf a Yfi a'  
gYVlnhU|h/
- ◆ <||\!%i hZ`YXWwGk|h Uk|Xh [fYfYhU%|bW`&i hZ`YXWwGcZ  
Unk|Xk|h Zi`Hd' [fYfYhU%&|bWcf a Yfi a' gYVlnh Zi`Hd'`cf' E  
Z`YXWwGcZUnk|Xk|h Zi`Hd' [fYfYhU%&|bWcf`||\`gYVlnh Zi`Hd''

**FYUfcd|cbg**

- ◆ @ck! BcU|b'cf gU VwWg/
- ◆ A Yfi a ! gU VwWg/
- ◆ <||\! gU VwWgU|dmUZ`Xh'dUWcf fYUWhYgU'



: ||ifY7%&'D77HÜjYgY7fUWg'

§' Si fUj]m7fUWgID77L

SYGdjb

Si fUj]mVWj] gVgXVnhYbU] ]ncZhYWBWYk]hgUXXj]fdaYbU' ZWfggWUgZYVhukVWg'-hi gUnlUWfgUdUMB'cZMVGfihh' parallel to a joint or linear crack. A dark coloring can usually be seen around the fine XfUj]mVWg'Hlgnd'cZMVGj' aUnjYbUmVXleXghN]fulbcZhY WBWYk]h]b%c'SZYfSSle\*SSa]`jaYVgicZhY^chidVW'

GjY]h@jYg

@ ÍSÍ VWj] \gXjYodXgYFUWg]MVYUaci hZgUVfUk]h` ]hYcf bcXghN]fulbcf: CS'dhU' cfÍSÍ VWj] \gVWfX]bU] ]a]X fUcZhYgUzgWUg]bcYcfkVWg]cfUch' db'ch'Vih]WgUfY a]gh UXXghN]fulb\UgVWfX'GaY: CS'dhU'

A ÍSÍ VWj] \gXjYodXgYFUWg]MVYUaci hZgUVfUk]h` XghN]fulbcf: CS'dhU' cfÍSÍ VWj] \gVWfX]bU] ]a]X fUcZhYgUzgWUg]bcYcfkVWg]cfUch' db'ch'Vih]WgUfY a]gh UXXghN]fulb\UgVWfX'GaY: CS'dhU'

< ÍSÍ VWj] \gXjYodXgYFUWg]MVYUaci hZgUVfUk]h` XghN]fulbcZ: CS'dhU'



8% >chhGU'SUa U YD7L

>chhGU'SUa U YgUmWbNjdbzk\JWbUVgg] cffcVgk UWai UYbhY^chh  
cfUck'g]hZUHbZfUd'bcZkUP"5Wai U'bcZbMadYgVYaUMUgjb'  
hY'chhY YghYgUVZca YdbNj Uxauingj hbVWlqzgUMlqzcf  
gU]h"DJUVY'chh' YVbWkchYX'YgZhYgUgdchh'chhZca hY  
UWai U'bcZaUMUgUxUg'cfY YgkU'Zca gXh' XkbUXgZb] hY  
Zi bX]bgj dbf] hYgV' HdWlndgZ'chhGU'SUa U YU'Y%'g]dd] hY  
'chhSUH'&N]i gbcZ'chhSUH' HkX]fckh/(E\UXh] 'cZHY'Y')E  
'cgicZcbXkchYgUVX'YgUx\*EUWcfUgVWczgUUh]bhY'chh

**Gj YlDg**

- ◆ @ck ! ]b[ YbUn]ccXWbNjdbhfi [\cihYgN]db"GUUH]gdMZfa]h' kY k]h'cbnUa ]b]fUaci bhcZUnicZhYUj YndgczLa U YdYgHh
- ◆ A W]a ! ]b[ YbUn]fVbNjdbhfi [\cihYgN]dbzk]h'dYcfacfYcZ UnicZhYUj YndgczLa U YdYgHicWff]h] ]cUacXUUYX]fY" GUUHbX]g]aa YUUYdUW YHk]h]b&N]f/
- ◆ <||\ ! ]b[ YbUn]bcfVbNjdbhfi [\cihYgN]dbzk]h'dYcfacfYcZ UnicZhYUj YndgczLa U YgYgHicWff]h] ]cUg] YX]fY"GUUH bX]g]aa YUUYdUW YH

**FYUfcd]hg**

- ◆ @ck ! BcU]cb/
- ◆ A W]a ! gU^chh
- ◆ <||\ ! gU^chh



: ||ifY7%'D7 >chhGU'SUa U Y'

**88! GaU DUWID77L**

5' dUWlgUBfUk\ YfhYcfll jBU'dj Ya Yh  
has been removed and replaced by a filler

aUfJU': cfWbXllcbY U UjcbzdUWll lg  
Xj jXXllc lkc lndg' gaU fngghU) 'gei UfY  
ZNUUXUf Yfj Y) 'gei UfYZNL'@Uf YdUWg'  
UfYXgUfVXj bhYbl hgUfcb'

**Gj Yfllg:**

- ◆ @k! DUWlgZblcbll kY'zkjh'  
'llhYcfbcXfllcfUjcb/
- ◆ A Yfi a ! DUW\lgXfllcfUfXZUbf  
acXfUfYgdU' ll WbVYgXbUfcbXhY  
Yf Yg' DUWa UfJU WbVYg'cX YZ  
kjh WbgXfUfYfZfllh jcf: C8'  
dUfllUf/
- ◆ < ll \ ! DUW\lgXfllcfUfXZUfYfVn  
gdU' ll UfcbXhYdUWcfWUfll'  
kjh bhYdUWZc UgdUf\ jWkUfUfllg'  
fYUWa Yh

**FYUfcdllcbg**

- ◆ @k ÈScBchll /
- ◆ A Yfi a ! FYUWdUWcfFYUWY  
gUf
- ◆ < ll \ ÈFYUWdUWcfFYUWYgUf



**: llifY7% 'D77 GaU DUW'**

**&" @U[YDUWID77L**

Patching is the same as defined **ZfUgaU`dUW`  
 \ckYVzhYufUcZhYdUWlgacfyhUb) 'gi UY  
 ZN15 i f]mWlgUdUWhUgfyUWkhY  
 cf] jU'dj Ya YHMMgycZdUWa YhcZ  
 i bXf ci bXi f]jNg'HYgj Ylmj YgcZLi f]m  
 WlfYhYga YghcgYZffYi U'dUWj."**

**GjYfng**

- ◆ @ck? DUWlgZbUjcbj kY'zkjh `jhycf  
bcXNfcdUjcb/
- ◆ A Yjia ! DUW\UgXNfcdUWZbXf  
acXUygU'j VbVYgYbUci bXhY  
Y'Yg'DUWa UqJU VbVYg'cX'Yzkjh'  
WbgXUUYZcfih jcf: CS'dNHU/
- ◆ < j\ ! DUW\UgXNfcdUWZyhYVn  
gdU'j Uci bXhYdUWcfVWUj k]h'b'  
hYdUWZc UgUMk\jWkUffUg'  
fyUWa Yh

**FYUfcdjbg**

- ◆ @ck E8cBch] /
- ◆ A Yjia ! FYUWdUWcfFYUWWhYgU'
- ◆ < j\ E'FYUWdUWcfFYUWWhYgU'



**: j]ifY7% 'D77 @U[YDUW'**



**&" Dddi lgiD77L**

5' dddi HgUga U` d]WwZdj Ya YHhUfNUg` cogYZca hYg fZWX Yc ZYH  
hUk UWcb]bWa VbUcbk]h Y d]g] YU [fY UHg' Dddi lgi g UnU] YZca`  
Udd ja UYn]bWlc ( ]bWYg]X]a YfUxZca %&]bWlc &]bWgXnd"

**Gj YfNg**

No degrees of severity are defined for popouts. < ckY Yzddi lgaig HYYHNgj Y  
VZfYh YnfYw HX]g U]g]Yg ]Yzj YU Yddi hX]ghiaig H VWX  
Udd ja UYn]fYddi lgi f gi UYn]fXj YhYH]fYg UVfU



**: ]ifY7%. 'Dddi lgi'**

**&" Dadh ID77L**

**8YAdhb**

**Dadh lghYYMbcZaUhfUvkUfhci [\ `c]hgcfVWgWigXVhWZMcb:  
cZhYgWi bWfdigh `cUg'5ghYkUf'lgYWwZ]hUf]YgdffWgcZ] f]j YzghZ  
WncfgHbXyj lgbUdc]fygj YcgicZdj Ya Yhg ddbHG fAWg]h] Ux  
VgYcf]V]fUYaUhfU'cbhYdj Ya YhVgYc^c]hgcfVWgUfyj]Wwcz  
dadh'Dadh bnf^c]hg]bWUgdcf^c]hgUYUx'cgicZj ddbfk\]Wk]'`  
'YXlcVW]h] i bWfYUUX'cUg'**

**GjY]h@jYg**

**BcX]fygcZjY]hufXW]bX'hggZ]W]hlc]bXUfhUdadh Y]gg'**



&" GUVh ID77L

AUWVWd'cfVtHh'fYZgkUbllkf'czgUdczZbZcf\Uf]bVWghU  
YfXcbnhfi[\hYiddf'gZWCzhYWBWYHYWVgFXlc]bWgWU  
U]YgZ/SSX]fYg'AUWVWd'cfVtHh]lgjgUmWgXVnjYfZhg]hY  
WBWYUxaUmXlc:gU]h'cZhYgfZWk\|W]ghYfU\_XkbcZhYgV  
gZAWcUXh of approximately 1/4 to 1/2 inW'GU]h'aUhgVWgXVn  
]adcfWgh]V]bUXdcfU[f]UY'5bchYfW]h]XgiFWcZNg]gghY  
fU]bVWkYbhYU\_U]g]BUC'UX? &E]bgaYWaY]gUXWU]ba]bU]g]b'  
gaYU[f]UYg'UcXVgZfaYXnhYfU]bVWkYbhYU\_U]g]UXU[f]UY  
fj]h]Yd]g]ghU]gYUfU\_Xkb]hYWBWY'

GjYfHj

- ◆ @k! 7U]h'cfAUWVWd'Y]ggjYg]bZAWhgUfUHYgZAW]g]b'  
[ccXW]h]b]k]h]bc:gU]h'HYWVWdU]b]a]g]MkY X]b]X]X  
Y]n]f]W]b]h]X
- ◆ A]Y]a!GU]gg]Y]X]g]Y]U]h]d]a]U]Y]n]i'cf'Y]g]c]Z]h]Y]g]f]Z]W]k]h]g]a]Y  
:CS'd]h]U]/
- ◆ <||\!GU]gg]Y]Y]g]Y]X]W]g]h]U]||\:CS'd]h]U]'g]U]n]a]c]f]h]U]b'  
)i'c]Z]h]Y]g]f]Z]W]g]U]Z]W]X



**&": U 1h 1D77L**

**GHya Yhcf Zi 1h 1g UXZZYbWcZYj UjbUu'cjhcf VUWUg XVnid YjU' cfVhg' jUjcb'**

**Gj Yfng**

Severity levels are defined by the difference in elevation across the fault and the

	<b>Fi bkUng#U jkUng</b>	<b>5dfcbg</b>
@	<b>0% 1bW</b>	<b>% E% 1bW</b>
A	<b>% E% 1bW</b>	<b>% 1bW</b>
<	<b>2% 1bW</b>	<b>2% 1bW</b>

**FYUfCdcbg**

- ◆ @k! BcUjcb'
- ◆ AYa a E; f1Nj Udh hY'chh
- ◆ <|| E; f1Nj 'cf'chicUXUhgZfng'fUjcb'



**&" G UMFYXGUVFD77L**

**=hfgNMh VWGufYVWghUMFU ]hcZifcfacydWgVWU gczj YcUjh' UxwfhDXeiUYgdhffHY\|\!severity level of this distress type, as defined below, lghZfYXlc UgUg UMFYXgU'ZU' dWgc fVWgufYVWghUj bXkjh bUWbf VNUzhYXgUgUgUj YWbfVNU"**

**Gj YfHg**

- ◆ **@ck! Slab is broken into four or five pieces with the vast majority of the cracks fj Y, ) dWVhcZck!gj YfHh**
- ◆ **AWja ! (1) Slab is broken into four or five pieces with over 15 percent of the VWGcZaYja gj YfHhc \|\!gj YfHhVWg/cffgU|gVc\_Y]hc'gl' cfacydWgkjh'gj Y, ) dWVhcZhYVWgZck! /**
- ◆ **<|\! 5hlg^Y Y'Zgj YfHhYgU|gWYXg UMFYXgU|gVc\_Y]hc' four or five pieces with some or all of the cracks of high severity; (2) slab is Vc\_Y]hc'gl' cfacydWgkjh'gj Y%) dWVhcZhYVWgZaYja! cf \|\!gj YfHh**

**FYUfcdhcg**

- ◆ **@ck EGU'7UWg/**
- ◆ **AWja !: i`Xdh dUWcffYUWhYgU'**
- ◆ **<|\!: i`Xdh dUWcffYUWhYgU'**



&" Gflb\_ qY7f0WfD77L

Gflb\_ qY7f0WfD77L qf]bY7f0WghUhfYi gUnobnUZk ZYhcd| UbXXcbdi  
YfN6XUWgghYfHfYgU'VH YnfYZfa YXf]d| hfYg]d| UbXW]d| 'cZfY  
WbWfYUfXig UnkcbdiNfNhfci | \ hfYXdh 'cZfYgU'

**GjYfNg**

No degrees of severity are defined. It is sufficient to indicate that shrinkage cracks exist.

**FYUfcdhbg**

- ◆ 8cBch]d



"

'S' >chhGUgfD7L


>chhGUh lghYXghN fUbcZHYgUVX Ygkjh b&ZYrZHYgXZHY'chH'  
5'chhGU i gUnKXgbcN Nbxj MjU mnci [\ hYgUZA HhGgUghY'chHh  
UbU' Y'GU' h' Ng l'Zca YWgij YgYggUthY'chH'WU gXVh'Z'U'cb'  
cZbWadYgVYaUhfUgcfH'Z'W'Ug' KYU WbWYUthY'chH'U gXVn  
cj Ykcf h'EWa VbXkjh h'Z'W'Ug'g'U'chY'W'g'Z'g'U' h''

**Gj Yhng**

- ◆ @k! gj Y&ZYhcdj UxlgVc\_Y]bc'acfyhUbhfYd]WgXVbXVn  
'ck'cfa Y]a' gj Y]mWVgkjh ^]hY'c'bc: CS'dbhU'Z'cf'g&'YghU'  
&ZYhcdj UxlgVc\_Y]bc'acfyhUbhfYd]WgXVbXVn ^]hY: CS'cf]Y  
XaU'YdnhU/
- ◆ A Y]a ! gj Y&ZYhcdj UxlgVc\_Y]bc'acfyhUb' d]WgXVbXVn]]\h  
cfa Y]a WVg'cf'ga Y: CS'dbhU'Y ]gh'Z'cf'g&'YghU'&ZYhcdj '  
UxlgVc\_Y]bc'd]Wg'cf'Z]a Y]Xkjh'ga YcZ'Yd]Wg'cg'Y'cf'U'ghZ'  
W]gh W]gXUVY: CS'cf]YXaU'YdnhU/
- ◆ <]]\! gj Y&ZYhcdj UxlgVc\_Y]bc'acfyhUbhfYd]WgXVbXVn'cbY  
cfacY]]\ 'gj Y]mWVgkjh ^]]\ : CS'dbhU'

**FYUfCd]bg**

- ◆ @k! BcU]cb/
- ◆ A Y]a ! d]Z'fa Udu]U'X'h'dUW
- ◆ <]]\! d]Z'fa Udu]U'X'h'dUW'



'% 7cbfGdUgd77L

7cbfGdUd ghYfYH'cfVfUXkbcZhYgUkjhBUdIdJaUYn&ZncZ  
hYVbf"5 WbfGdU XZfZca UWbfVfU JbhUHfYgdUUh'YgXkKUX  
lcJbfGdUfchk\YhYVfU YfXgjVfU nhfi[\ hYgU'

**GjYfng**

- ◆ @k! YhY%hYgdU'lgVc\_Yb]bc'dYcfkcdWgXfXVnck'gjYfhn  
VWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/
- ◆ AYfja È%hYgdU'lgVc\_Yb]bc'kcd'afYdWgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'
- ◆ <J\ È%hYgdU'lgVc\_Yb]bc'kcd'afYdWgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'  
gjYfhnVWgkjh`JhYcfbc: CS'ddHfU/cf&hYgdU'lgXfXVnckYaYfja'

**FYUfCdHbg**

- ◆ @k! BcUfcb/
- ◆ AYfja! dffUXh'dUW
- ◆ <J\! dffUXh'dUW





' &'5GF 'ID77L

5GF 'lgW gXVhWwá ]W'fUWfcbVhK YbU\_UlgUkXWfUjbfUWj Yg ]Wwá ]bMUG  
k\ ]WZfa U ]Y' HY ]Y UgcVgkUfZVg gh ' Y d h g d b k \ ]Wwá U h á U ]YhY  
WbMfYUxIXUWhgí VifYg' 5` UlgUfYacgicZb ]hfcXVXVhYdchUx  
Vá Yhkh ]bhYdj Yá Yh' 5GF 'WUW ] 'a U h YUWYUfXVhWwá ]W'dj Yá Yh  
X ]Wg'

Jlg U ]bXWUfghU5GF 'a U h YdYgHh ]WXY'

% 7UW ] 'cZHYWbMfYdj Yá YhZb ]bUa UfdUMbE

& K \ ]ZVfkb ] fúicfchYWcfX ]Y'cfgh ]h 'a U h YdYgHhU ]YUW  
g fW

' " 5 [ ] f ] UYddi lg

(" -bMfY ]bWbMfYj c'ia YfU d h g d h Ua U h Yg' ]hXgff ]bcZUXWfif  
]h ]fU'gí VifYgcf d ng ]UYYá Ylg'9 U ad YgcZ ]d h g d b ]WXYg'c ]h 'cZ  
Ugd Uhdj Yá Ylg' [ \ ]Wb ]h ]h žgUZI ]h ž'c ]h a ]gU ] ]ba YhZUxUf g d b c z  
'c ]h g U g c f Y d h g d b 'c ]h ] 'Yg'

6WU g'5GF 'ga U ]U'XVhWwá 5GF 'lg ]YMU n d YgHh fci [ \ c ] h Y d j Yá Yh  
gUfcb' 7cfh ] UxWbMfYcMf ] fú ]WUngg'ghYcbn ]W ]h ] Yá YhcXc'  
WZfa hYdYgWcZ5GF' HYZ`ck ]h ] g'c' Xv\_Yh ]ba ]Xk \ ]b ]Wb ]h ]h '  
hYdYgWcZ5GF hci [ \ ] ]g U ]hgUfcb

%; YMU n5GF XgYggUfYbdcVg ]Y ]bhYZf ]Zk' nUgUZYVh ]h ]Wcb' -b  
WbUgZdU ]Wg'f ] U ]YUW ]h ] W'cWf hYXh'cZU ]h ]h ]WcbUx ]gUd ]f ]h  
k ]h ]bhYZf ]h ]f'

& 5GF 'lgXVhWwá ]W'fUWfcbVhK YbU\_UlgUkXWfUjbfUWj Yg ]Wwá ]bMUG  
hY'c ]hW 8:7UW ] 'dYXa ]b ]h ]MfY YodgUgUfYgcZdU ]YUWg'c'  
'c ]hWgUx ]b ]fWUW ]h ] k ]h ]bhYgU'

' " 5GF 'lgXVhWwá ]W'fUWfcbVhK YbU\_UlgUkXWfUjbfUWj Yg ]Wwá ]bMUG  
Y d h g d b'


**GjYfhi@jYg**

**@** A|jaUlebc: cf||bCVVNSUaU|YECSE'ddnh|UZca VWG/c|hgcf5GF' fYUXdddi lg/VWGUhYg fZWFYH| \HFYKa|b|hm?aa'cf~Yg|@|hY lebcY|NBWcZag Ya Yh|bdj Ya Yhcf g ffdi b|h| g| VifgcfYYa Ylg'

**Gca Y: CS'ddnh|U/|b|NGXgkY|h| 'cfchY: CS'fYag U'a YhcXga UnWY f|i |fX' A UnWY|NBWcZg'Uvag Ya Yh|bX'cf ga YXa U|Yc UXW|h g| VifgcfYYa Ylg'**

**A** A Y|i a'5GF Xg|Ng|g|N|Z|N|h|UXZca ~ck Vm|U|h| 'dbYcfadYcZhY ZE`ck|h|. |b|NGX: CS'ddnh|U|b|NGX|W|h| 'cZhYgUzga YZU'a Ylg' Ud| VWGcfU|W|h|N|G|N|d|g|fYg|h|g fZWFddi lg'Z|W|N|Y'a Un cW|Z|U|b|c|Z|k|N|VWg|fYKa|b|hm?aa'cfk|N|h|U'a UnWY g'Vj|N|X|h|| \hfVWg'

**<** ObYcfVh'cZhYZE`ck|h| Y|g| %|@|cgYcfalg|h| W|N|Y|ZU'a Ylgk\|W dg\|| \: CS'ddnh|U|Z &EGU'g fZWF|N|f|h|U|X|Z|b|N|b|g| h|Z|W|h|n X|f|U|X|U|X|dj Ya Yh'f|i |Ng|aa Y|U|Y|U|f/'a UnUg'f|i |fY|U|g|e' UXW|h|g| VifgcfYYa Ylg'



This Page Intentionally Left Blank

**APPENDIX D**

**DETAILED PAVEMENT CONDITION DATA**



5@SCH7caVbYSS8%89%

; YbUWASUY

%89%8888

DjY%Z

BVkc.	885	BuY	FcWjg	JYX			
GfUW	58%	BuY	5dcb\$%CbHJU	Ig	5DFCB	5fU	))ž+' Gc h
GWjcb	%	cZ %	: fca.	HUjkUn7cbNMfS&	H.	9(YcZDjYh	@Gj7cbgH' '#%888
GfUW	57	: Ua]m	5@SCH5dcbg	NcbY	7UWcfm		FUb. G
5fU		))ž+' Gc h	@Y[h.	'SS:h	KPh.	%) : h	
GUg		GUW@Y[h.	: h	GUWkPh.	: h	>ch@Y[h.	: h
Gcd Xf.		GfYHhdY		; fUX \$		@Uyg \$	
GwJcb7caaYhg							

Kcf_SUY	' #888%	Kcf_HdY	Bk7cbgUcb! :hJU	7cX	BI !B		=gAUcfA/ F. HfY
Kcf_SUY	- #88%	Kcf_HdY	7UWGUH !'57	7cX	7G57		=gAUcfA/ F. :UgY
Kcf_SUY	- #88%	Kcf_HdY	GfUWfUlaYH'GifinGU	7cX	GHG		=gAUcfA/ F. :UgY

@GjhgH'SUY	%8888%	HUcladYg	%&	GfjYK	(		
7cbjcbg	D7= *						
-hgNjcb7caaYhg							

GladYBaVf.	%	HdY	F	5fU	)8888Gc h	D7=	*+
GladY7caaYhg							
(	@CB; H 8-B5@HF5BGJ9FC0'	@		(888 : h			
	7F57?-B;						
(	@CB; H 8-B5@HF5BGJ9FC0'	A		%)'88 : h			
	7F57?-B;						
)+	K95H 9F-B;	@		&8888 Gc h			
)+	K95H 9F-B;	A		&8888 Gc h			

GladYBaVf.	\$	HdY	F	5fU	)8888Gc h	D7=	*)
GladY7caaYhg							
(	@CB; H 8-B5@HF5BGJ9FC0'	@		%)'88 : h			
	7F57?-B;						
(	@CB; H 8-B5@HF5BGJ9FC0'	A		%888 : h			
	7F57?-B;						
)&	F5J9@B;	@		)888 Gc h			
)+	K95H 9F-B;	@		&+)88 Gc h			
)+	K95H 9F-B;	A		&+)88 Gc h			

GladYBaVf.	\$	HdY	F	5fU	(&888Gc h	D7=	*,
GladY7caaYhg							
(	@CB; H 8-B5@HF5BGJ9FC0'	@		)888 : h			
	7F57?-B;						
(	@CB; H 8-B5@HF5BGJ9FC0'	A		%888 : h			
	7F57?-B;						
)+	K95H 9F-B;	@		&8888 Gc h			
)+	K95H 9F-B;	A		&8888 Gc h			

GladYBaVf.	%	HdY	F	5fU	(&888Gc h	D7=	+%
GladY7caaYhg							
(	@CB; H 8-B5@HF5BGJ9FC0'	@		&'88 : h			
	7F57?-B;						
(	@CB; H 8-B5@HF5BGJ9FC0'	A		%8888 : h			
	7F57?-B;						
)+	K95H 9F-B;	@		&8888 Gc h			
)+	K95H 9F-B;	A		&8888 Gc h			

BYkcf_	885	BláY	FcWlbg JYX
GfUDW	FS &	BláY	FilkÚn!&CbMHU I g FIEK5M 5fU "'*Z\$Gh
GWlch	%	cZ &	: fca. FilkÚn) 9BX H. FilkÚn& 9BX @g]7cbg' - #8888
GfZAW	57	: Úa]m 5@SCHFKg	NbY 7UH]cfm FUb. D
5fU	' &Z\$Gh	@Y[h.	(Z) : h K]Ph. , \$: h
GUg		GU@Y[h.	: h GUVK]Ph. : h >ch@Y[h. : h
Gci Xf.		GfYHhY	; fUX \$ @Uyg \$
Gw]cb7caa Ylg			
Kcf_8UY	%#S%-	Kcf_HdY Bk7cbg Vcb! :h]U	7cX BI !-B =gAUcfA/ F. HiY
Kcf_8UY	- #8888	Kcf_HdY &'g YUm	7cX C&S& =gAUcfA/ F. HiY
Kcf_8UY	%#S8%	Kcf_HdY 7UWGUH] !'57	7cX 7G57 =gAUcfA/ F. : UgY
Kcf_8UY	%#%8%	Kcf_HdY GfZAWGU! 7cUHF	7cX GG7H =gAUcfA/ F. : UgY
@g]hgl'8UY	%8888%	HBUCladyg *	GfjYhX ,
7cb]hbg	D7= +,		
-hg]W]cb7caa Ylg			
QádYBi aVf.	\$	HdY F	5fU *8888Gh D7= +,
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		'+) '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	%	HdY F	5fU *8888Gh D7= , \$
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		'\$) '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	%	HdY F	5fU *8888Gh D7= +'
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		)') '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	&	HdY F	5fU *8888Gh D7= +,
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		'+) '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	' &	HdY F	5fU *8888Gh D7= +
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		' '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	'-	HdY F	5fU *8888Gh D7= , %
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		& '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	(*	HdY F	5fU *8888Gh D7= +,
QádY7caa Ylg			
(,	@CB; H 8-B5@H5BGJ9FC@' @		'+) '\$\$ : h
	7F57?-B;		
)+	K95H 9F-B;	@	*8888 Gh
QádYBi aVf.	)'	HdY F	5fU *8888Gh D7= , \$
QádY7caa Ylg			

(, @CB; H 8-B5@F5BGJ9FC0' @ ' %'SS : h  
7F57?-B;  
)+ K95H 9F-B; @ \*SSSS G: h

BYkcf.	885	BláY	FcWlbg JYX				
GfUW	FS &	BláY	FibkÚi\$!&CbMHU	I gY	FIEK5M	5fYU	''*Z\$Gz h
GMlch	\$&	cZ &	: fca.	FibkÚi& 9bX	H.	9(YcZDjYh	@Gj7cbgH' - #8888
GfZUW	57	: Úa]m	5@SCHFKg	NcbY	7UH[cfm		FUb. D
5fYU		,ž(\$Gz h	@Y[h.	% : h	K]Ph.	, \$: h	
GUg		GU@Y[h.	: h	GUVK]Ph.	: h	>ch@Y[h.	: h
Gci Xf.		GfYWHdY		; fUX \$		@Ug \$	
GMlcb7caa Ylg							
Kcf_8UY	%#S%-	Kcf_HdY	Bk7cbgVcb!h]U		7cXY BI!B		=gAUcfA/ F. HiY
Kcf_8UY	-#8888	Kcf_HdY	&'qYUm		7cXY C@S&		=gAUcfA/ F. HiY
Kcf_8UY	%#S%	Kcf_HdY	7UWGUH!57		7cXY 7G57		=gAUcfA/ F. :UgY
Kcf_8UY	%#S%	Kcf_HdY	GfZUWGU!7cUHF		7cXY GG7H		=gAUcfA/ F. :UgY
@Gj7cbg'8UY %8888%							
7cb]cbg D7= +,							
-hg]Mlcb7caa Ylg							
GladYBi aVf. \$%							
HdY F 5fYU ((SSSSGz h D7= ++							
GladY7caa Ylg							
(&CB; H 8-B5@HF5BGJ9FC@' @ &)'SS : h							
7F57?-B;							
)+ K95H 9F-B; @ ((SSSS Gz h							
GladYBi aVf. \$&							
HdY F 5fYU ((SSSSGz h D7= +							
GladY7caa Ylg							
(&CB; H 8-B5@HF5BGJ9FC@' @ &\$SS : h							
7F57?-B;							
)+ K95H 9F-B; @ ((SSSS Gz h							



BVkc_f.	885		BUaY	FcW]hg ]YX			
GfUW	H79%		BUaY	HI]kUr7dbNMfS%CbKHU I g	H5L-K5M	5fYU	, 3*' Gc h
GM]ch	%	cZ %	: fca.	FibkUr!)&		H. H<U]UfS%	@U]7cb]h' *#(888
GfZUW	57	: Ua]m	5@SCH57HI]kUg	NcbY		7U]cfm	FUb. G
5fYU		, 3*' Gc h	@Y]h.	&S: h	K]Ph.	' S: h	
GUg		GU@Y]h.	: h	GUVK]Ph.	: h	>cb]h@Y]h.	: h
Gci Xf.		GfY]HhY		; fUX \$		@U]g \$	
GM]cb7caaYlg							
Kcf_8UY	%888%		Kcf_HhY	Bk7cb]h' V]cb! :h]U	7cX	BI !:B	=gAUcfA/ F. HhY
Kcf_8UY	*#(888		Kcf_HhY	Bk7cb]h' V]cb! :h]U	7cX	BI !:B	=gAUcfA/ F. HhY
Kcf_8UY	-#88%		Kcf_HhY	7U]WGU]h' !:57	7cX	7G57	=gAUcfA/ F. :Ug
Kcf_8UY	-888%		Kcf_HhY	GfZUW-FUaYH' Gifm]GU	7cX	GHG	=gAUcfA/ F. :Ug
@U]7cb]h'8UY	%888%		HhU]cladyg	&		GfjY]X	&
7cb]h]cbg	D7= +)						
-hg]NM]cb7caaYlg							
GladyEiaVf.	%	HhY	F	5fYU	),, ('SSGc h	D7= +)	
Glady7caaYlg							
(,	@CB; H 8-B5@#F5BGJ9FC0' @			%888 : h			
	7F57?-B;						
)+	K95H:9F-B;	@		&(888 Gc h			
)+	K95H:9F-B;	A		&(888 Gc h			
GladyEiaVf.	&&	HhY	F	5fYU	&+ 'SSGc h	D7= +)	
Glady7caaYlg							
(,	@CB; H 8-B5@#F5BGJ9FC0' @			)'SS : h			
	7F57?-B;						
)+	K95H:9F-B;	@		%(888 Gc h			
)+	K95H:9F-B;	A		%-'SS Gc h			

BYkcf. 885 BUAY FcWlbg JYX

GfUW H7S& BUAY HI]kUn7dbNMfS8Cb8HU I g/ H5L-K5M 5fU +2% G& h

GM]ch \$% cZ % : fca. FikUn9)!& H. 5drb\$% @Gj7ch]H' '#%888

GfZUW 57 : Ua]m 5@SCH57HI]kUg NdbY 7UH]cfm FUb. G

5fU +2% G& h @Y[h. %& h K]Ph. ') : h

GUg GUV@Y[h. : h GUVK]Ph. : h >ch@Y[h. : h

Gci Xf. GfYWHdY ; fUX \$ @Ug \$

GM]cb7caa Ylg

Kcf\_8UY '#%888 Kcf\_HdY Bk7ch]V]cb! :h]U 7cX BI!-B =gAUcfA/ F. HiY

Kcf\_8UY -#488% Kcf\_HdY 7UWGUH]!57 7cX 7G57 =gAUcfA/ F. :Ug

Kcf\_8UY -#888% Kcf\_HdY GfZUWH]UaYH]Gifin]GU 7cX GHG =gAUcfA/ F. :Ug

@Gj7ch]H'8UY %8888% HRUcladyg & GfjYnX &

7ch]V]ch]g D7= +&

=gAUcfA/ F. :Ug

GladyBiavf. \$% HdY F 5fU (,, '\$\$G& h D7= \*-

Glady7caa Ylg

(, @CB; H 8-B5@HF5BGJ9FG' @ ' \$\$\$ : h  
7F57?-B;

)& F5J9@B; @ %\$\$\$ G& h

)+ K95H 9F-B; @ &- ('\$\$ G& h

)+ K95H 9F-B; A &- ('\$\$ G& h

GladyBiavf. \$& HdY F 5fU &&'\$\$G& h D7= +

Glady7caa Ylg

(, @CB; H 8-B5@HF5BGJ9FG' @ ('\$\$ : h  
7F57?-B;

(, @CB; H 8-B5@HF5BGJ9FG' A \$\$\$ : h  
7F57?-B;

)+ K95H 9F-B; @ &&'\$\$ G& h

BYkcf.	885	BLAY	FcWlbg JYX				
6fUW	H 5B; %	BLAY	HI]kUia U]f\$%CbYHU	I g	H5L-K5M	5fU	)z+( G e h
GM]ch	%	cZ %	: fca.	5dcb\$%	H.	H<U]Ug	@U]7cbg]i %##88X
GfZAW	57	: Ua]m	5@8CH57HI]UBg	NcbY	7U]cfm		FUb. H
5fU	)z+( G e h	@Y]h.	&& h	K]Ph.	888: h		
GUg		GU@Y]h.	: h	GUVK]Ph.	: h	>cb]@Y]h.	: h
Gci Xf.		GfY]HhY		; fUX \$		@U]g \$	
GM]cb7caa Ylg							
Kcf_8UY	%##88	Kcf_HndY	Bk7cbg]U]cb! :h]U		7cX BI !-B		=gAUcfA/ F. H]Y
Kcf_8UY	%##88X	Kcf_HndY	Bk7cbg]U]cb! :h]U		7cX BI !-B		=gAUcfA/ F. H]Y
Kcf_8UY	-#88%	Kcf_HndY	7U]WGU]h !'57		7cX 7G57		=gAUcfA/ F. :Ug
Kcf_8UY	-#88%	Kcf_HndY	GfZAW-FUa YH'Gifm]GU		7cX GHG		=gAUcfA/ F. :Ug
@U]i:hg]'8UY %8888%							
HBUCladyg %							
GfjY]X -							
7cb]U]cbg D7= +%							
-hg]U]cb7caa Ylg							
GladY]iaVf. %							
HndY F 5fU (*)'88G e h D7= *-							
GladY7caa Ylg							
(	@CB; HI 8-B5@HF5BGJ9FC@	@		888 : h			
	7F57?-B;						
(	@CB; HI 8-B5@HF5BGJ9FC@	A		%888 : h			
	7F57?-B;						
)+	K95H 9F-B;	@		88;'88 G e h			
)+	K95H 9F-B;	A		88;'88 G e h			
GladY]iaVf. \$&							
HndY F 5fU (*)'88G e h D7= *&							
GladY7caa Ylg							
()	89F9GCB	A		(-'88 G e h			
(	@CB; HI 8-B5@HF5BGJ9FC@	@		88'88 : h			
	7F57?-B;						
(	@CB; HI 8-B5@HF5BGJ9FC@	A		%888 : h			
	7F57?-B;						
)&	F5J9@B;	A		, '88 G e h			
)+	K95H 9F-B;	@		&%88 G e h			
)+	K95H 9F-B;	A		&%88 G e h			
GladY]iaVf. \$							
HndY F 5fU ')%88G e h D7= *-							
GladY7caa Ylg							
(	@CB; HI 8-B5@HF5BGJ9FC@	@		88'88 : h			
	7F57?-B;						
(	@CB; HI 8-B5@HF5BGJ9FC@	A		%888 : h			
	7F57?-B;						
)+	K95H 9F-B;	@		%, '88 G e h			
)+	K95H 9F-B;	A		%,)'88 G e h			
GladY]iaVf. \$							
HndY F 5fU )*888G e h D7= *'							
GladY7caa Ylg							
(	@CB; HI 8-B5@HF5BGJ9FC@	@		*888 : h			
	7F57?-B;						
(	@CB; HI 8-B5@HF5BGJ9FC@	A		&888 : h			
	7F57?-B;						
)+	K95H 9F-B;	@		&%888 G e h			
)+	K95H 9F-B;	A		&%888 G e h			
GladY]iaVf. \$							
HndY F 5fU )*'888G e h D7= +*							
GladY7caa Ylg							
(	@CB; HI 8-B5@HF5BGJ9FC@	@		%888 : h			
	7F57?-B;						
(	@CB; HI 8-B5@HF5BGJ9FC@	@		(+'88 : h			
	7F57?-B;						
(	@CB; HI 8-B5@HF5BGJ9FC@	A		%)'88 : h			
	7F57?-B;						

QldYBiaVf. \$ HdY F 5fU \*\$'\$\$Geh D7= ,\*

QldY7caaYlg

(, @CB; HI 8-B5@HF5BGJ9FC@ %\$\$\$ :h  
7F57?-B;  
)+ K95H:9F-B; @ \*\$'\$\$ Geh

QldYBiaVf. \$ HdY F 5fU \*\$ %\$\$Geh D7= \*'

QldY7caaYlg

(, @CB; HI 8-B5@HF5BGJ9FC@ +\$\$\$ :h  
7F57?-B;  
(, @CB; HI 8-B5@HF5BGJ9FC@ A \$\$\$ :h  
7F57?-B;  
)\$ D5H<-B; @ (,'\$\$ Geh  
)+ K95H:9F-B; @ ' \$\$\$ Geh  
)+ K95H:9F-B; A ' \$\$\$ Geh

QldYBiaVf. % HdY F 5fU )%'\$\$Geh D7= \*\*

QldY7caaYlg

(, @CB; HI 8-B5@HF5BGJ9FC@ ' \$\$\$ :h  
7F57?-B;  
(, @CB; HI 8-B5@HF5BGJ9FC@ A &)'\$\$ :h  
7F57?-B;  
)+ K95H:9F-B; @ )%'\$\$ Geh

QldYBiaVf. %& HdY F 5fU \*\$ %\$\$Geh D7= , \$

QldY7caaYlg

(, @CB; HI 8-B5@HF5BGJ9FC@ @ '+\$\$ :h  
7F57?-B;  
(, @CB; HI 8-B5@HF5BGJ9FC@ A , \$\$\$ :h  
7F57?-B;  
)+ K95H:9F-B; @ \*\$ %\$\$ Geh

BVkf.	85	BuY	FcWbg JYX				
GUBW	HFK9	BuY	HI]kUnHfHfci bXFK 9'	I g	H5L-K5M	5fU	(Z% G h
GUb	%	cZ %	: fca.	FibkUn!&	H.	9(YcZUj YaYh	@g7chg! - #8888
GfZW	57	: Ua]m	5@SCH57HI]kUg	NbY	7U]cfm		FUb. D
5fU	(Z% G h	@Y[h.	)S:h	K]h.	++:h		
GUg	GU@Y[h.	:h	GVK]h.	:h	>ch@Y[h.		:h
Gci Xf.	GfYHhY		; fUY \$		@Ug \$		
GUb7caaYhg							
Kcf_8UY %8%8%-		Kcf_HdY Bk7chg! h]U		7cX BI !B		=gAUcfA/ F. HiY	
Kcf_8UY - #8888		Kcf_HdY &'gYUm		7cX C@S&		=gAUcfA/ F. HiY	
Kcf_8UY %8%88%		Kcf_HdY 7UWGUH !57		7cX 7G57		=gAUcfA/ F. :Ug	
Kcf_8UY %8%88%		Kcf_HdY GfZWGU!7UHF		7cX GG7H		=gAUcfA/ F. :Ug	
@g7chg!8UY %8888%		HRUladYg %		GfjYhX %			
7cb]hdg D7= ,*							
hgUb7caaYhg							
QadYBi aVf. %		HdY F	5fU	((%)88G h		D7= ,*	
QadY7caaYhg							
(, @/ H7F		@	%88 :h				
)+ K95H 9F-B;		@	((%)88 G h				

**APPENDIX E**  
**DISTRESS SUMMARY REPORT**









This Page Intentionally Left Blank

## **APPENDIX F**

### **PAVEMENT CONDITION REPORTS**

F1: Section Forecasted Pavement Condition Rating

F2: Branch PCI Rating

F3: Branch FOD Rating



**Appendix F1**  
**Forecasted Section PCI**  
 Robbins Field (20A)

Branch ID	Section ID	Forecasted PCI						
		2021	2022	2023	2024	2025	2026	2027
A01	01	70	68	65	63	61	59	57
RW0624	01	77	74	71	70	70	70	68
RW0624	02	77	74	71	70	70	70	68
TC01	01	77	75	72	70	66	62	57
TC02	01	74	71	69	65	60	56	51
THANG01	01	73	70	67	63	59	54	49
TTRW05	01	86	83	81	79	77	75	72

%&#18888

### 6fUw7cbXhcbFYhcfh

DjY%&Z&

DjY YHSUUGY 5@SCH7ca VbYSS%&#%

6fUw7s	Bi a Vf cZ GMjcbg	G a 'GMjcb' @b  h HE	5j  'GMjcb' KPh HE	Hi Y5fU Re: E	I gY	5j MU Y D7=	GRbXEX 8Y Jhcb' D7=	KM  \HX 5j MU Y D7=
5#%	%	' \$\$\$	%) '\$	))ž+' '\$	5DFCB	*, '\$	\$ \$\$	*, '\$
F\$ &	&	(žž '\$	, \$ \$\$	'' *žž '\$	FI BK5M	+, '\$	\$ \$\$	+, '\$
H7\$%	%	& \$ \$\$	' \$ \$\$	, ž *' '\$	H5L-K5M	+) '\$	\$ \$\$	+) '\$
H7\$&	%	% & \$\$	' ) '\$	+ž% '\$	H5L-K5M	+& \$\$	\$ \$\$	+& \$\$
H 5B; \$%	%	& & \$\$	\$\$ \$ \$	)ž+( '\$	H5L-K5M	+% \$\$	\$ \$\$	+% \$\$
HFK\$)	%	) \$ \$	+ '\$	(ž% '\$	H5L-K5M	, * '\$	\$ \$\$	, * '\$

%896:8888
Dj Y&cZ&
  
**6fubW7cbYhcbFYbch**
  
Dj Ya YHSUWUgY 5@BCH7ca VbYSS88%

I gY7UW  cfm	Bi a VYfcZ GWM cbg	HEU'5fYUQe: IL	5fh a YjW 5j YU  YD7=	5j YU  YGfB D7=	KY  \ fX 5j YU  YD7=
5DFCB	%	) ) 2+ '88	, '88	\$88	, '88
FI BK5M	&	' ' * 28 \$88	+ '88	\$88	+ '88
H5L-K5M	(	+ 2 ** '88	+ * '88	) ! *	+ & -
5@@	+	(* - 28 - '88	+ ) ('	) ) \$	+ ) ; -

, #&#\$\$\$%
DUY%Z&
  
**6fUw7cbXhcbFYhfh**
  
 DjYaYHSUUVgy 5@SCHS\$%

6fUw7s	Bi a VfcZ GMfcbg	G a 'GMfcb' @b h HE	5j  'GMfcb' KPh HE	Hi Y5fYU RGe HE	I gy	5j YU Y : CS' DcHhJU	GRbXEX 8Y Jhcb' : CS'DcH	KY  \HX 5j YU Y : CS'DcHb
5\$%	%	' \$\$\$	%) '\$	))ž+' '\$	5DFCB	(* '\$	\$ \$\$	(* '\$
F\$ &	&	(žž '\$	, \$ \$\$	'' *žž '\$	FI BK5M	' (' '\$	\$ \$\$	' (' '\$
H7\$%	%	& \$ \$\$	' \$ \$\$	, ž *' '\$	H5L-K5M	' , '\$	\$ \$\$	' , '\$
H7\$&	%	% & \$\$	' ) '\$	+ž% '\$	H5L-K5M	(% '\$	\$ \$\$	(% '\$
H 5B; \$%	%	& & \$\$	\$\$ \$ \$	)ž+' '\$	H5L-K5M	( & '\$	\$ \$\$	( & '\$
HFK\$)	%	) \$ \$	+' '\$	(ž% '\$	H5L-K5M	&' '\$	\$ \$\$	&' '\$

**6fubW7cbYhcbFYbfn** **DjY&cZ&**  
**DjY YHSUWY 5@BCHSS %**

I gY7UW  cfm	B  a VYfcZ GWM cbg	HEU'5fYUQe: IL	5fha YfW 5j YU Y: CS	5j YU YGB' : CS DcHb U'	KY  \ BX 5j YU Y: CS D
5DFCB	%	) ) 2+ 'SS	(*SS	SSS	(*SS
FI BK5M	&	' ' * 2 \$SS	' ('SS	SSS	' ('SS
H5L-K5M	(	+ 2 ** 'SS	' * ) \$	* ' , \$	( \$ ) \$
5@@	+	(* - 2 - 'SS	' + %	* ' ,	' * [ -

**APPENDIX G**

**SAFETY AND PREVENTIVE MAINTENANCE POLICIES**





**Appendix G1**  
**Localized Safety (Stopgap) Repair Policy**

Distress	Distress Severity	Description	Code	Work Type	Work Unit
41	High	ALLIGATOR CR	PA-FD	Patching - AC Full-Depth	SqFt
43	High	BLOCK CR	CS-AC	Crack Sealing - AC	Ft
45	High	DEPRESSION	PA-FD	Patching - AC Full-Depth	SqFt
47	High	JT REF. CR	CS-AC	Crack Sealing - AC	Ft
48	High	L & T CR	CS-AC	Crack Sealing - AC	Ft
50	High	PATCHING	PA-FD	Patching - AC Full-Depth	SqFt
53	High	RUTTING	PA-FD	Patching - AC Full-Depth	SqFt
54	High	SHOVING	PA-PD	Patching - AC Partial-Depth	SqFt
55	NA	SLIPPAGE CR	PA-PD	Patching - AC Partial-Depth	SqFt
56	High	SWELLING	PA-FD	Patching - AC Full-Depth	SqFt
61	High	BLOW-UP	SL-PC	Slab Replacement - PCC	SqFt
61	Medium	BLOW-UP	PA-PF	Patching - PCC Full Depth	SqFt
62	High	CORNER BREAK	PA-PF	Patching - PCC Full Depth	SqFt
63	High	LINEAR CR	PA-PF	Patching - PCC Full Depth	SqFt
63	Medium	LINEAR CR	CS-PC	Crack Sealing - PCC	Ft
64	High	DURABIL. CR	SL-PC	Slab Replacement - PCC	SqFt
64	Medium	DURABIL. CR	PA-PF	Patching - PCC Full Depth	SqFt
66	High	SMALL PATCH	PA-PP	Patching - PCC Partial Depth	SqFt
67	High	LARGE PATCH	PA-PF	Patching - PCC Full Depth	SqFt
70	High	SCALING	SL-PC	Slab Replacement - PCC	SqFt
71	High	FAULTING	GR-PP	Grinding (Localized)	Ft
72	High	SHAT. SLAB	SL-PC	Slab Replacement - PCC	SqFt
74	High	JOINT SPALL	PA-PP	Patching - PCC Partial Depth	SqFt
75	High	CORNER SPALL	PA-PP	Patching - PCC Partial Depth	SqFt
76	High	ASR	SL-PC	Slab Replacement - PCC	SqFt

Appendix G2  
Localized Preventive Repair Policy

<b>Dstress</b>	<b>Dstress Severity</b>	<b>Description</b>	<b>Code</b>	<b>WorkType</b>	<b>Work Unit</b>
41	Medun	ALLGATORCF	PAAC	Patching- ACFull Depth	Sqft
41	Hgh	ALLGATORCF	PAAC	Patching- ACFull Depth	Sqft
42	NA	BIBBING	PAAS	Patching- ACPartial Depth	Sqft
42	Hgh	BLOCKCR	PAAC	Patching- ACFull Depth	Sqft
42	Medun	BLOCKCR	CSAC	GackSealing- AC	R
44	Low	CORRUATION	PAAS	Patching- ACPartial Depth	Sqft
44	Hgh	CORRUATION	PAAS	Patching- ACPartial Depth	Sqft
44	Medun	CORRUATION	PAAS	Patching- ACPartial Depth	Sqft
42	Medun	DEPRESSION	PAAC	Patching- ACFull Depth	Sqft
42	Low	DEPRESSION	PAAC	Patching- ACFull Depth	Sqft
42	Hgh	DEPRESSION	PAAC	Patching- ACFull Depth	Sqft
42	Hgh	JIRE CR	CSAC	GackSealing- AC	R
42	Medun	JIRE CR	CSAC	GackSealing- AC	R
42	Hgh	L&TCR	CSAC	GackSealing- AC	R
42	Medun	L&TCR	CSAC	GackSealing- AC	R
42	NA	OILSPILLAGE	PAAC	Patching- ACFull Depth	Sqft
51	Hgh	PAKING	PAAC	Patching- ACFull Depth	Sqft
51	Medun	PAKING	PAAC	Patching- ACFull Depth	Sqft
52	Hgh	RAVING	PAAS	Patching- ACPartial Depth	Sqft
52	Hgh	RUIDING	PAAC	Patching- ACFull Depth	Sqft
52	Low	RUIDING	PAAC	Patching- ACFull Depth	Sqft
52	Medun	RUIDING	PAAC	Patching- ACFull Depth	Sqft
52	NA	SLIPPAGECR	PAAC	Patching- ACFull Depth	Sqft
52	Low	SWELLING	PAAC	Patching- ACFull Depth	Sqft
52	Medun	SWELLING	PAAC	Patching- ACFull Depth	Sqft
61	Low	BLOWUP	PAH	Patching- FCCFull Depth	Sqft
61	Medun	BLOWUP	PAH	Patching- FCCFull Depth	Sqft
61	Hgh	BLOWUP	PAH	Patching- FCCFull Depth	Sqft
62	Medun	CORNERBREAK	PAH	Patching- FCCFull Depth	Sqft
62	Hgh	CORNERBREAK	PAH	Patching- FCCFull Depth	Sqft
62	Low	CORNERBREAK	CSFC	GackSealing- FC	R
62	Medun	LINEARCR	CSFC	GackSealing- FC	R
62	Hgh	LINEARCR	PAH	Patching- FCCPartial Depth	Sqft
64	Medun	DURABL CR	PAH	Patching- FCCFull Depth	Sqft
64	Hgh	DURABL CR	SLFC	SkbReplacement- FC	Sqft
62	Hgh	JISEALDMG	JSIC	Jirt Seal (Localized)	R
62	Medun	JISEALDMG	JSIC	Jirt Seal (Localized)	R
62	Hgh	SMALLPATCH	PAH	Patching- FCCPartial Depth	Sqft
62	Medun	SMALLPATCH	PAH	Patching- FCCPartial Depth	Sqft
62	Medun	LARGEPATCH	PAH	Patching- FCCFull Depth	Sqft

Appendix G2  
Localized Preventive Repair Policy

<b>Dstress</b>	<b>Dstress Severity</b>	<b>Description</b>	<b>Code</b>	<b>WorkType</b>	<b>Work Unit</b>
<b>6</b>	<b>Hgh</b>	<b>LARGEPAICH</b>	<b>PAH</b>	<b>Patching- FCCFull Depth</b>	<b>SqFt</b>
<b>6E</b>	<b>N/A</b>	<b>PUMING</b>	<b>JSIC</b>	<b>Joint Seal (Localized)</b>	<b>R</b>
<b>7</b>	<b>Medun</b>	<b>SCAING</b>	<b>PAH</b>	<b>Patching- FCCPartial Depth</b>	<b>SqFt</b>
<b>7</b>	<b>Hgh</b>	<b>SCAING</b>	<b>SLR</b>	<b>Slab Replacement- FCC</b>	<b>SqFt</b>
<b>7I</b>	<b>Hgh</b>	<b>FAILING</b>	<b>GRH</b>	<b>Girding (Localized)</b>	<b>R</b>
<b>7I</b>	<b>Medun</b>	<b>FAILING</b>	<b>GRH</b>	<b>Girding (Localized)</b>	<b>R</b>
<b>7Z</b>	<b>Medun</b>	<b>SHR SLAB</b>	<b>SLR</b>	<b>Slab Replacement- FCC</b>	<b>SqFt</b>
<b>7Z</b>	<b>Hgh</b>	<b>SHR SLAB</b>	<b>SLR</b>	<b>Slab Replacement- FCC</b>	<b>SqFt</b>
<b>7A</b>	<b>Hgh</b>	<b>JONISPAIL</b>	<b>PAH</b>	<b>Patching- FCCPartial Depth</b>	<b>SqFt</b>
<b>7A</b>	<b>Medun</b>	<b>JONISPAIL</b>	<b>PAH</b>	<b>Patching- FCCPartial Depth</b>	<b>SqFt</b>
<b>7C</b>	<b>Medun</b>	<b>CORNERSPAII</b>	<b>PAH</b>	<b>Patching- FCCPartial Depth</b>	<b>SqFt</b>
<b>7C</b>	<b>Hgh</b>	<b>CORNERSPAII</b>	<b>PAH</b>	<b>Patching- FCCPartial Depth</b>	<b>SqFt</b>
<b>7E</b>	<b>Medun</b>	<b>ASR</b>	<b>SLR</b>	<b>Slab Replacement- FCC</b>	<b>SqFt</b>
<b>7E</b>	<b>Hgh</b>	<b>ASR</b>	<b>SLR</b>	<b>Slab Replacement- FCC</b>	<b>SqFt</b>

## **APPENDIX H**

### **M&R UNIT COSTS**

H1: M&R Unit Costs

H2: Component Costs for Repair

H3: Airport Category

---

## Maintenance and Repair (M&R) Unit Costs

The M&R costs developed for the ALDOT PMP include costs for maintenance, preservation, and repair activities and are described below.

### Unit Costs Source Data

The source for the M&R costs data is RSMMeans, which has data for 14 locations throughout Alabama, as identified by the yellow highlighted boxes in Figure 1. The cost data is presented in terms of individual line items like asphalt wearing course, aggregate base etc., which were consolidated to develop the activity costs described below.

The cost data show a distinct difference in costs between locations north and south of Birmingham, especially for the higher value items like the asphalt layers. Therefore, the unit costs were developed accordingly for the airports north and south of Birmingham, as identified in Figure 1. Appendix H2 presents the component costs used in developing the M&R costs.




Figure 1: RSMMeans Unit Costs Locations.

**Maintenance & Repair (M&R) Activities**

Maintenance activities are localized activities which are typically assigned in the first year of the M&R plan based on the observed distresses.

Repair activities are further subdivided into preservation, rehabilitation, and reconstruction. Repair activities are conducted for larger areas, typically at the section level and are assigned based on the Critical Pavement Condition Index, denoted as CP in Table 1. The CP is based on the section’s rank or importance within the overall network and typically ranges from 55 to 70. The CP was set at 70 for the ALDOT runway pavements and 65 for the other pavements.

*Table 1: Repair Activities.*

Activity Type	PCI	Activity
Preservation	> CP	Runway Surface Treatment
		Taxiway and Apron Surface Treatment
Rehabilitation	> CP	2" AC OL <sup>1</sup>
	55 - CP	Mill 2" & 2" AC OL
	45 - 55	Mill 2" & 3" AC OL
Reconstruction	0 - 45	Reconstruct with AC

<sup>1</sup>For Sections with Structural Distress and PCI greater than Critical PCI

The depths for the milling and overlay (AC OL) in Table 1 were established by creating a balance between removal of surficial distress and providing additional pavement structural capacity. All overlay options include full-depth patching to repair localized distresses.

From the FAA 5010 records, the Alabama airport network includes a wide range of allowable aircraft loads. The airports were divided into three categories of allowable aircraft loads based on requirements for minimum pavement thickness and the use of a P-401 surface layer. The categories are based on the aircraft maximum gross takeoff weight (MGTOW) and include: less than 12,500 lbs, 12,500 to 30,000 lbs, and 30,000 to 100,000 lbs. Appendix H3 presents the category for each airport.

For any sections requiring reconstruction, the pavement sections were established primarily in accordance with the requirements in Table 3 of the FAA’s Advisory Circular 150/5320-6F. The pavement sections used for developing the cost estimates are:

≤ 12,500 lbs	4" P-403 (State HMA Mix) + 6" P-209 Base
12,500 – 30,000 lbs	4" P-403 (State HMA Mix) + 8" P-209 Base
30,000 – 100,000 lbs	5" P-401 + 10" P-209 Base

It is important to note that while the FAA requires a stabilized base for those pavements that support aircraft operations with MGTOWs that are greater than 100,000 lbs, the number of such operations is minimal for those airports shown in Appendix H3. As a result, the cost of a stabilized base is excluded in the development of the unit costs for ALDOT’s PMP update. However, based on the Engineer’s future design and aircraft fleet mix development, project-level construction work could include the use of a stabilized base at that time.

**M&R Unit Costs**

Paving projects typically include additional project costs like mobilization, design, construction administration and inspections, and drainage improvements. A summary of non-direct pavement construction line items has been included in the unit costs in Tables 5 and 6 as described below. These non-direct items are expressed as a percentage of the total component costs for each activity.

These non-direct pavement construction items were developed from API’s extensive experience with APMP project cost estimation. These percentages may vary for Alabama airport construction projects; however, since the direct pavement scope of work is estimated in a network-level evaluation, these conservative estimates serve as a good starting point for the development of realistic total project costs and annual APMP budgets for ALDOT. For repair activities such as Mill & Overlay, which typically do not include significant drainage work, the corresponding multiplier was reduced by 50 percent. The non-direct cost factors are presented in Table 2.

*Table 2: Cost Factors.*

Factor	Function of	Estimate		
		Preservation	Rehabilitation	Reconstruction
Mobilization	All costs, less design	10%	10%	10%
Drainage Improvements	Paving costs	-	4%	8%
Contingency	All costs, less mobilization and design	10%	20%	20%
Design & CM	All costs, less mobilization and design	15%	20%	20%

The M&R unit costs for maintenance, preservation, and repair activities were developed from the RSMMeans cost data and are presented in the following section.

***Maintenance***

The maintenance activities include crack seal, and full and partial-depth patching. The unit costs are presented in Table 3.

*Table 3: Unit Costs for Maintenance.*

Activity	Unit Cost	Unit
Seal Cracks - AC	\$3.95	lf
AC Full-Depth Patching	\$25.05	sf
AC Partial-Dept Patching	\$16.28	sf
Seal Cracks – PCC	\$6.00	lf
PCC Full-Depth Patching	\$35.00	sf
PCC Partial-Depth Patching	\$175.00	sf
Jt. Seal	\$8.00	lf
Slab Replacement	\$20.00	sf

**Preservation**

The unit costs for the surface treatments are presented in Table 4. They include sealing of cracks and application of pavement markings.

*Table 4: Unit Costs for Preservation Activities.*

Activity	Unit Cost	Unit
Runway Surface Treatment	\$0.57	sf
Taxiway and Apron Surface Treatment	\$0.88	sf

**Rehabilitation and Reconstruction**

As discussed previously, repair activities are also divided into rehabilitation and reconstruction. The unit costs for airport repair for the Northern Region (Birmingham Area) and Southern Region (Montgomery Area) are shown in Tables 5 and 6, respectively.

*Table 5: Unit Costs for Repair Activities, Northern Region.*

Activity Type	Activity	MGTOW, thousand lbs		
		≤ 12.5	12.5-30	30-100
Rehabilitation	2" AC OL	\$3.78		\$4.19
	Mill 2" & 2" AC OL	\$4.15		\$4.56
	Mill 2" & 3" AC OL	\$5.18		\$5.79
Reconstruction	AC Reconstruction	\$8.40	\$9.10	\$10.91

*Table 6: Unit Costs for Repair Activities, Southern Region.*

Activity Type	Activity	MGTOW, thousand lbs		
		≤ 12.5	12.5-30	30-100
Rehabilitation	2" AC OL	\$3.54		\$3.91
	Mill 2" & 2" AC OL	\$3.90		\$4.27
	Mill 2" & 3" AC OL	\$4.82		\$5.37
Reconstruction	AC Reconstruction	\$7.63	\$8.25	\$9.87



**Appendix H2**  
**Component Costs for Repair**

Activity Type	Unit	Birmingham (Northern)	Montgomery (Southern)	Comments
Milling 1" to 3"	SY	\$2.08	\$2.01	
Pavement Demolition	SY	\$6.34	\$6.12	
Haulage - For Demolition & AC	CY	\$6.08	\$5.87	
Haulage for 12" Thick Demolition	SY	\$2.03	\$1.96	
Haulage for 2" Thick AC Paving	SY	\$0.34	\$0.33	
Haulage for 3" Thick AC Paving	SY	\$0.51	\$0.49	
Haulage for 4" Thick AC Paving	SY	\$0.68	\$0.65	
AC Wearing Course	Ton	\$97.42	\$86.90	
AC Binder Course	Ton	\$87.80	\$78.17	
P401 - For airports with >60 kip aircraft	Ton	\$116.90	\$104.28	Assumed P401 cost to be 20% greater than AC Wearing Course
6" Aggregate Base (P208)	SY	\$10.17	\$9.12	
8" Aggregate Base (P208)	SY	\$13.29	\$11.89	
6" P209 Aggregate Base	SY	\$12.20	\$10.94	Assumed P209 cost to be 20% greater than P208
8" P209 Aggregate Base	SY	\$15.95	\$14.27	Assumed P209 cost to be 20% greater than P208
10" P209 Aggregate Base	SY	\$19.94	\$17.84	Direct multiplier for 10" from 8"
4" P154 Aggregate Base	SY	\$5.42	\$4.86	Assumed P154 cost to be 20% lower than P208
6" P154 Aggregate Base	SY	\$8.14	\$7.30	Assumed P154 cost to be 20% lower than P208
Pavement Markings	sf	\$1.48	\$1.39	

**Appendix H3  
Airport Category**

Region	City	FAA ID	Max Gross Weight (Thousand lbs)			Max GW	Category
			S	D	2D		
Birmingham	Reform	3M8	12.5	-	-	12.5	<= 12,500
	Fayette	M95	15.0	-	-	15.0	12,500-30,000
	Hamilton	HAB	15.0	-	-	15.0	12,500-30,000
	Scottsboro	4A6	15.0	-	-	15.0	12,500-30,000
	Alabaster	EET	16.0	-	-	16.0	12,500-30,000
	Centre-Piedmont	PYP	16.0	-	-	16.0	12,500-30,000
	Fort Payne	4A9	16.0	-	-	16.0	12,500-30,000
	Haleyville	1M4	20.0	-	-	20.0	12,500-30,000
	Hartselle	5M0	20.0	-	-	20.0	12,500-30,000
	Guntersville	8A1	24.0	-	-	24.0	12,500-30,000
	Cullman	CMD	30.0	-	-	30.0	12,500-30,000
	Russellville	M22	30.0	-	-	30.0	12,500-30,000
	Jasper	JFX	50.0	-	-	50.0	> 30,000
	Oneonta	20A	20.0	35.0	55.0	55.0	> 30,000
	Bessemer	EKY	60.0	60.0	-	60.0	> 30,000
	Albertville	8A0	60.0	90.0	130.0	130.0	> 30,000
	Madison	MDQ	60.0	75.0	140.0	140.0	> 30,000
	Decatur	DCU	75.0	125.0	150.0	150.0	> 30,000
	Tuscaloosa	TCL	61.0	87.0	168.0	168.0	> 30,000
	Gadsden	GAD	90.0	115.0	195.0	195.0	> 30,000
Montgomery	Florala	0J4	-	-	-	-	<= 12,500
	Elba	14J	4.0	-	-	4.0	<= 12,500
	Headland	0J6	12.0	-	-	12.0	<= 12,500
	Roanoke	7A5	12.0	-	-	12.0	<= 12,500
	Greenville	PRN	15.0	-	-	15.0	12,500-30,000
	Union Springs	07A	15.0	-	-	15.0	12,500-30,000
	Wetumpka	08A	15.0	-	-	15.0	12,500-30,000
	Atmore	0R1	16.0	-	-	16.0	12,500-30,000
	Clanton	02A	16.0	-	-	16.0	12,500-30,000
	Eufaula	EUF	16.0	-	-	16.0	12,500-30,000
	Geneva	33J	16.0	-	-	16.0	12,500-30,000
	Greensboro	7A0	16.0	-	-	16.0	12,500-30,000
	Centreville	0A8	18.0	-	-	18.0	12,500-30,000
	Ashland-Lineville	26A	20.0	-	-	20.0	12,500-30,000
	Sylacauga	SCD	20.0	-	-	20.0	12,500-30,000
	St. Elmo	2R5	23.0	-	-	23.0	12,500-30,000
	Ozark	71J	-	25.0	-	25.0	12,500-30,000
	Camden	61A	27.0	-	-	27.0	12,500-30,000
	Bay Minette	1R8	28.0	-	-	28.0	12,500-30,000
	Foley	5R4	28.0	-	-	28.0	12,500-30,000
Tuskegee	06A	28.5	-	-	28.5	12,500-30,000	

**Appendix H3  
Airport Category**

Region	City	FAA ID	Max Gross Weight (Thousand lbs)			Max GW	Category
			S	D	2D		
Montgomery	Alexander City	ALX	30.0	-	-	30.0	12,500-30,000
	Dauphin Island	4R9	30.0	-	-	30.0	12,500-30,000
	Pell City	PLR	30.0	-	-	30.0	12,500-30,000
	Prattville	1A9	30.0	-	-	30.0	12,500-30,000
	Enterprise	EDN	-	-	-	-	> 30,000
	Evergreen	GZH	30.0	50.0	-	50.0	> 30,000
	Marion	A08	30.0	50.0	-	50.0	> 30,000
	Selma	SEM	33.0	54.0	-	54.0	> 30,000
	Fairhope	CQF	36.0	58.0	-	58.0	> 30,000
	Brewton	12J	40.0	60.0	-	60.0	> 30,000
	Demopolis	DYA	30.0	38.0	60.0	60.0	> 30,000
	Monroeville	MVC	70.0	-	-	70.0	> 30,000
	Auburn-Opelika	AUO	45.0	75.0	-	75.0	> 30,000
	Talladega	ASN	30.0	65.0	95.0	95.0	> 30,000
	Gulf Shores	JKA	80.0	100.0	-	100.0	> 30,000
	Troy	TOI	24.0	80.0	140.0	140.0	> 30,000
	Anniston	ANB	28.0	43.5	260.0	260.0	> 30,000
Andalusia-OPP	79J	98.0	160.0	275.0	275.0	> 30,000	

## **APPENDIX I**

### **PAVEMENT CAPITAL IMPROVEMENT PROGRAM**

I1: PCIP Summary

I2: Year 1 Maintenance Plan



**Appendix I1**  
**PCIP Summary**  
Robbins Field (20A)

Branch & Section	2021	2022	2023	2024	2025	2026	2027
A01-01	Preventive \$1710.48 Before:69.78 After:69.78	Preventive \$2395.07 Before:67.57 After:67.57	Preventive \$3119.74 Before:65.36 After:65.36	StopGap \$1044.08 Before:63.15 After:63.15	StopGap \$1216.93 Before:60.93 After:60.93	Required Project Major Below Critical \$302327.85 Before:58.72 After:100	Preventive \$149.53 Before:97.79 After:97.79
RW0624-01	Preventive \$7526.58 Before:77.27 After:77.27	Preventive \$8815.08 Before:73.88 After:73.88	Preventive \$9873.83 Before:71.42 After:71.42	Preventive \$10605.72 Before:70.11 After:70.11	Required Project Major Below Critical \$1733004 Before:69.8 After:100	Preventive \$504.54 Before:98.7 After:98.7	Preventive \$1006.65 Before:97.48 After:97.48
RW0624-02	Preventive \$198.5 Before:77.27 After:77.27	Preventive \$232.49 Before:73.88 After:73.88	Preventive \$260.41 Before:71.42 After:71.42	Preventive \$279.71 Before:70.11 After:70.11	Required Project Major Below Critical \$45705.6 Before:69.8 After:100	Preventive \$13.31 Before:98.7 After:98.7	Preventive \$26.55 Before:97.48 After:97.48
TC01-01	Preventive \$201.98 Before:76.61 After:76.61	Preventive \$224.6 Before:74.59 After:74.59	Preventive \$250.75 Before:72.29 After:72.29	StopGap \$100.32 Before:69.51 After:69.51	StopGap \$137.26 Before:66.06 After:66.06	Required Project Major Below Critical \$46668.35 Before:61.9 After:100	Preventive \$10.64 Before:98.98 After:98.98
TC02-01	Preventive \$182.98 Before:73.92 After:73.92	Preventive \$204.77 Before:71.49 After:71.49	StopGap \$87.31 Before:68.52 After:68.52	StopGap \$118.7 Before:64.85 After:64.85	StopGap \$157.46 Before:60.48 After:60.48	Required Project Major Below Critical \$38226.3 Before:55.62 After:100	Preventive \$8.71 Before:98.98 After:98.98

**Appendix I1**  
**PCIIP Summary**  
 Robbins Field (20A)

Branch & Section	2021	2022	2023	2024	2025	2026	2027
THANG01-01	Preventive \$1542.57 Before:73.06 After:73.06	Preventive \$1732.13 Before:70.45 After:70.45	Preventive \$2655.51 Before:67.23 After:67.23	StopGap \$1069.96 Before:63.3 After:63.3	StopGap \$1397.82 Before:58.7 After:58.7	Required Project Major Below Critical \$397028.08 Before:53.76 After:100	Preventive \$71.28 Before:98.98 After:98.98
TTRW05-01	Preventive \$65.42 Before:85.5 After:85.5	Preventive \$78.88 Before:83.03 After:83.03	Preventive \$92.03 Before:80.77 After:80.77	Preventive \$104.34 Before:78.72 After:78.72	Required Project Major Above Critical \$23355.35 Before:76.76 After:100	Preventive \$5.33 Before:98.98 After:98.98	Preventive \$11.61 Before:97.85 After:97.85

**Appendix I2**  
**Localized Maintenance Plan**  
Robbins Field(20A)

Branch ID	Section ID	Policy	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
A01	01	Preventive	48	L & T CR	Low	720	Ft	1.3	No Localized M & R	0		\$0.00	\$0
A01	01	Preventive	48	L & T CR	Medium	1,516	Ft	2.73	Crack Sealing - AC	1,516	Ft	\$3.95	\$5,988
A01	01	Preventive	52	RAVELING	Low	150	SqFt	0.27	No Localized M & R	0		\$0.00	\$0
A01	01	Preventive	57	WEATHERING	Low	27,661	SqFt	49.86	No Localized M & R	0		\$0.00	\$0
A01	01	Preventive	57	WEATHERING	Medium	27,661	SqFt	49.86	No Localized M & R	0		\$0.00	\$0
RW0624	01	Preventive	48	L & T CR	Low	19,792	Ft	6.04	No Localized M & R	0		\$0.00	\$0
RW0624	01	Preventive	57	WEATHERING	Low	327,600	SqFt	100	No Localized M & R	0		\$0.00	\$0
RW0624	02	Preventive	48	L & T CR	Low	530	Ft	6.13	No Localized M & R	0		\$0.00	\$0
RW0624	02	Preventive	57	WEATHERING	Low	8,640	SqFt	100	No Localized M & R	0		\$0.00	\$0
TC01	01	Preventive	48	L & T CR	Low	155	Ft	1.81	No Localized M & R	0		\$0.00	\$0
TC01	01	Preventive	57	WEATHERING	Low	4,282	SqFt	50.01	No Localized M & R	0		\$0.00	\$0
TC01	01	Preventive	57	WEATHERING	Medium	4,281	SqFt	49.99	No Localized M & R	0		\$0.00	\$0
TC02	01	Preventive	48	L & T CR	Low	334	Ft	4.76	No Localized M & R	0		\$0.00	\$0
TC02	01	Preventive	48	L & T CR	Medium	20	Ft	0.29	Crack Sealing - AC	20	Ft	\$3.95	\$79
TC02	01	Preventive	52	RAVELING	Low	100	SqFt	1.43	No Localized M & R	0		\$0.00	\$0
TC02	01	Preventive	57	WEATHERING	Low	4,520	SqFt	64.44	No Localized M & R	0		\$0.00	\$0
TC02	01	Preventive	57	WEATHERING	Medium	2,394	SqFt	34.13	No Localized M & R	0		\$0.00	\$0
THANG01	01	Preventive	45	DEPRESSION	Medium	59	SqFt	0.1	Patching - AC Full-Depth	95	SqFt	\$25.05	\$2,364
THANG01	01	Preventive	48	L & T CR	Low	698	Ft	1.22	No Localized M & R	0		\$0.00	\$0
THANG01	01	Preventive	48	L & T CR	Medium	1,633	Ft	2.85	Crack Sealing - AC	1,633	Ft	\$3.95	\$6,450
THANG01	01	Preventive	50	PATCHING	Low	58	SqFt	0.1	No Localized M & R	0		\$0.00	\$0
THANG01	01	Preventive	52	RAVELING	Medium	10	SqFt	0.02	No Localized M & R	0		\$0.00	\$0
THANG01	01	Preventive	57	WEATHERING	Low	35,691	SqFt	62.21	No Localized M & R	0		\$0.00	\$0
THANG01	01	Preventive	57	WEATHERING	Medium	14,795	SqFt	25.79	No Localized M & R	0		\$0.00	\$0
TTRW05	01	Preventive	48	L & T CR	Low	118	Ft	2.67	No Localized M & R	0		\$0.00	\$0
TTRW05	01	Preventive	57	WEATHERING	Low	4,415	SqFt	100	No Localized M & R	0		\$0.00	\$0