

Alabama Statewide Airport Pavement Management Program Update



Bill Pugh Field (M22)

Final Report

February 2022



Submitted to

Alabama Aeronautics Bureau

Submitted by



All About Pavements, Inc (API)
www.allaboutpavements.com

Pavement Management – Evaluation – Testing – Design

**ALABAMA STATEWIDE AIRPORT PAVEMENT MANAGEMENT
PROGRAM UPDATE**

Bill Pugh Field (M22)

FINAL REPORT

Prepared For:

Alabama Aeronautics Bureau
1409 Coliseum Blvd.
Montgomery, AL 36110

Prepared By:

ALL ABOUT PAVEMENTS, INC.
205 Ramblewood Drive
Chatham, Illinois 62629

February 2022

This Page Intentionally Left Blank

Executive Summary

The Aviation Inc. team, which included All About Pavements, Inc., (API) was awarded a contract by the Alabama Department of Transportation’s Aeronautics Bureau (ALDOT) in 2018 to update the existing Alabama Statewide Airport Pavement Management Program (APMP). The scope of this project includes the airside pavement network at Bill Pugh Field (M22).


The following APMP tasks were completed to achieve the project objectives at M22:

- Update the PAVER work history with records review information provided by ALDOT
- Conduct a visual pavement condition survey of the airfield pavements
- Update the PAVER database with inventory and condition data
- Update Maintenance and Rehabilitation (M&R) policies and unit costs
- Develop a 7-Year Pavement Capital Improvement Program (PCIP) with associated cost estimates

ES.1 Pavement Inventory

There are 5 branches and 10 sections within M22’s pavement network with a total surface area of approximately 0.6 million square feet (sf). Figure ES-1 shows the distribution of the pavement network by surface type and branch use.

Figure ES-1: Pavement Area (sf) by Surface Type and Branch Use.



ES.2 Pavement Condition

Visual pavement inspections were conducted in November 2019 using the Pavement Condition Index (PCI) method as specified in ASTM D5340-12 and FAA AC 150/5380-6C. The PCI is a numerical rating scale from 0 to 100 that provides a measure of the pavement’s functional surface condition. The overall



area-weighted network PCI (AW PCI) for the M22 pavement network is 77, representing a “Satisfactory” condition. The network area-weighted pavement age (AW Age) is 18 years.

Table ES-1 is a listing of the section PCI values and ratings.

Table ES-1: M22 Section PCI Values and Ratings.

Branch ID	Name	Section ID	Surface	Area, sf	PCI	PCI Category
A01	Apron 01	01	AC	91,746	89	Good
R0220	Runway 02-20	01	AC	189,600	81	Satisfactory
R0220	Runway 02-20	02	AC	185,175	73	Satisfactory
R0220	Runway 02-20	03	AC	37,725	75	Satisfactory
TA	Taxiway A	01	AC	5,043	74	Satisfactory
TA	Taxiway A	02	AC	4,723	85	Satisfactory
THANG01	Taxiway Hangar 01	01	AC	5,287	85	Satisfactory
THANG01	Taxiway Hangar 01	02	AC	14,522	54	Poor
THANG01	Taxiway Hangar 01	03	AC	25,480	41	Poor
TTRW02	TW Turnaround RW 02	01	AC	12,000	78	Satisfactory

ES.3 Pavement Maintenance and Repair Funding Levels

The PAVER database was updated with 2019 condition data, maintenance and repair (M&R) policies, and unit costs; which were then used to evaluate the effect of multiple funding levels on the overall future pavement condition. Figure ES-2 presents the forecasted M22 network PCI values for each funding level.

ES.4 Pavement Capital Improvement Program (PCIP)

The analysis output from the unlimited funding budget scenario was used as a starting point in developing the PCIP. For this scenario, sections were grouped into projects to allow for a logical construction sequence. Table ES-2 summarizes the 7-year PCIP, which has an estimated total cost of approximately \$2.6 million. These recommendations are based on a network-level evaluation. Project-level evaluations should be conducted prior to developing design and bid package documents.

In addition to the major rehabilitation needs that are identified in the PCIP, PAVER was used to develop maintenance activities to repair specific PCI distresses in Year 1. The estimated costs for these maintenance activities are \$6,117 as summarized in Table ES-3.



Figure ES-2: M&R Funding Levels.




Table ES-2: Summary of Pavement Capital Improvement Program.

Project Year	CIP Project	Total Project Cost	Total Project Area, sf	AWPCI Before	AWPCI After
2021	M22_21-01_Apron Preservation	\$89,197	101,756	86	93
	M22_21-02_Taxiway Hangar Reconstruction	\$316,261	40,002	41	100
2022	M22_22-01_Runway 02-20 Rehabilitation	\$1,893,014	429,543	71	100
2025	M22_25-01_Runway 02-20 Surface Treatment	\$281,576	429,543	96	99
Total		\$2,580,049			

Table ES-3: Summary of Localized Maintenance Plan.

Policy	Work Description	Work Quantity	Work Unit	Work Cost
Preventive	Crack Sealing - AC	632	Ft	\$2,498
Safety	Patching - AC Full-Depth	145	SqFt	\$3,620
Total				\$6,117

TABLE OF CONTENTS

1 INTRODUCTION 1-1

1.1. OVERVIEW 1-1

1.2. WORK SCOPE 1-1

1.3. PAVEMENT MANAGEMENT CONCEPT 1-2

2 AIRFIELD PAVEMENT INVENTORY 2-1

2.1. INTRODUCTION 2-1

2.2. PAVEMENT INVENTORY 2-1

2.3. CLIMATIC CONDITIONS 2-1

2.4. PAVEMENT NETWORK DEFINITION 2-2

2.5. INVENTORY SUMMARY 2-3

3 PAVEMENT CONDITION 3-1

3.1. INTRODUCTION 3-1

3.2. PAVEMENT CONDITION RATING METHODOLOGY 3-1

3.3. DISTRESS TYPES 3-2

3.4. ADDITIONAL PCI-BASED INDICES 3-3

3.5. PCI SURVEY RESULTS 3-4

3.6. PCC PAVEMENTS 3-5

4 PAVEMENT CAPITAL IMPROVEMENT PROGRAM 4-1

4.1. INTRODUCTION 4-1

4.2. PERFORMANCE MODELING 4-1

4.3. CRITICAL PCI VALUES 4-3

4.4. M&R POLICIES AND UNIT COSTS 4-3

4.5. PAVEMENT CIP DEVELOPMENT 4-4

4.6. PAVEMENT CAPITAL IMPROVEMENT PROGRAM 4-6



LIST OF TABLES

Table 2.1: Average Annual Temperatures and Rainfall for M22.....	2-2
Table 2.2: PCI Sampling Rate for AC Surfaces.....	2-3
Table 2.3: M22 Pavement Branches.....	2-3
Table 2.4: M22 Pavement Age.....	2-3
Table 3.1: Pavement Condition Index Rating Scale.....	3-2
Table 3.2: Section PCI.....	3-5
Table 4.1: M&R Activities and Unit Costs.....	4-4
Table 4.2: Summary of M&R Funding Level Analyses.....	4-6
Table 4.3: Summary of 7-Year PCIP by Project.....	4-7
Table 4.4: Summary of 7-Year PCIP by Project and Section.....	4-7
Table 4.5: Summary of Year-1 Maintenance Plan.....	4-8

LIST OF FIGURES

Figure 1.1: Pavement Management Concept.....	1-2
Figure 2.1: Bill Pugh Field.....	2-1
Figure 2.2: M22 Pavement Area by Surface Type.....	2-4
Figure 2.3: M22 Pavement Area by Branch Use.....	2-4
Figure 3.1: FOD Potential Rating Scale.....	3-3
Figure 3.2: Pavement Condition by Branch Use.....	3-4
Figure 3.3: Pavement Condition by Percent of Area.....	3-4
Figure 4.1: PCI Forecasting.....	4-2
Figure 4.2: Family Curves.....	4-2
Figure 4.3: Budget Analysis Process.....	4-5
Figure 4.4: M&R Funding Levels.....	4-5

APPENDICES

- Appendix A:** Pavement Inventory Report
- Appendix B:** PMP Maps
- B1: Inventory Maps
 - B1A: Branch Identification
 - B1B: Section Identification
 - B1C: Sample Unit Layout
 - B1D: Pavement Type
 - B1E: Branch Use
 - B1F: Pavement Age
 - B2: Surface Condition Maps
 - B2A: 7-Color PCI
 - B2B: 3-Color PCI
 - B2C: FOD Rating
 - B2D: Survey Photo Locations
 - B3: Pavement Capital Improvement Program (PCIP) Maps
 - B3A: 2027 Forecasted PCI without PCIP
 - B3B: Repair Type
 - B3C: PCIP Recommendations
- Appendix C:** Overview of Pavement Distresses
- Appendix D:** Detailed Pavement Condition Data (electronic version only)
- Appendix E:** Distress Summary Report
- Appendix F:** Pavement Condition Reports
- F1: Section Forecasted Pavement Condition Rating
 - F2: Branch PCI Rating
 - F3: Branch FOD Rating
- Appendix G:** Safety and Preventive Maintenance Policies
- Appendix H:** M&R Unit Costs
- Appendix I:** Pavement Capital Improvement Program (PCIP)
- I1: CIP Summary
 - I2: Year 1 Maintenance Plan
- Appendix J:** USB Thumb Drive – FINAL ONLY
- Final Report in PDF format
 - Geo-referenced Field Photos

1 Introduction

1.1. Overview

The Alabama Department of Transportation's Aeronautics Bureau (ALDOT) is responsible for preserving and enhancing Alabama's air transportation system, which consists of 74 general aviation airports throughout the State. ALDOT implemented an Airport Pavement Management Program (APMP) in 2008 using the PAVER system. ALDOT awarded a project in 2018 to Aviation Inc. (Aviation) to update the System Plan and conduct an Economic Analysis for the Alabama airports. The scope of work also included an update of the APMP for 59 general aviation airports, which was conducted by All About Pavements, Inc., (API), a Aviation team member.

With this update of the APMP, the Alabama airports continue to be eligible for FAA funding for major pavement rehabilitation work under the Airport Improvement Program (AIP) since an APMP meets the pavement maintenance management requirements described in Appendix A of AC 150/5380-6C.

This report discusses the evaluation of the airside pavements at Bill Pugh Field (M22), the current and forecasted pavement condition, and the development of the Pavement Capital Improvement Program (PCIP).

1.2. Work Scope

The goals of the Alabama Statewide Airport Pavement Management Update program are as follows:

- Conduct a visual pavement inspection of the asphalt surfaced pavements for 59 of the 74 general aviation airports in Alabama.
- Based on the visual inspection analysis results, develop a 7-year PCIP for each airport.

The scope of work is as shown below:

- Conduct a Records Review
- Update Pavement Network Definition
- Conduct Pavement Condition Surveys
- Update and customize existing APMP PAVER database
- Develop PCIP and associated project cost estimates
- Prepare Draft and Final Reports
- Develop a web-based viewer for reporting APMP data

As required in the Scope of Work, a detailed pavement condition survey was not conducted for any Portland Cement Concrete (PCC) aprons and PCC taxiways longer than 2,000 ft. Instead, a condition rating of "Good", "Fair", or "Poor" was assigned based on the overall pavement condition.

The deliverable products include a PAVER 7.0 database, individual airport evaluation reports, a statewide summary report, and the web viewer. The M22 report will be one of the 59 individual airport reports that will be available on ALDOT's website.




1.3. Pavement Management Concept

An APMP provides an integrated framework for comprehensive evaluation and decision making for managing airfield pavements. The essential components of an effective APMP provide for an objective evaluation of the condition of existing pavements, identification of short-term and long-range major rehabilitation work, necessary improvements in the pavement structural capacity, and the recurring maintenance work that should be completed each year. The APMP will also provide a budget for each of these types of pavement construction.

Historically, most organizations have made maintenance decisions based on past experience, without the benefit of documented data or analysis. This practice does not encourage life cycle cost analysis, nor the evaluation of cost effectiveness of alternate scenarios, and can lead to the inefficient use of funds. With limited allocated funding for Maintenance and Repair (M&R) Program projects, a defined procedure for setting priorities and schedules that will maximize the funds available is more important than ever.

In examining the lifespan of a 20-year pavement, a “Good” to “Fair” condition rating may last only 5 to 15 years. After that point, the rate of deterioration of pavements accelerates sharply as the age of the pavement increases, and within five years, the pavement may deteriorate to the point of failure. In order to extend pavement life, maintenance and repairs need to be scheduled and performed before the pavement surface declines to a “fair” condition. The point at which rehabilitation can be done before the steep decline occurs is called the “critical PCI”, and is generally considered to occur when the Pavement Condition Index (PCI) is between 60 and 70 for general aviation airports. If the work is done before deterioration accelerates, the cost of rehabilitation can be reduced as shown in Figure 1.1.

Figure 1.1: Pavement Management Concept.



2 Airfield Pavement Inventory

2.1. Introduction

M22 is a General Aviation (GA) airport located approximately 3 miles southeast of Russellville. The airport was activated in October 1969 and is owned and operated by the City of Russellville. Figure 2.1 shows an aerial image of the airport.

Figure 2.1: Bill Pugh Field.



(Source: Google Earth)

2.2. Pavement Inventory

M22 consists of one runway, a connector taxiway, and an apron. The total pavement area is approximately 0.6 million square feet. All pavements at M22 are Asphalt Concrete (AC) surfaced. A complete listing of the pavement sections is included in Appendix A. Runway 02-20 is 5,500 ft. long and 75 ft. wide.

A records search was undertaken to identify any preservation or rehabilitation work that has occurred at M22 since the last APMP update in 2009. The following records that were provided by ALDOT were reviewed, and the PAVER database was updated with work history information:

- Apron Reconstruction, 2012
- Sealcoat Runway 02-20, 2015

2.3. Climatic Conditions

Table 3.1 provides a summary of the climatic data for the geographic region that includes M22. As the table shows, the pavements at M22 are exposed to freeze-thaw cycles from December to February. The mean air temperature for January ranges from an average low of 28 degrees °F to an average high of 50 degrees °F. The average annual rainfall at M22 is near 57 inches.



Table 2.1: Average Annual Temperatures and Rainfall for M22.

	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
High Temp (°F)	50	55	63	72	79	86	90	89	84	74	63	53
Low Temp (°F)	28	30	38	44	53	61	66	64	58	45	37	31
Precip. (in)	5.4	4.8	6.3	5.0	5.9	4.2	4.7	3.0	4.2	3.4	5.1	5.4

Source: www.intellicast.com

2.4. Pavement Network Definition

A key element in developing an APMP system is defining the pavement network, which is the process of dividing an agency’s pavements into a hierarchical order that facilitates inspection and M&R planning. The M22 network (e.g. all airside pavements) is then divided into branches, which are a readily identifiable part of the pavement system and have distinct functions. For airports, branches typically consist of individual runways, taxiways and aprons. Figure B1A in Appendix B shows the branches at M22.

Once branches have been defined, pavement evaluation and analysis techniques require the airfield pavement system to be broken up into discrete sections. A pavement “section” is the smallest management unit that is used when considering the application and selection of maintenance and rehabilitation (M&R) treatments, and is defined in Section 2.1.8 of ASTM D 5340-12 as “a contiguous pavement area having uniform construction, maintenance, usage history, and condition. A section should also have the same traffic volume and load intensity.” A complete list of the pavement inventory and the corresponding section designations are included in Appendix A. Figure B1B presents the section layout.

To facilitate the visual survey of the airside pavement, each section is further subdivided into conveniently defined sub-section areas, or sample units. Similar sizing is critical as studies have found that maintaining the size of the sample units to within 40 percent of the established norm may reduce the standard error of the average PCI values. To meet that criteria, ASTM recommends that sample units for asphalt pavements be 5,000 square feet (± 2,000).

Table 2.2 was used as a guideline in developing sampling rates that reflect typical rates that are used for other large pavement networks. In general, this sampling rate will not provide a 95% confidence level with a standard error of 5 PCI points. A higher level of sampling is recommended before a project-level rehabilitation design is developed for a pavement section or facility.

Sample units that include a one-time occurrence of a distress (i.e. a large patch) or an unusual severity or quantity of a distress seen elsewhere, were designated as “additional” sample units as described in the ASTM D5340 PCI procedure. This allows the PCI to be calculated without extrapolating the aberrant distress throughout the section as a whole. In Appendix B, Figure B1C shows the sample unit layout for M22.



Table 2.2: PCI Sampling Rate for AC Surfaces.

Total Samples	Samples to Inspect
1	1
2	2
3 – 6	3
7 – 13	4
14 – 39	5
> 39	15 percent, but less than 12

2.5. Inventory Summary

There are 5 branches (facilities) at M22 that include 10 pavement sections and a total area of approximately 0.6 million square feet of paved surfaces, as shown in Table 2.3.

Table 2.3: M22 Pavement Branches.

Branch ID	Branch Name	Branch Use	Area, sf	Number of Sections
A01	Apron 01	APRON	91,746	1
R0220	Runway 02-20	RUNWAY	412,500	3
TA	Taxiway A	TAXIWAY	9,766	2
THANG01	Taxiway Hangar 01	TAXIWAY	45,289	3
TTRW02	TW Turnaround RW 02	TAXIWAY	12,000	1
Total			571,301	10

Table 2.4 shows the distribution of airfield pavement by age with the area-weighted age being 18 years for all airside pavements at M22.

Table 2.4: M22 Pavement Age.

Age (Years)	Number of Sections	Percent of Area	Area, sf
0 – 5	0	0	0
6 – 10	2	17	97,033
11 – 15	0	0	0
16 – 20	6	76	434,266
> 20	2	7	40,002

Figure 2.2 shows the distribution by surface type. Figure 2.3 presents the distribution by pavement use (e.g. runway, taxiway, and apron).



Figure 2.2: M22 Pavement Area by Surface Type.





Figure 2.3: M22 Pavement Area by Branch Use.



Maps B1D, B1E, and B1F show the pavement type, branch use, and pavement age, respectively.

3 Pavement Condition

3.1. Introduction

A visual PCI survey of the airside pavements at M22 was conducted in order to assist in the development of a realistic PCIP. The PCI survey measures and records pavement distresses that exist within each of the inspected sample units. This survey was conducted in November 2019 by a two 2-person team. The survey was performed in accordance with the methods described in ASTM D 5340-12 and FAA AC 150/5380-7B, using the sampling rates from Chapter 2 of this API report.

During the pavement survey, Quality Control (QC) and data verification were performed on both the individual distresses and the calculated section PCI values. QC included the following activities;

- Review of distress quantities to identify data entry errors (100% review at the sample unit level). General guidance was used from ASTM D5340-12, section 13, which addresses the precision of distress quantities that are recorded during PCI surveys.
- Duplicate surveys were performed to ensure consistency between each of the inspectors in a 2-person PCI survey team.

3.2. Pavement Condition Rating Methodology

The PCI is a measure of the pavement's functional surface condition. It provides insight into the causes of each distress, and whether the distress is primarily caused by load, climatic conditions, and other material related deficiencies. The PCI is a numerical rating (on a scale of 0 to 100) that is based on the type, severity and quantity of each distress that is found in an inspected sample unit.

The PCI survey results are displayed using seven categories and ratings in accordance with the ASTM, but can also be presented using a simplified 3-category rating system for use in comparing with other distress related indices, as shown in Table 3.1.



Table 3.1: Pavement Condition Index Rating Scale.

	Simplified PCI Color Legend	ASTM PCI Color Legend	PCI Range	PCI Ratings and Definition
GOOD			86-100	<u>GOOD</u> : Pavement has minor or no distresses and should require only routine maintenance.
			71-85	<u>SATISFACTORY</u> : Pavement has scattered low-severity distresses that should require only routine maintenance.
FAIR			56-70	<u>FAIR</u> : Pavement has a combination of generally low- and medium-severity distresses. Near-term maintenance and repair needs may range from routine to major.
POOR			41-55	<u>POOR</u> : Pavement has low-, medium-, and high-severity distresses that probably cause some operational problems. Near-term M&R needs range from routine to major. requirement for
			26-40	<u>VERY POOR</u> : Pavement has predominantly medium- and high-severity distresses that cause considerable maintenance & operational problems. Near-term M&R needs will be major.
			11-25	<u>SERIOUS</u> : Pavement has mainly high-severity distresses that cause operational restrictions; immediate repairs are needed.
			0-10	<u>FAILED</u> : Pavement deterioration has progressed to the point that safe aircraft operations are no longer possible; complete reconstruction is required.

3.3. Distress Types

The ASTM D5340 standard considers 17 distresses, which tend to fall into one of the following four cause categories:

- Load related: AC distresses include alligator cracking, corrugation, depression, polished aggregate, rutting and slippage cracking; PCC distresses include corner breaks, longitudinal cracking, divided slabs, polished aggregate, pumping and joint spalling.
- Climate and durability related: AC distresses include bleeding, block cracking, joint reflection cracking, longitudinal and transverse (L&T) cracking, swelling, raveling, and weathering; PCC distresses include blow-ups, “D” cracking, longitudinal cracking, pop-outs, pumping, scaling, shrinkage cracks, and joint and corner spalling.
- Moisture & Drainage related: AC distresses include alligator cracking, depressions, potholes and swelling; PCC distresses include corner breaks, divided slabs and pumping.
- Other factors: Oil spillage, jet blast erosion, bleeding, patching and concrete slab joint faulting.

As described above, distress may have more than one cause. For example, depressions may be caused by incorrect compaction during construction, or by subgrade softening due to environmental factors. In addition, a distress may be initiated by one cause but may progress to a distress of higher severity by another cause. Therefore, engineering judgment is critical in analyzing the actual causes of the distress.


Distress descriptions provided in Appendix C were taken from the “PCI Field Manual,” developed by the U.S. Army Construction Engineering Research Lab (CERL), latest edition. Appendix C provides a detailed explanation of each type of AC and PCC surface distress.

3.4. Additional PCI-based Indices

The distress data used to compute PCI can also be used to calculate additional indices that are helpful in understanding the condition of the pavement and developing PCIP recommendations. One additional index that was computed is the Foreign Object Damage (FOD) potential index.

The FOD index was developed by the US Air Force and is described in detail in the US Army Corp of Engineers Engineering Technical Letter (ETL) 04-09, Pavement Engineering Assessment (EA) Standards. Loose objects on an airfield pavement surface resulting from pavement distresses can be detrimental to aircraft engines, specifically engines that are low to the ground. The objects are ingested into the engines causing costly damage and presenting a safety hazard. Not all pavement distresses create a FOD potential. Therefore, an additional index was identified that uses the results of the PCI distress survey. As shown in Figure 3.1, the scale ranges from 0 to 100 with 0 being no FOD potential. Note that the FOD index uses a simplified three color scale.

Figure 3.1: FOD Potential Rating Scale.





3.5. PCI Survey Results

The airside pavements at M22 include 10 sections with 106 sample units. The sample number of sample units that were surveyed in the field is 32, which is 30 percent of the total samples. Data from the inspected sample units were input into the PAVER database and a resultant PCI for each section was computed.

Figure 3.2 presents the area-weighted PCI by use and the overall airside network.




Figure 3.3 shows the distribution of the M22 pavement network by condition. Approximately 7 percent of the network is in “Poor” or worse condition.




Table 3.2 is a listing of the section PCI.

Table 3.2: Section PCI.

Branch ID	Name	Section ID	Surface	Area, sf	PCI	PCI Category	FOD
A01	Apron 01	01	AC	91,746	89	Good	21
R0220	Runway 02-20	01	AC	189,600	81	Satisfactory	31
R0220	Runway 02-20	02	AC	185,175	73	Satisfactory	40
R0220	Runway 02-20	03	AC	37,725	75	Satisfactory	38
TA	Taxiway A	01	AC	5,043	74	Satisfactory	39
TA	Taxiway A	02	AC	4,723	85	Satisfactory	26
THANG01	Taxiway Hangar 01	01	AC	5,287	85	Satisfactory	26
THANG01	Taxiway Hangar 01	02	AC	14,522	54	Poor	50
THANG01	Taxiway Hangar 01	03	AC	25,480	41	Poor	57
TTRW02	TW Turnaround RW 02	01	AC	12,000	78	Satisfactory	34

Figure B2A and B2B in Appendix B are maps of the section PCI in 7- and 3-scale categories, respectively. Figure B2C is a map of the FOD rating. Appendix D contains a detailed report of the PCI values and distress type, quantity, and severity data for each sample unit that was surveyed in a section. Appendix E is a summary report of the extrapolated distress data at the section level.

Appendix F contains current section and branch PCI data and forecasted section PCI values. FOD values by section and branch are also presented. Figure B2D in Appendix B shows the locations of the photos that were taken during the survey. Photos are included in Appendix J.

3.6. PCC Pavements

As stated earlier, the project scope did not include a detailed pavement condition survey for any Portland Cement Concrete (PCC) aprons. For these pavements, a rating of “Good”, “Fair”, or “Poor” was assigned based on the overall pavement condition. There are no PCC aprons at M22.

This Page Intentionally Left Blank

4 Pavement Capital Improvement Program

4.1. Introduction

PCI data were collected and entered into the PAVER database. In addition, the database customization included the following components, which are described in detail in this chapter.

1. Performance Modeling
2. Maintenance & Repair (M&R) Triggers (Critical PCI)
3. M&R Policies
4. Unit Costs

Once the database was customized, it was used to run budget analysis scenarios and develop a 7-year PCIP.

4.2. Performance Modeling

To determine long-term M&R needs, a APMP must be able to predict future pavement condition. Future pavement condition is predicted using equation models that are generated from current and historical PCI data. Equation models are developed by grouping pavements based on similar performance characteristics such as region, construction history, surface type, traffic, priority and use. Mathematical techniques such as straight-line extrapolation and regression that include boundary and outlier filters are used to develop models that provide the best fit equation for the pavement condition data. PAVER's Prediction Modeling module was used to develop pavement performance models that are commonly referred to as 'Family Curves'.

Prediction models are used at the section level to compute future conditions based on the typical performance of the pavement sections that are included in each model. Future condition is computed by defining its position relative to the prediction model. The section prediction curve, or equation, is drawn through the current PCI-age point for each specific section. Since the shifted curve will run parallel to the computed prediction model, the predicted condition can be computed for any future age. Figure 4.1 is an illustration of this process.

Prediction models provide an effective way to compute future pavement performance based on past and current conditions, and pavement maintenance and rehabilitation practices. As new PCI inspection surveys are conducted, these models should be updated accordingly. In the case of the Alabama statewide airport pavement network, the best fit family curves were developed for each region by grouping pavements according to branch use (e.g. runway, taxiway) and surface type (e.g. AC, AAC, and APC). The family curves for ALDOT were developed based on branch use and are presented in Figure 4.2.



Figure 4.1: PCI Forecasting.





Figure 4.2: Family Curves.



4.3. Critical PCI Values

The Critical PCI value is defined as “*the PCI value at which the rate of PCI loss increases with time, or the cost of applying localized preventive maintenance increases significantly.*” This definition is incorporated into PAVER in defining and measuring the critical PCI values. These values, or M&R triggers, are assigned for each prediction model. As such, the critical PCI values are directly related to the branch use.

These critical PCI levels are selected based on several factors including a review of performance models; experience; other airport triggers; and acknowledge that time is required for funding approval and design. Note that preventive maintenance is recommended, and it should generally be performed above the critical PCI (trigger) values and Major M&R is generally performed below them. The critical PCI (CP) values were set at 70 for runways and taxiways, and 65 for other pavements.

4.4. M&R Policies and Unit Costs

M&R policies refer to the activities that are applied at different condition levels to maintain and repair a pavement section.

Maintenance activities are localized activities which are typically assigned in the first year of the M&R plan based on the observed distresses. Safety (stopgap) maintenance addresses distresses that would affect operational safety if left unrepaired and is applied to pavements below the critical PCI. Preventive maintenance activities are aimed at slowing the rate of deterioration through consistent maintenance of existing pavements and are generally applied to pavements above the critical PCI. Appendix G presents the policies for preventive and safety maintenance.

Repair activities are conducted for larger areas, typically at the section level and are assigned based on the critical PCI. Repair activities broadly consist of three categories: preservation, rehabilitation, and reconstruction. Pavement preservation involves activities like surface treatments that are used to extend pavement service life and to delay more expensive rehabilitation work. These are applied when the pavement is in relatively good condition and does not exhibit any structural distress. Rehabilitation activities are used to repair pavements below or around the critical PCI and typically include mill and overlay. Reconstruction is recommended when the pavement has deteriorated to a level where rehabilitation is no longer cost effective.

Table 4.1 lists the pavement activity types, the individual activities within each type, and their associated 2020 unit costs. A more detailed description of the M&R activities and the development of the M&R unit costs is presented in Appendix H.

In accordance with ALDOT’s focus on preservation, surface treatment is applied to all resurfaced and reconstructed runways, taxiways, and aprons three years after construction work is complete. Taxilanes and T-Hangar pavements are excluded from this requirement. This policy is applicable for projects in the PCIP between 2021 and 2024. For cost estimating, this surface treatment is assumed to have the same cost as the runway surface treatment.



Table 4.1: M&R Activities and Unit Costs.

Activity Type	PCI	Activity	Cost/sf
Maintenance	Note 1	Seal Cracks – AC (\$/lf)	\$3.95
		AC Full-Depth Patching	\$25.05
		AC Partial-Depth Patching	\$16.28
Preservation	75-90	Runway Surface Treatment	\$0.57
		Taxiway and Apron Surface Treatment	\$0.85
Rehabilitation	> CP	2" AC OL ²	\$3.78
	55 - CP	Mill 2" & 2" AC OL	\$4.15
	45 - 55	Mill 2" & 3" AC OL	\$5.18
Reconstruction	0 - 45	AC Reconstruction	\$9.10

¹ Preventive > CP; Safety (Stopgap) < CP

² For sections with structural distress and PCI > CP

4.5. Pavement CIP Development

The PAVER database, updated with condition data and customized with condition performance priorities, policies, and costs; was used to evaluate the effect of multiple funding levels on the overall future pavement condition. This output was further used to develop the PCIP. Figure 4.3 illustrates the process that PAVER uses in the funding analysis.

The following M&R funding levels were used for the M22 pavement network to help establish the 7-Year PCIP. Figure 4.4 presents the network area-weighted average PCI for each of the following funding scenarios at the end of the analysis period:

- Unlimited Funding: Unlimited funding is available for all pavement needs. The PCI increases to 92 by 2027.
- Maintain PCI: Maintain existing PCI of 77.
- Constrained Funding: This scenario constrains the funding to \$1 million each year (total of \$7 million). The PCI increases to 92 in 2027.
- Do Nothing: Performing no M&R would reduce the network PCI from 77 to 58 by 2027.



Figure 4.3: Budget Analysis Process.




Figure 4.4: M&R Funding Levels.




Table 4.2 summarizes the annual funding required for the above analyses. For the unlimited analysis, all pavement needs are funded in the year they are required. Therefore, the unfunded costs are zero. The total funded amount over the 7-year period is approximately \$2.4 million. For the annual funding level of \$1 million per year, funding is prioritized based on the prioritization matrix. When the needs exceed the funding for any year, the remaining sections are transferred to the succeeding year and the amount



for these activities are represented as “unfunded”. There are no “unfunded” repairs in 2027 for this funding level.

Table 4.2: Summary of M&R Funding Level Analyses.

Year	Unlimited	Maintain PCI	Constrained \$1M/year	Do Nothing
2021	\$426,000	\$196,000	\$426,000	\$0
2022	\$821,000	\$35,000	\$821,000	\$0
2023	\$174,000	\$181,000	\$174,000	\$0
2024	\$862,000	\$260,000	\$862,000	\$0
2025	\$4,000	\$8,000	\$4,000	\$0
2026	\$5,000	\$10,000	\$5,000	\$0
2027	\$65,000	\$72,000	\$65,000	\$0
Total	\$2,356,000	\$763,000	\$2,356,000	\$0
2027 Backlog	-	\$2,028,000	-	\$2,833,000

Map B3A in Appendix B presents the 2027 forecasted PCI by section when the M&R activities recommended in the CIP are not conducted.

4.6. Pavement Capital Improvement Program

The unlimited funding analysis contains rehabilitation activities for sections from the same branch spread out over the seven-year period, which is not always operationally feasible to construct. The analysis output was treated as a starting point in developing the CIP. Sections were often integrated together to account for construction feasibility and other factors, resulting in larger projects which were more realistic. In addition, each project could contain sections whose condition did not trigger rehabilitation but were included to provide a logical plan which would avoid creating “islands” of newer pavement within a particular feature. For example, if the PAVER analysis showed rehabilitation was required for eight out of 10 sections on a runway, the entire runway would be recommended for rehabilitation to provide a continuous new pavement surface.

Table 4.3 shows the projects and the associated costs for the recommended 7-year PCIP. Table 4.4 is a more detailed view of the PCIP. This table lists the individual pavement section, section level M&R work, section repair cost, surface area and the PCI before the M&R is applied. The costs that are presented represent an annual escalation rate of 3% for the unit costs. The total 7-year PCIP cost is approximately \$2.6 million. Map B3B shows the recommended repair types, while Map B3C presents the recommended projects and activities in the PCIP. Appendix I1 presents a summary of the recommended activities and cost by year for each section at M22.



Table 4.3: Summary of 7-Year PCIP by Project.

Project Year	CIP Project	Total Project Cost	Total Project Area, sf	AWPCI Before	AWPCI After
2021	M22_21-01_Apron Preservation	\$89,197	101,756	86	93
	M22_21-02_Taxiway Hangar Reconstruction	\$316,261	40,002	41	100
2022	M22_22-01_Runway 02-20 Rehabilitation	\$1,893,014	429,543	71	100
2025	M22_25-01_Runway 02-20 Surface Treatment	\$281,576	429,543	96	99
Total		\$2,580,049			

Table 4.4: Summary of 7-Year PCIP by Project and Section.

Branch	Section	Area, sf	PCI Before Rehab	Activity	Activity Type	Cost
M22_21-01_Apron Preservation						\$89,197
A01	01	91,746	86	Taxiway & Apron Surface Treatment	Preservation	\$80,423
TA	02	4,723	82	Taxiway & Apron Surface Treatment	Preservation	\$4,140
THANG01	01	5,287	82	Taxiway & Apron Surface Treatment	Preservation	\$4,634
M22_21-02_Taxiway Hangar Reconstruction						\$316,261
THANG01	02	14,522	49	Mill 2" & 3" AC OL	Rehabilitation	\$77,483
THANG01	03	25,480	37	AC Reconstruction	Reconstruction	\$238,779
M22_22-01_Runway 02-20 Rehabilitation						\$1,893,014
R0220	01	189,600	-	Mill 2" & 2" AC OL	Rehabilitation	\$835,575
R0220	02	185,175	-	Mill 2" & 2" AC OL	Rehabilitation	\$816,074
R0220	03	37,725	-	Mill 2" & 2" AC OL	Rehabilitation	\$166,256
TA	01	5,043	-	Mill 2" & 2" AC OL	Rehabilitation	\$22,225
TTRW02	01	12,000	-	Mill 2" & 2" AC OL	Rehabilitation	\$52,885
M22_25-01_Runway 02-20 Surface Treatment						\$281,576
R0220	01	189,600	-	Surface Treatment	Preservation	\$124,287
R0220	02	185,175	-	Surface Treatment	Preservation	\$121,387
R0220	03	37,725	-	Surface Treatment	Preservation	\$24,730
TA	01	5,043	-	Surface Treatment	Preservation	\$3,306
TTRW02	01	12,000	-	Surface Treatment	Preservation	\$7,866
Total						\$2,580,049

The FAA, under the Airport Improvement Program (AIP) provides approximately 90 percent of eligible costs for planning and development of public-use airports included in the NPIAS as grants. The remaining 10 percent of costs are shared between ALDOT and the airport sponsor. The following is the distribution of the 7-yr PCIP cost of \$2.6 million for M22:



- FAA (90%): \$2.4 million
- ALDOT (5%): \$0.1 million
- Airport Sponsor (5%): \$0.1 million

The recommendations within the PCIP are based on a network-level study and should be used for planning purposes only. A detailed project-level assessment should be conducted for each project to determine the appropriate repair activities and develop more accurate cost estimates.

Table 4.5 summarizes the maintenance activities that are recommended for Year 1 (2021). The estimated cost is approximately \$6,117. A complete listing of the maintenance activities by section is presented in Appendix I2. This may be used as a basis for establishing an annual maintenance budget for the M22 pavements.

Table 4.5: Summary of Year-1 Maintenance Plan.

Policy	Work Description	Work Quantity	Work Unit	Work Cost
Preventive	Crack Sealing - AC	632	Ft	\$2,498
Safety	Patching - AC Full-Depth	145	SqFt	\$3,620
			Total	\$6,117

APPENDIX A
INVENTORY



Appendix A
Pavement Inventory Report
 Bill Pugh Field (M22)

Branch ID	Name	Branch Use	Section ID	Rank ¹	Length (ft)	Width (ft)	Area (sf)	LCD ²	Surface ³
A01	Apron 01 Russellville	APRON	01	S	325	260	91,746	6/3/2013	AC
R0220	Runway 02-20 Russellville	RUNWAY	01	P	2,528	75	189,600	4/1/2004	AC
R0220	Runway 02-20 Russellville	RUNWAY	02	P	2,469	75	185,175	4/1/2004	AC
R0220	Runway 02-20 Russellville	RUNWAY	03	P	503	75	37,725	4/1/2004	AC
TA	Taxiway A Russellville	TAXIWAY	01	S	118	35	5,043	4/1/2004	AC
TA	Taxiway A Russellville	TAXIWAY	02	S	104	35	4,723	4/1/2004	AC
THANG01	Taxiway Hangar 01 Russellville	TAXIWAY	01	T	105	40	5,287	6/3/2013	AC
THANG01	Taxiway Hangar 01 Russellville	TAXIWAY	02	T	407	35	14,522	1/1/1969	AC
THANG01	Taxiway Hangar 01 Russellville	TAXIWAY	03	T	465	68	25,480	1/1/1969	AC
TTRW02	TW Turnaround RW 02 Russellville	TAXIWAY	01	P	150	80	12,000	4/1/2004	AC

¹ P = Primary pavement, S = Secondary pavement, T = Tertiary pavement

² LCD = Last construction date. The date of the last major pavement rehabilitation (e.g. AC overlay)

³ AC = Asphalt Cement Concrete, AAC = Asphalt Overlay AC, PCC = Portland cement Concrete, APC = Asphalt Overlay PCC

APPENDIX B

PMP Maps

B1: Inventory Maps

B1A: Branch Identification

B1B: Section Identification

B1C: Sample Unit Layout

B1D: Pavement Type

B1E: Branch Use

B1F: Pavement Age

B2: Surface Condition Maps

B2A: 7-Color PCI

B2B: 3-Color PCI

B2C: FOD Rating

B2D: Survey Photo Locations

B3: Pavement Capital Improvement Plan (PCIP) Maps

B3A: 2027 Forecasted PCI without PCIP

B3B: M&R Needs

B3C: PCIP Recommendations

Legend

- Section Boundary
- Branch Identification**
- Apron 01 Russellville
- Runway 02-20 Russellville
- TW Turnaround RW 02 Russellville
- Taxiway A Russellville
- Taxiway Hangar 01 Russellville




Figure B1A

**Alabama Statewide
Pavement Management Program Update
Bill Pugh Field (M22)
Russellville, AL**

Branch Identification		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 1
REVISED JMA	SCALE 1 in = 400 ft	FINAL

JVIATION
ENGINEERING & PLANNING

All About
Pavements, Inc. (API)
www.allaboutpavements.com
Telephone: 217-586-2765 FAX: 217-586-1967

Legend

□ Section Boundary




Figure B1B


**Alabama Statewide
Pavement Management Program Update
Bill Pugh Field (M22)
Russellville, AL**

Section Identification		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 2
REVISED JMA	SCALE 1 in = 400 ft	FINAL

JVIATION
 ENGINEERING & PLANNING

All About
Pavements, Inc. (API)
www.allaboutpavements.com
Telephone: 217-586-2765 FAX: 217-586-1967

Legend

Section Boundary

Sample Unit Layout

SU Boundary

Inspected




Figure B1C

Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

Sample Unit Layout

ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 3
REVISED JMA	SCALE 1 in = 400 ft	FINAL



Legend

□ Section Boundary

Pavement Type

■ Asphalt Concrete (AC)




Figure B1D


**Alabama Statewide
Pavement Management Program Update
Bill Pugh Field (M22)
Russellville, AL**

Pavement Type		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 4
REVISED JMA	SCALE 1 in = 400 ft	FINAL



Legend

Section Boundary

Branch Use

- APRON
- RUNWAY
- TAXIWAY




Figure B1E

Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

Branch Use		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 5
REVISED JMA	SCALE 1 in = 400 ft	FINAL




Legend

Section Boundary

Pavement Age (Yrs)

- 0 - 10
- 11 - 15
- 16 - 25
- 26 - 50
- >50



Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

Figure B1F

Pavement Age		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 6
REVISED JMA	SCALE 1 in = 400 ft	FINAL




All About
 Pavements, Inc. (API)
 www.allaboutpavements.com
 Telephone: 217-586-2765 FAX: 217-586-1967

Legend

Section Boundary

PCI (7 Color)

- Good (86-100)
- Satisfactory (71-85)
- Fair (56-70)
- Poor (41-55)
- Very Poor (26-40)
- Serious (11-25)
- Failed (0-10)



**Alabama Statewide
Pavement Management Program Update
Bill Pugh Field (M22)
Russellville, AL**

Figure B2A

7-Color PCI


			ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 7
			REVISED JMA	SCALE 1 in = 400 ft	FINAL

Legend

Section Boundary

PCI (3 Color)

- Good (71-100)
- Fair (56-70)
- Poor (0-55)



Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

Figure B2B

3-Color PCI		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 8
REVISED JMA	SCALE 1 in = 400 ft	FINAL

JVIATION
 ENGINEERING & PLANNING

All About
 Pavements, Inc. (API)
 www.allaboutpavements.com
 Telephone: 217-586-2765 FAX: 217-586-1967

Legend

Section Boundary

FOD Rating

- Good (0 - 45)
- Fair (46 - 60)
- Poor (61 - 100)




Figure B2C

Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

FOD Rating		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 9
REVISED JMA	SCALE 1 in = 400 ft	FINAL



Legend

- Section Boundary
- Survey Photo Locations






Figure B2D


**Alabama Statewide
Pavement Management Program Update
Bill Pugh Field (M22)
Russellville, AL**

Survey Photo Locations

 JV AVIATION ENGINEERING & PLANNING	 All About Pavements, Inc. (API) <small>www.allaboutpavements.com Telephone: 217-586-2765 FAX: 217-586-1967</small>	ENGINEER	DATE	MAP NUMBER
		KP/MR	May 2021	Page 10
REVISED	SCALE	FINAL		
JMA	1 in = 400 ft			

Legend

Section Boundary

Forecasted PCI without PCIP

- Good (86-100)
- Satisfactory (71-85)
- Fair (56-70)
- Poor (41-55)
- Very Poor (26-40)
- Serious (11-25)
- Failed (0-10)




Figure B3A

Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

2027 Forecasted PCI without PCIP

		ENGINEER	DATE	MAP NUMBER
		KP/MR	May 2021	Page 11
		REVISOR	SCALE	
		JMA	1 in = 400 ft	FINAL

All sections recommended for Rehabilitation or Reconstruction between 2021 and 2024 also receive Surface Treatment in the 3rd year of paving.

Legend

Section Boundary

Repair Type

- Preservation
- Reconstruction
- Rehabilitation




Figure B3B

Alabama Statewide
 Pavement Management Program Update
 Bill Pugh Field (M22)
 Russellville, AL

Repair Type		
ENGINEER	DATE	MAP NUMBER
KP/MR	May 2021	Page 12
REVISED	SCALE	FINAL
JMA	1 in = 400 ft	



All sections recommended for Mill & AC Overlay or AC Reconstruction between 2021 and 2024 also receive Surface Treatment in the 3rd year of paving

Legend

Project Name

- M22_21-01_Apron Preservation
- M22_21-02_Taxiway Hangar Reconstruction
- M22_22-01_Runway 02-20 Rehabilitation

M&R Activity

- AC Reconstruction
- Mill 2" & 2" AC OL
- Mill 2" & 2" AC OLP
- Taxiway & Apron Surface Treatment




Figure B3C

**Alabama Statewide
Pavement Management Program Update
Bill Pugh Field (M22)
Russellville, AL**

PCIP Recommendations		
ENGINEER KP/MR	DATE May 2021	MAP NUMBER Page 13
REVISED JMA	SCALE 1 in = 400 ft	FINAL

www.allaboutpavements.com
 Telephone: 217-586-2765 FAX: 217-586-1967

APPENDIX C

OVERVIEW OF PAVEMENT DISTRESSES



% 5 [Ucf 7fUWb] 157L

◆

◆

◆


◆

◆

◆



& 6YH 157L



3" 6cW7fUWb| 157L

◆

◆

◆

◆

◆

◆



Corrugation [U]b[5]L

Description


Corrugation is a series of closely spaced ridges and valleys (ripples) occurring at fairly regular intervals, usually less than 5 feet (1.5 meters) along the pavement. The ridges are perpendicular to the traffic direction. Traffic action combined with an unstable pavement surface or base usually causes this type of distress.

Severity Levels

@

A

<



)" 8YfYgcbi57L

◆

◆

◆

◆

◆

◆



*" >Yi6Uj157L

8Yj1db

GjYj1@jYg



+!">chFYZWcb7fUWbl f57L

8yAdcb

GjYfhicjYg

@

A

^



, " @b [] i X b U b X H U b g j Y g Y 7 f U W b [] B 5 7 L

◆

◆

◆

◆

◆

◆



9" CIP CURB



98' DFWM



- ◆
- ◆
- ◆



- ◆
- ◆
- ◆



%D'lg X5[[fY]te (AC)

8Y[d]b

GjY]h@jYg



%&FU Yb| B7L

8Vb|db


8YgYAl 'GjY|n@jYg'

@


A

<

BdY h|g|UbK XdYgg|bWnYSS+ 'g fjYn



Gi ffr#7cUHfCjY8YgYAl GYfJh@Yg



@

A


<

Dfci g: fMcb7ci fgYGjYfhi@jYg

@

A

<



%" Film 157L

-
- ◆
 - ◆
 - ◆

-
- ◆
 - ◆
 - ◆



%"G|dd|Y7fUW| 157L

from the direction of traffic. They are produced when braking or turning wheels cause the

_____ No degrees of severity are defined. It is sufficient to indicate that a slippage

- ◆
- ◆



%"GkY|b| 157L

8Yg|d|b

GjY|n|@jYg

@

A

<



%"KXhYb 157L

8YgJdb

GjYh@jYg

@

A

<



%!"6dk!l d!d77L


8yq!d!bb

GjYf!h@jYg

@

A

<



-
- ◆ filled, it has a mean width less than approximately 1 inch (3 millimeters); a filled crack can be of any width, but the filler material
 - ◆ One of the following conditions exists: (1) filled or non filled c filled crack has a mean width between 1/8 inch (3 millimeters) and 1 inch (25 millimeters); (3) a filled crack is not spalled or only lightly spalled, but the filler is in unsatisfactory
 - ◆ One of the following conditions exists: (1) filled or non filled crack is severely spalled, causing definite FOD potential; (2) a non filled crack ha

-
- ◆
 - ◆
 - ◆



%" 7fUWg"@cb|liXpUZHFUbg YgYUbx8|U|cbU'fD77L

◆

◆

◆

◆

◆

◆



88'8i fUv]ln7fUWgfD77L

8YgAd]cb


parallel to a joint or linear crack. A dark coloring can usually be seen around the fine

GjY]ln@jYg

@

A

<



8% > chGU'Sa U YD77L

- ◆
- ◆
- ◆


- ◆
- ◆
- ◆



8& GaU DUWID77L

has been removed and replaced by a filler





&" @U[YDUWID77L

Patching is the same as defined





&" Dddi lgiD77L

No degrees of severity are defined for popouts.



&"Diadj iD77L

8YAdjb

GjYfm@jYg



&" GW]b] iD77L

of approximately 1/4 to 1/2 in

-
- ◆
 - ◆
 - ◆



Figure 10-7

Severity levels are defined by the difference in elevation across the fault and the

	Figure 10-7	Severity
@		
A		
<		



&" G UHFXGUVH77L

severity level of this distress type, as defined below,

-
- ◆ Slab is broken into four or five pieces with the vast majority of the cracks
 - ◆ (1) Slab is broken into four or five pieces with over 15 percent of the
 - ◆ four or five pieces with some or all of the cracks of high severity; (2) slab is

-
- ◆
 - ◆
 - ◆



&" Gfb_ UY7fCWID77L

No degrees of severity are defined. It is sufficient to indicate that shrinkage cracks exist.



'S' > qhG UgfD77L

◆


◆

◆

◆

◆

◆



'% 7cfbYfGUgID77L

◆

◆

◆

◆

◆

◆




' & 5G 1D77L

GjYfh@jYg

@

A

<



APPENDIX D

DETAILED PAVEMENT CONDITION DATA



5@8CHE7ca VbYSS9%89%

; YMFUPASUY

%89%89%

DJY%Z%8

BYkcf.	A&&	BuY	G'D[\:]YX
GUBW	59%	BuY	5dcb9%Figgj]Y I g 5DFCB 5fU -%(* Gc h
GWjcb	%	z %	: fca. Hl[kU5 H. 9NYcZDJyYh @Gj7cbg! *#%89%
GfZUW	57	: Ua]m	5@8CHE5dcbg NcbY 7UWcfm FUb. G
5fU	-%(* Gc h	@Y[h.	' & : h KPh. &S: h
GUg	GU@Y[h.	: h	GVKPh. : h >ch@Y[h. : h
Gcd Xf.	GfYHhdY		; fUX \$ @bYg \$
Gwjcb7caaYlg			

Kcf_8UY	%89%*	Kcf_HdY	Bk7cbg! Vcb! h]U 7cX BI !B =gAUcfA/ F. HfY
Kcf_8UY	(#89%	Kcf_HdY	7UWGUH!57 7cX 7G57 =gAUcfA/ F. :Ug
Kcf_8UY	(#89%	Kcf_HdY	GfZUWU!7cUHf 7cX GG7H =gAUcfA/ F. :Ug
Kcf_8UY	*#89%	Kcf_HdY	GWg!5[fUY 7cX G65; =gAUcfA/ F. :Ug
Kcf_8UY	*#89%	Kcf_HdY	Gg7cbg! G]ha]bg 7cX 65!6= =gAUcfA/ F. :Ug
Kcf_8UY	*#89%	Kcf_HdY	7cadYfFWbg! Vcb!57 7cX 7F!57 =gAUcfA/ F. HfY

@Gj7cbg!8UY	%4%89%	HUGadYg	% GfjYk)
7cbY]cbg	D7= , -		
-hgNjcb7caaYlg			

GadYBiaVf.	%	HdY	F 5fU)89%89%Gc h D7= ,*
GadY7caaYlg			
(, @/ H7F	@	, \$89 : h	
)& F5J9@B;	@	*89% Gc h	
)+ K95H9F-B;	@	(- (\$89 Gc h	

GadYBiaVf.	\$	HdY	F 5fU)89%89%Gc h D7= -(
GadY7caaYlg			
)+ K95H9F-B;	@)89%89% Gc h	

GadYBiaVf.	%\$	HdY	F 5fU)%89%89%Gc h D7= ,+
GadY7caaYlg			
(, @/ H7F	@	%89% : h	
)+ K95H9F-B;	@)%89%89% Gc h	

GadYBiaVf.	%&	HdY	F 5fU)89%89%Gc h D7= ,,
GadY7caaYlg			
(, @/ H7F	@),'89% : h	
)+ K95H9F-B;	@)89%89% Gc h	

GadYBiaVf.	%	HdY	F 5fU), +\$89%89%Gc h D7= -%
GadY7caaYlg			
(, @/ H7F	@	- '89% : h	
)+ K95H9F-B;	@), +\$89%89% Gc h	

BVkc_f.	A&&		BuY	G`D[\:]YX				
GfUW	FSSS		BuY	FibkUisSSFi g`j]`Y	I g`	FIEK5M	5fU	(%SSGeh
GMch \$		cZ ' : fca.		FibkUisSS9bX		H. 9(YcZDjYaYh		@g7cbg' (#SSX
GfUW 57		: Ua]m 5@SCHFKg		NbY		7Uf[cfm		Fub. D
5fU		'z& Geh @Y[h.)\$: h	K]Ph.			+) : h
GUg		GU@Y[h.		: h	GUVK]Ph.			: h
Gci Xf.		GfYWHdY			; fUX \$			@Uyg \$
GMcb7caaYlg								
Kcf_SUY (#SSX		Kcf_HdY Bk7cbg' Ucb' h]U				7cX BI!-B		=AUcfA/ F. HiY
Kcf_SUY *#SS%)		Kcf_HdY FibkUisSSFi g`j]`Y				7cX FK!GH		=AUcfA/ F. : Ugy
@g7cbg'SUY %4#SS%		HBUcladyg +				GfjYbX (
7cbg' D7= +)								
-bg'GMcb7caaYlg								
QadYBi aVf. \$%		HdY F		5fU)*&'SSGeh		D7= +)
QadY7caaYlg								
(, @/ H7F		@				&)'SS : h		
(, @/ H7F		A				SS : h		
)+ K95H 9F-B;		A				&SSSS Geh		
QadYBi aVf. \$		HdY F		5fU)*&'SSGeh		D7= +'
QadY7caaYlg								
(, @/ H7F		@				', SSS : h		
(, @/ H7F		A				+'SS : h		
)+ K95H 9F-B;		@				&SSSS Geh		
QadYBi aVf. \$)		HdY F		5fU)*&'SSGeh		D7= +*
QadY7caaYlg								
(, @/ H7F		@				(%SS : h		
)+ K95H 9F-B;		@				&SSSS Geh		
QadYBi aVf. \$-		HdY F		5fU)*&'SSGeh		D7= +,
QadY7caaYlg								
(, @/ H7F		@				') SSS : h		
)+ K95H 9F-B;		@				&SSSS Geh		

BYkcf. A&& BLaY G'D[\:\]X

GfUW FS888 BLaY FilkUn888Figgj]Y I g FIEK5M 5fU (%888Geh

GWfch && z' :fca. GWfcb8% H. FilkUn888X @gh7chj' (#888

GfUW 57 :Ua]m 5@CHFKg NdbY 7Uf]cfm Fub. D

5fU %)2%) Geh @Y[h. &* :h K]h. +) :h

GUg GUV@Y[h. :h GUVK]h. :h >ch@Y[h. :h

Gci Xf. GfYWHdY ;fUX \$ @byg \$

GWfcb7caaYhg

Kcf_8UY %888*- Kcf_HdY Bk7chj' Ucb' h]U 7cX BI!-B =AUcfA/ F. HiY

Kcf_8UY (#888(Kcf_HdY 7cadYfYWhj' Ucb' 57 7cX 7F57 =AUcfA/ F. HiY

Kcf_8UY *#888% Kcf_HdY FilkUnGfZWHfLaYh 7cX FK!GH =AUcfA/ F. :Ug

@gh7chj'8UY %888% HRUcladyg ' GfjYhX *

7ch]chj' D7= +'

=gh7chj'7caaYhg

QladYBi aVf. \$ HdY F 5fU)*&'888Geh D7= *-

QladY7caaYhg

(, @/ H7F @ '(888 :h

(, @/ H7F A '888 :h

)& F5J9@B; A 88888 Geh

)+ K95H9F-B; @ 88888 Geh

QladYBi aVf. \$(HdY F 5fU)*&'888Geh D7= +)

QladY7caaYhg

(, @/ H7F @ '8888 :h

(, @/ H7F A %'888 :h

)+ K95H9F-B; @ &8888 Geh

QladYBi aVf. % HdY F 5fU)*&'888Geh D7= +(

QladY7caaYhg

(, @/ H7F @ (8888 :h

)\$ D5H7<-B; @ 888 Geh

)+ K95H9F-B; @ &8888 Geh

QladYBi aVf. % HdY F 5fU)*&'888Geh D7= +(

QladY7caaYhg

(, @/ H7F @ (*)'888 :h

)+ K95H9F-B; @ &8888 Geh

QladYBi aVf. & HdY F 5fU)*&'888Geh D7= +&

QladY7caaYhg

(, @/ H7F @ (*)'888 :h

(, @/ H7F A 8888 :h

)+ K95H9F-B; @ &8888 Geh

QladYBi aVf. '% HdY F 5fU)*&'888Geh D7= +*

QladY7caaYhg

(, @/ H7F @ (%'888 :h

)+ K95H9F-B; @ &8888 Geh

BYkcf.	A&&	BláY	G`D[\:]YX					
GfUW	FSSS	BláY	FibkUnSSFi	g`j]Y	I g`	FIEK5M	5fU	(%SSGe h
GMch	%	z ' : fca.	FibkUnSS9bX			H. GMcbS&	@g]7cbg] (#SSX	
GfUW	57	: Ua]m 5@SCHFKg	NbY			7U]cfm	Fub. D	
5fU	%žSSGe h	@Y[h.	S& : h	K]h.		+) : h		
GUg		GU@Y[h.	: h	GUVK]h.		: h	>ch@Y[h.	: h
Gci XE.		GfYWHdY		; fUX \$			@bYg \$	
GMcb7caaYlg								
Kcf_8UY (#SSX		Kcf_HdY Bk7cbg]Vcb]h]U				7cX BI!B		=AUcfA/ F. HfY
Kcf_8UY *#SS%)		Kcf_HdY FibkUnGfUWfUaYh				7cX FK!GH		=AUcfA/ F. :UgY
@g]hgl'8UY %4#SS%		HRUCladYg '(GfjYhX)		
7cb]cbg D7= ,%								
-bg]Vcb7caaYlg								
QladYBi aVf. \$		HdY F	5fU)*&'SSGe h	D7= ,'	
QladY7caaYlg								
(, @/ H7F		@				&'SS : h		
)+ K95H 9F-B;		@				&SSSS Ge h		
QladYBi aVf. %\$		HdY F	5fU)*&'SSGe h	D7= ,%	
QladY7caaYlg								
(, @/ H7F		@				'SSSS : h		
)+ K95H 9F-B;		@				%SSSS Ge h		
QladYBi aVf. %		HdY F	5fU)*&'SSGe h	D7= +,	
QladY7caaYlg								
(, @/ H7F		@				'+)SS : h		
)+ K95H 9F-B;		@				SSSSSS Ge h		
QladYBi aVf. &		HdY F	5fU)*&'SSGe h	D7= ,%	
QladY7caaYlg								
(, @/ H7F		@				%SSS : h		
(, @/ H7F		A				SSSS : h		
)+ K95H 9F-B;		@				&SSSS Ge h		
QladYBi aVf. '%		HdY F	5fU)*&'SSGe h	D7= , \$	
QladY7caaYlg								
(, @/ H7F		@				'SSSS : h		
)+ K95H 9F-B;		@				SSSSSS Ge h		

BVkc.	A&&		BlaY	G`D[\:]YX			
GfUW	H5		BlaY	HI]kUis5 Figgj]Y	Ig	H5L-K5M	5fU
GMch	%		cZ &	: fca.	FibkUis55	H. GMcb55	@g]7cbg] (#555)
GfZUW	57		: Ua]m	5@SCH57HI]kUig	NbY	7U]cfm	FUb. G
5fU)X' Gc h	@Y[h.	%: h	K]h.	'): h
GUg			GU@Y[h.		: h	GUVK]h.	: h
Gci Xf.			GfYWHdY		; fUX \$		>ch@Y[h. : h
GMcb7caa Ylg							@bg \$
Kcf_8UY (#555)			Kcf_HdY	Bk7cbg]Vcb! :h]U		7cX BI!B	=AUcfA/ F. HfY
Kcf_8UY *#555%			Kcf_HdY	FibkUig fZWHFla Yh		7cX FK!GH	=AUcfA/ F. :Ug
@g]hgl'8UY %4#55%			HRUcladyg	%		GfjYX	%
7cb]cbg D7= +(
-bg]cb7caa Ylg							
QldYBaVf. \$%			HdY	F	5fU)5555Gc h	D7= +(
QldY7caa Ylg							
(, @/ H7F			@		'')'55 : h		
(, @/ H7F			A		%55 : h		
)+ K95H 9F-B;			@		%5555 Gc h		

BVkf.	A&&		BuY	G`D[\:]YX			
GfUW	H5		BuY	HI]kUis Figgj]Y	Ig	H5L-K5M	5fU
GMch	S&	cZ &	: fca.	GMkb%		H. 5drb%	@g]7cb] (#4SSX
GfUW	57	: Ua]m	5@SCH57HI]kUg	NbY		7U]cfm	Fub. G
5fU		(z& G&h	@Y]h.	%(:h	K]h.	'):h	
GUg		GU@Y]h.	:h	GUVK]h.	:h	>ch@Y]h.	:h
Gci XE.		GfY]HdY		; fUX \$		@Ug \$	
GMcb7caaYlg							
Kcf_SUY (#4SSX		Kcf_HdY	Bk7cb]Vcb!h]U		7cX BI!B	=AUcfA/ F. HfY	
@g]hgl'SUY %4#SS%		HRUladYg	%	GfjYhX	%		
7cb]h]g D7= ,)							
hg]Vcb7caaYlg							
QladYBiaVf. S%		HdY	F	5fU	(+&'SSG&h	D7= ,)	
QladY7caaYlg							
(, @/ H7F		@	SSS :h				
(, @/ H7F		A	SSS :h				
)+ K95H9FB		@	' SSS G&h				

BYkcf.	A&&	BuY	G'D[\:]YX				
GfUW	H 5B, %	BuY	HI]kUia U[uf\$%figgY]Y I g	H5L-K5M	5fU	() &- Gc h	
GMch	\$	cZ ' : fca.	GMcb&&	Hc <U[ufg		@gh7cbg' %%%*-	
GfUW	57	: Ua]m 5@SCH57HI]UBg	NbY	7UH[cfm		FUb. H	
5fU	\$z, \$Gc h	@Y[h.	(*) : h	K]Ph.	*, : h		
GUg		GU@Y[h.	: h	GUVK]Ph.	: h	>ch@Y[h.	: h
Gci Xf.		GfYWHuY		; fUX \$		@bg \$	
GMcb7caaYlg							
Kcf_8UY %%%*-		Kcf_HuY Bk7cbg]Ucb! :h]U		7cX BI!-B		=AUcfA/ F. HfY	
Kcf_8UY (#\$\$\$		Kcf_HuY 7UWGUH]!57		7cX 7G57		=AUcfA/ F. :UgY	
Kcf_8UY (#\$\$\$		Kcf_HuY GfZVWGU!7cUHF		7cX GG7H		=AUcfA/ F. :UgY	
@gh7cbg'8UY %%%*%#		HRUcladyg)		GfjYhX (
7cb]cbg D7= (%)							
hg]Ucb7caaYlg							
QadYBiaVf. %		HuY F	5fU	*' \$'\$\$Gc h		D7= '%	
QadY7caaYlg							
(% 5@@; 5HCF'7F		A		&)'\$\$ Gc h			
(% 5@@; 5HCF'7F		<) '\$\$ Gc h			
(, @/ H7F		@		' \$\$\$: h			
(, @/ H7F		A		' \$\$\$: h			
)\$ D5H<-B;		@		\$ '\$\$ Gc h			
) + K95H 9F-B;		@		' %\$\$ Gc h			
QadYBiaVf. \$\$		HuY F	5fU)&'\$\$Gc h		D7= '(
QadY7caaYlg							
(% 5@@; 5HCF'7F		A		\$ '\$\$ Gc h			
(, @/ H7F		@		\$)'\$: h			
)\$ D5H<-B;		@		% '\$\$ Gc h			
)\$ D5H<-B;		<		&'\$\$ Gc h			
) + K95H 9F-B;		@		& '\$\$ Gc h			
QadYBiaVf. \$		HuY F	5fU)' \$\$\$Gc h		D7= (*	
QadY7caaYlg							
(% 5@@; 5HCF'7F		A		% '\$\$ Gc h			
(, @/ H7F		@		' \$'\$\$: h			
(, @/ H7F		A		+'\$\$: h			
) + K95H 9F-B;		@		\$\$\$ '\$\$ Gc h			
QadYBiaVf. \$		HuY F	5fU)' '\$\$Gc h		D7=)+	
QadY7caaYlg							
(% 5@@; 5HCF'7F		A		% '\$\$ Gc h			
(, @/ H7F		@		' '\$\$: h			
) + K95H 9F-B;		@) '\$\$ Gc h			

GVkcf.	A&&	BuY	G`D[\:]YX
GfUW	H5B; %	BuY	HI]kUia U[uf\$%figgY]Y I g' H5L-K5M 5fU ()&- Gz h
GVkch	\$&	cZ ' : fca.	GVkcb\$& H. GVkcb\$ @gh7cbg' %&&*-
GfZUW	57	: Ua]m 5@SCH57HI]Ubg	NbY 7UH[cfm Fub. H
5fU	%(a&&Gz h	@Y[h. (\$: h K]Ph. '): h	
GUg	GV@Y[h.	: h GUVK]Ph. : h	>ch@Y[h. : h
Gci Xf.	GfYWHuY	; fUX \$	@bg \$
GVkcb7caaYlg			
Kcf_8UY %&&*-	Kcf_HuY Bk7cbg' Vcb' :h]U		7cX BI !-B =gAUcfA/ F. HiY
Kcf_8UY (#&&&X	Kcf_HuY 7UWGUH] !57		7cX 7G57 =gAUcfA/ F. :UgY
Kcf_8UY (#&&&X	Kcf_HuY GfZUWGU!7cUHF		7cX GG7H =gAUcfA/ F. :UgY

@gh7cbg'8UY %&&#&&% **HRUcladyg ' GfjYnX ' 7cb]cbg D7=)(=gAUcfA/ F. :UgY**

QladYBiaVf. %	HuY	F	5fU)&\$&&Gz h	D7=)%
QladY7caaYlg					
(% 5@; 5HCF'7F	A		' \$\$\$ Gz h		
(, @/ H7F	@		(&&&& : h		
)\$ D5H<-B;	@		%)'\$\$ Gz h		
)\$ D5H<-B;	A) \$\$\$ Gz h		
)' FI HEB;	@		\$\$&& Gz h		
)+ K95H 9F-B;	@)&&&& Gz h		

QladYBiaVf. \$&	HuY	F	5fU)' &&&&Gz h	D7= ()
QladY7caaYlg					
(% 5@; 5HCF'7F	A		+) '\$\$ Gz h		
(, @/ H7F	@		%&&&& : h		
(, @/ H7F	A		*&&&& : h		
)\$ D5H<-B;	@		-*&&&& Gz h		
)' FI HEB;	@		*&&&& Gz h		
)+ K95H 9F-B;	@		%&&&&&& Gz h		

QladYBiaVf. \$	HuY	F	5fU	'-' &&&&Gz h	D7= +&
QladY7caaYlg					
(, @/ H7F	@		' &&&& : h		
(, @/ H7F	A		%&&&& : h		
)+ K95H 9F-B;	@)&&&& Gz h		

BYkcf. A&&	BuY	G`D[\:]YX					
GfUW H 5B \$%	BuY	HI]kUa U[uf\$FigY]Y I g	H5L-K5M	5fU		() &- G h	
GMch \$%	cZ ' : fca.	5dcb\$%	H. GMcb\$&			@g]7cbg] *##\$%	
GfUW 57	: Ua]m 5@SCH57HI]Ubg	NbY	7U[cfm			Fb. H	
5fU)&- G h @Y[h.	% : h	K]h.		(S: h		
GUg	GU@Y[h.	: h	GUVK]h.		: h	>ch@Y[h.	: h
Gci Xf.	GfYHhY		; fUX \$			@bg \$	
GMcb7caa Ylg							
Kcf_8UY %\$%*-	Kcf_HnY Bk7cbg]Vcb! :h]U		7cX BI!B			=AUcfA/ F. HiY	
Kcf_8UY (#\$%)	Kcf_HnY 7UWGUH!57		7cX 7G57			=AUcfA/ F. :UgY	
Kcf_8UY (#\$%)	Kcf_HnY GfUWGU!7cUHf		7cX GG7H			=AUcfA/ F. :UgY	
Kcf_8UY *##\$%	Kcf_HnY GfUg!5[[f]UY		7cX G65;			=AUcfA/ F. :UgY	
Kcf_8UY *##\$%	Kcf_HnY GfU7cig!G]ha]hg		7cX 65!6-			=AUcfA/ F. :UgY	
Kcf_8UY *##\$%	Kcf_HnY 7cadYfYw]g]Vcb!57		7cX 7F!57			=AUcfA/ F. HiY	
@g]hgl'8UY %\$#%\$%	HfUcladyg %		GfjYX %				
7cb]cbg D7= ,)							
-bg]Vcb7caa Ylg							
GldYBiaVf. \$%	HnY F	5fU)&-!\$\$G h		D7= ,)		
GldY7caa Ylg							
(, @/ H7F	@	&'\$\$: h					
(, @/ H7F	A	%\$\$: h					
) + K95H 9F-B;	@)&-!\$\$ G h					

BYkcf.	A&&		BuY	G`D[\:]YX				
GfUW	HFKS&		BuY	HKHfHfibiNFK`S&	IgY	H5L-K5M	5fU	%SSS Gc h
				FigXj]Y				
GUVch	S%		cZ %	: fca.	FibkUinSS		H. 9[YcZUjYaYh	@Gj7chg! (#SSS
GfZAW	57		: Ua]m	5@SCH57HI]kug	NbY		7UN]dim	FUb. D
5fU	%SSS Gc h		@Y[h.		%S: h		KPh.	, S: h
GUg			GUv@Y[h.		: h		GUVKPh.	: h
Gci Xf.			GfYWHnY					>clh@Y[h. : h
GUVcb7caaYhg								@Uhg \$
Kcf_8UY	%##*.		Kcf_HnY	Bk7chg! Vcb! :h]U			7cXY BI !-B	=gAUcfA/ F. HiY
Kcf_8UY	(#SSS		Kcf_HnY	7cadYWFVW]g! Vcb! 57			7cXY 7F!57	=gAUcfA/ F. HiY
@Gjhg! 8UY	%#SS%		HRUCladYg	&			GfjYMX &	
7cbN]dg	D7= +,							
-hgN]cb7caaYhg								
QladYBi aVf.	S%		HnY	F	5fU		*SSS Gc h	D7= +)
QladY7caaYhg								
(, @/ H7F			@		&SS : h			
(, @/ H7F			A		(SS : h			
)\$ D5H<-B;			@		, 'SS Gc h			
)+ K95H 9F-B;			@)-- 8SS Gc h			
QladYBi aVf.	S&		HnY	F	5fU		*SSS Gc h	D7= ,%
QladY7caaYhg								
(, @/ H7F			@		&&'SS : h			
)\$ D5H<-B;			@		+ 'SS Gc h			
)+ K95H 9F-B;			@)-- 'SS Gc h			

APPENDIX E
DISTRESS SUMMARY REPORT



) ° k
" h 7 U

"	o	o	o	v	U	o	j	j y)
°		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	O	7	
°		°#			k†- OS.....	#)	O	o7	
°		°#			‡ - ° u- kOS.....	#)	O	o7	
k		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	O	7	
k		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	U	7	
k		°#			‡ - ° u- kOS.....	#)	O	o7	
k		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	O	7	
k		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	U	7	
k		°#			h u# OS.....	#)	O	o7	
k		°#			k†- OS.....	#)	U	o7	
k		°#			‡ - ° u- kOS.....	#)	O	o7	
k		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	O	7	
k		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	U	7	
k		°#			‡ - ° u- kOS.....	#)	O	o7	
k		°#			‡ - ° u- kOS.....	#)	U	o7	
u°		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	O	7	
u°		°#			OV8ey) @° Ouk° Vof- lo° #k° #NOS.....	#)	U	7	
u°		°#			‡ - ° u- kOS.....	#)	O	o7	

) ° :
) ö k
 " h 7 U

"	ø	ø	ø	ø) v) U	ø	j	j y)
u		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	O		7	
u		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	U		7	
u		°#			‡ - ° u- kOS	#)	O		o7	
u° V8		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	O		7	
u° V8		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	U		7	
u° V8		°#			‡ - ° u- kOS	#)	O		o7	
u° V8		°#			° OS u k#k° #MOS	O	U		o7	
u° V8		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	O		7	
u° V8		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	U		7	
u° V8		°#			h u# OS	#)	O		o7	
u° V8		°#			h u# OS	#)	U		o7	
u° V8		°#			kyuOS	O	O		o7	
u° V8		°#			‡ - ° u- kOS	#)	O		o7	
u° V8		°#			° OS u k#k° #MOS	O	=		o7	
u° V8		°#			° OS u k#k° #MOS	O	U		o7	
u° V8		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	O		7	
u° V8		°#			OVSey) @° Ouk° Vof- lo° #k° #MOS	#)	U		7	
u° V8		°#			h u# OS	#)	=		o7	
u° V8		°#			h u# OS	#)	O		o7	
u° V8		°#			‡ - ° u- kOS	#)	O		o7	

) ° :
) ° k
 " h 7 U

"	°	°	°	°)))	°	j	j)
v	U	o	j	y)						
uk		°#			OV8ey) @° Ouk° Vof- ko° #k° #M8°.....	#)	O		7		
uk		°#			OV8ey) @° Ouk° Vof- ko° #k° #M8°.....	#)	U		7		
uk		°#			h u# @8°.....	#)	O		o7		
uk		°#			‡ - °u- k@8°.....	#)	O		o7		

°# ° # # °°# ° \ °# h## h # # °h# ° \ h##

APPENDIX F

INVENTORY

F1: Section Forecasted Pavement Condition Rating

F2: Branch PCI Rating

F3: Branch FOD Rating

Appendix F1
Forecasted Section PCI
 Bill Pugh Field (M22)

Branch ID	Section ID	Forecasted PCI						
		2021	2022	2023	2024	2025	2026	2027
A01	01	86	84	82	80	78	75	73
R0220	01	77	73	71	70	70	70	67
R0220	02	71	70	70	69	66	57	52
R0220	03	72	70	70	70	69	64	55
TA	01	71	68	64	60	55	50	46
TA	02	82	80	78	76	74	72	69
THANG01	01	82	80	78	76	74	72	69
THANG01	02	49	46	43	40	36	33	29
THANG01	03	37	33	30	26	23	19	16
TTRW02	01	76	74	71	68	64	60	55

%88:888%

6fUw7cbXhcbFYhfh

DjY%z&

DjYaYHSUUVgy 5@SCH7ca VbYSS%89%

6fUw7s	Bi a VfcZ GMfcbg	G a 'GMfcb' @b h hE	5j 'GMfcb' KPh hE	Hi Y5fYU RGe hE	I gy	5j MU Y D7=	GRbXEX 8Y Jhcb' D7=	KY \HX 5j MU Y D7=
59%	%	' &'88	&888	-%(*'88	5DFCB	,-'88	\$88	,-'88
F888	')ž 8888	+'88	(%ž 8888	FI BK5M	+''	'(\$	+''*
H5	&	88888)'88	-ž**'88	H5L-K5M	+)'\$)'\$	+''&
H5B; 9%	'	-+'88	(+*+	()ž-'88	H5L-K5M	*\$88	%/(*)\$' \$
HFk8&	%	%\$88	, \$88	%88888	H5L-K5M	+,'88	\$88	+,'88

%SSSS%
DJ Y&Z&
6fubW7cbYhcbFYbch
DjYa YHSUWUy 5@BCH7ca VbYSS%SS%

I gY7UW cfm	Bi a VYfcZ GWIcbg	HEU'5fYUQe: IL	5fha YjW 5j YU YD7=	5j YU YGB' D7=	KY \ BX 5j YU YD7=
5DFCB	%	-% (*'SS	, - 'SS	\$SS	, - 'SS
FI BK5M	'	(%SS)SSSS	+*'''	'('\$	+*''*
H5L-K5M	*	*+2\$)'SS	*-')\$	%('*)-'(-
5@@	%\$)+% \$'SS	+ ')\$	%'SS%	+*'++

, #&#\$\$\$%
DUY%Z&
6fUw7cbXhcbFYhfh
DjYaYHSUUVgy 5@SCHS\$\$ %

6fUw7s	Bi a VfcZ GMfcbg	G a 'GMfcb' @b h hEL	5j 'GMfcb' KPh hEL	Hi Y5fYU RGe hEL	I gy	5j YU Y : CS' DcHhJU : CS	GRbXEX SY Jhcb' DcHh : CS	KY \HX 5j YU Y : CS
5\$%	%	' &'\$\$	&\$\$	-%(*'\$\$	5DFCB	\$\$\$	\$\$\$	\$\$\$
F\$\$\$\$	')ž \$\$\$	+'\$\$	(%ž \$\$\$	FI BK5M	'*''	' '*	')*
H5	&	\$\$\$\$)'\$\$	-ž**'\$\$	H5L-K5M	' & \$	*') \$	' & %
H5B; \$%	'	- +'\$\$	(+*+	()ž- '\$\$	H5L-K5M	((''	%'&)%&
HFk\$&	%	%\$\$, \$\$\$	%\$\$\$\$	H5L-K5M	' ('\$\$	\$\$\$	' ('\$\$

, #8-#88%
DJ Y&cZ&
6fubW7cbYhcbFYbch
 DjYa YHSUWUy 5@8CH88\$ %

I gY7UW cfm	Bi a VYfcZ GWIcbg	HEU'5fYUQe: IL	5fha YfW 5j YU Y: CS	5j YU YGB' : CS DcHbJU	KY \ BX 5j YU Y: CS D
5DFCB	%	-% (*'88	8/88	888	8/88
FI BK5M	'	(%8) 8888	1*111	1''*	1)'*
H5L-K5M	*	*+28)'88	1, 1*+	888 \$	0''-
5@@	%8)+% 8/88	1*188	88),	1('*

APPENDIX G

SAFETY AND PREVENTIVE MAINTENANCE POLICIES



Appendix G1
Localized Safety (Stopgap) Repair Policy

Distress	Distress Severity	Description	Code	Work Type	Work Unit
41	High	ALLIGATOR CR	PA-FD	Patching - AC Full-Depth	SqFt
43	High	BLOCK CR	CS-AC	Crack Sealing - AC	Ft
45	High	DEPRESSION	PA-FD	Patching - AC Full-Depth	SqFt
47	High	JT REF. CR	CS-AC	Crack Sealing - AC	Ft
48	High	L & T CR	CS-AC	Crack Sealing - AC	Ft
50	High	PATCHING	PA-FD	Patching - AC Full-Depth	SqFt
53	High	RUTTING	PA-FD	Patching - AC Full-Depth	SqFt
54	High	SHOVING	PA-PD	Patching - AC Partial-Depth	SqFt
55	NA	SLIPPAGE CR	PA-PD	Patching - AC Partial-Depth	SqFt
56	High	SWELLING	PA-FD	Patching - AC Full-Depth	SqFt
61	High	BLOW-UP	SL-PC	Slab Replacement - PCC	SqFt
61	Medium	BLOW-UP	PA-PF	Patching - PCC Full Depth	SqFt
62	High	CORNER BREAK	PA-PF	Patching - PCC Full Depth	SqFt
63	High	LINEAR CR	PA-PF	Patching - PCC Full Depth	SqFt
63	Medium	LINEAR CR	CS-PC	Crack Sealing - PCC	Ft
64	High	DURABIL. CR	SL-PC	Slab Replacement - PCC	SqFt
64	Medium	DURABIL. CR	PA-PF	Patching - PCC Full Depth	SqFt
66	High	SMALL PATCH	PA-PP	Patching - PCC Partial Depth	SqFt
67	High	LARGE PATCH	PA-PF	Patching - PCC Full Depth	SqFt
70	High	SCALING	SL-PC	Slab Replacement - PCC	SqFt
71	High	FAULTING	GR-PP	Grinding (Localized)	Ft
72	High	SHAT. SLAB	SL-PC	Slab Replacement - PCC	SqFt
74	High	JOINT SPALL	PA-PP	Patching - PCC Partial Depth	SqFt
75	High	CORNER SPALL	PA-PP	Patching - PCC Partial Depth	SqFt
76	High	ASR	SL-PC	Slab Replacement - PCC	SqFt

°
8
O h k h

)) o)	#	‡ u	‡ y
	U	° 08 u k#h	h° °)	h °° #7)	o7
	=	° 08 u k#h	h° °)	h °° #7)	o7
	V°	"O) 08"	h° °c	h °° #h)	o7
	=	"O #Mk"	h° °)	h °° #7)	o7
	U	"O #Mk"	#o° #	# ° ° °° #	7
	O	# hky8 u@V	h° °c	h °° #h)	o7
	=	# hky8 u@V	h° °c	h °° #h)	o7
	U	# hky8 u@V	h° °c	h °° #h)	o7
	U) - h k α@V	h° °)	h °° #7)	o7
	O) - h k α@V	h° °)	h °° #7)	o7
	=) - h k α@V	h° °)	h °° #7)	o7
	=	Kk 7 #k'	#o° #	# ° ° °° #	7
	U	Kk 7 #k'	#o° #	# ° ° °° #	7
	=	O u#k"	#o° #	# ° ° °° #	7
	U	O u#k"	#o° #	# ° ° °° #	7
	V°	\ @h08	h° °)	h °° #7)	o7
	=	h u# 08"	h° °)	h °° #7)	o7
	U	h u# 08"	h° °)	h °° #7)	o7
	=	k° † - 08"	h° °c	h °° #h)	o7
	=	kyu08"	h° °)	h °° #7)	o7
	O	kyu08"	h° °)	h °° #7)	o7
	U	kyu08"	h° °)	h °° #7)	o7
	V°	α@h° 8 #k	h° °)	h °° #7)	o7
	O	‡ - 08"	h° °)	h °° #7)	o7
	U	‡ - 08"	h° °)	h °° #7)	o7
	O	"O‡ yh"	h° h	h ° h##7)	o7
	U	"O‡ yh"	h° h	h ° h##7)	o7
	=	"O‡ yh"	h° h	h ° h##7)	o7
	U	# kV k'k° N	h° h	h ° h##7)	o7
	=	# kV k'k° N	h° h	h ° h##7)	o7
	O	# kV k'k° N	#oh#	# ° ° °° h##	7
	U	@ ° k#k"	#oh#	# ° ° °° h##	7
	=	@ ° k#k"	h° h	h ° h##h)	o7
	U)yk° "O#k	h° h	h ° h##7)	o7
	=)yk° "O#k	α@h	o k °° h##	o7
	=	Kio° Q US	KG	K ° ° °°	7
	U	Kio° Q US	KG	K ° ° °°	7
	=	d° @h u#	h° h	h ° h##h)	o7
	U	d° @h u#	h° h	h ° h##h)	o7
	U	Ol8 h u#	h° h	h ° h##7)	o7

°
8
O h k h

)) o)	#	‡ u	‡ y
=		Ol8 h u#	h h	h ' h##7)	o7
V°		hyUh08	kG	K o ' O	7
U		α# 08	h h	h ' h##h)	o7
=		α# 08	αh	o k ' h##	o7
=		7y008	8kh	8 ' O	7
U		7y008	8kh	8 ' O	7
U		α° u' α''	αh	o k ' h##	o7
=		α° u' α''	αh	o k ' h##	o7
=		K@uch @	h h	h ' h##h)	o7
U		K@uch @	h h	h ' h##h)	o7
U		# kV kch @	h h	h ' h##h)	o7
=		# kV kch @	h h	h ' h##h)	o7
U		° dk	αh	o k ' h##	o7
=		° dk	αh	o k ' h##	o7

APPENDIX H

M&R UNIT COSTS

H1: M&R Unit Costs

H2: Component Costs for Repair

H3: Airport Category

Maintenance and Repair (M&R) Unit Costs

The M&R costs developed for the ALDOT PMP include costs for maintenance, preservation, and repair activities and are described below.

Unit Costs Source Data

The source for the M&R costs data is RSMMeans, which has data for 14 locations throughout Alabama, as identified by the yellow highlighted boxes in Figure 1. The cost data is presented in terms of individual line items like asphalt wearing course, aggregate base etc., which were consolidated to develop the activity costs described below.

The cost data show a distinct difference in costs between locations north and south of Birmingham, especially for the higher value items like the asphalt layers. Therefore, the unit costs were developed accordingly for the airports north and south of Birmingham, as identified in Figure 1. Appendix H2 presents the component costs used in developing the M&R costs.




Figure 1: RSMMeans Unit Costs Locations.

Maintenance & Repair (M&R) Activities

Maintenance activities are localized activities which are typically assigned in the first year of the M&R plan based on the observed distresses.

Repair activities are further subdivided into preservation, rehabilitation, and reconstruction. Repair activities are conducted for larger areas, typically at the section level and are assigned based on the Critical Pavement Condition Index, denoted as CP in Table 1. The CP is based on the section’s rank or importance within the overall network and typically ranges from 55 to 70. The CP was set at 70 for the ALDOT runway pavements and 65 for the other pavements.

Table 1: Repair Activities.

Activity Type	PCI	Activity
Preservation	> CP	Runway Surface Treatment
		Taxiway and Apron Surface Treatment
Rehabilitation	> CP	2" AC OL ¹
	55 - CP	Mill 2" & 2" AC OL
	45 - 55	Mill 2" & 3" AC OL
Reconstruction	0 - 45	Reconstruct with AC

¹For Sections with Structural Distress and PCI greater than Critical PCI

The depths for the milling and overlay (AC OL) in Table 1 were established by creating a balance between removal of surficial distress and providing additional pavement structural capacity. All overlay options include full-depth patching to repair localized distresses.

From the FAA 5010 records, the Alabama airport network includes a wide range of allowable aircraft loads. The airports were divided into three categories of allowable aircraft loads based on requirements for minimum pavement thickness and the use of a P-401 surface layer. The categories are based on the aircraft maximum gross takeoff weight (MGTOW) and include: less than 12,500 lbs, 12,500 to 30,000 lbs, and 30,000 to 100,000 lbs. Appendix H3 presents the category for each airport.

For any sections requiring reconstruction, the pavement sections were established primarily in accordance with the requirements in Table 3 of the FAA’s Advisory Circular 150/5320-6F. The pavement sections used for developing the cost estimates are:

- 12,500 lbs 4" P-403 (State HMA Mix) + 6" P-209 Base
- 12,500 – 30,000 lbs 4" P-403 (State HMA Mix) + 8" P-209 Base
- 30,000 – 100,000 lbs 5" P-401 + 10" P-209 Base

It is important to note that while the FAA requires a stabilized base for those pavements that support aircraft operations with MGTOWs that are greater than 100,000 lbs, the number of such operations is minimal for those airports shown in Appendix H3. As a result, the cost of a stabilized base is excluded in the development of the unit costs for ALDOT’s PMP update. However, based on the Engineer’s future design and aircraft fleet mix development, project-level construction work could include the use of a stabilized base at that time.

M&R Unit Costs

Paving projects typically include additional project costs like mobilization, design, construction administration and inspections, and drainage improvements. A summary of non-direct pavement construction line items has been included in the unit costs in Tables 5 and 6 as described below. These non-direct items are expressed as a percentage of the total component costs for each activity.

These non-direct pavement construction items were developed from API’s extensive experience with APMP project cost estimation. These percentages may vary for Alabama airport construction projects; however, since the direct pavement scope of work is estimated in a network-level evaluation, these conservative estimates serve as a good starting point for the development of realistic total project costs and annual APMP budgets for ALDOT. For repair activities such as Mill & Overlay, which typically do not include significant drainage work, the corresponding multiplier was reduced by 50 percent. The non-direct cost factors are presented in Table 2.

Table 2: Cost Factors.

Factor	Function of	Estimate		
		Preservation	Rehabilitation	Reconstruction
Mobilization	All costs, less design	10%	10%	10%
Drainage Improvements	Paving costs	-	4%	8%
Contingency	All costs, less mobilization and design	10%	20%	20%
Design & CM	All costs, less mobilization and design	15%	20%	20%

The M&R unit costs for maintenance, preservation, and repair activities were developed from the RSMMeans cost data and are presented in the following section.

Maintenance

The maintenance activities include crack seal, and full and partial-depth patching. The unit costs are presented in Table 3.

Table 3: Unit Costs for Maintenance.

Activity	Unit Cost	Unit
Seal Cracks - AC	\$3.95	lf
AC Full-Depth Patching	\$25.05	sf
AC Partial-Dept Patching	\$16.28	sf
Seal Cracks – PCC	\$6.00	lf
PCC Full-Depth Patching	\$35.00	sf
PCC Partial-Depth Patching	\$175.00	sf
Jt. Seal	\$8.00	lf
Slab Replacement	\$20.00	sf

Preservation

The unit costs for the surface treatments are presented in Table 4. They include sealing of cracks and application of pavement markings.

Table 4: Unit Costs for Preservation Activities.

Activity	Unit Cost	Unit
Runway Surface Treatment	\$0.57	sf
Taxiway and Apron Surface Treatment	\$0.88	sf

Rehabilitation and Reconstruction

As discussed previously, repair activities are also divided into rehabilitation and reconstruction. The unit costs for airport repair for the Northern Region (Birmingham Area) and Southern Region (Montgomery Area) are shown in Tables 5 and 6, respectively.

Table 5: Unit Costs for Repair Activities, Northern Region.

Activity Type	Activity	MGTOW, thousand lbs		
		12.5	12.5-30	30-100
Rehabilitation	2" AC OL	\$3.78		\$4.19
	Mill 2" & 2" AC OL	\$4.15		\$4.56
	Mill 2" & 3" AC OL	\$5.18		\$5.79
Reconstruction	AC Reconstruction	\$8.40	\$9.10	\$10.91

Table 6: Unit Costs for Repair Activities, Southern Region.

Activity Type	Activity	MGTOW, thousand lbs		
		12.5	12.5-30	30-100
Rehabilitation	2" AC OL	\$3.54		\$3.91
	Mill 2" & 2" AC OL	\$3.90		\$4.27
	Mill 2" & 3" AC OL	\$4.82		\$5.37
Reconstruction	AC Reconstruction	\$7.63	\$8.25	\$9.87

Appendix H2
Component Costs for Repair

Activity Type	Unit	Birmingham (Northern)	Montgomery (Southern)	Comments
Milling 1" to 3"	SY	\$2.08	\$2.01	
Pavement Demolition	SY	\$6.34	\$6.12	
Haulage - For Demolition & AC	CY	\$6.08	\$5.87	
Haulage for 12" Thick Demolition	SY	\$2.03	\$1.96	
Haulage for 2" Thick AC Paving	SY	\$0.34	\$0.33	
Haulage for 3" Thick AC Paving	SY	\$0.51	\$0.49	
Haulage for 4" Thick AC Paving	SY	\$0.68	\$0.65	
AC Wearing Course	Ton	\$97.42	\$86.90	
AC Binder Course	Ton	\$87.80	\$78.17	
P401 - For airports with >60 kip aircraft	Ton	\$116.90	\$104.28	Assumed P401 cost to be 20% greater than AC Wearing Course
6" Aggregate Base (P208)	SY	\$10.17	\$9.12	
8" Aggregate Base (P208)	SY	\$13.29	\$11.89	
6" P209 Aggregate Base	SY	\$12.20	\$10.94	Assumed P209 cost to be 20% greater than P208
8" P209 Aggregate Base	SY	\$15.95	\$14.27	Assumed P209 cost to be 20% greater than P208
10" P209 Aggregate Base	SY	\$19.94	\$17.84	Direct multiplier for 10" from 8"
4" P154 Aggregate Base	SY	\$5.42	\$4.86	Assumed P154 cost to be 20% lower than P208
6" P154 Aggregate Base	SY	\$8.14	\$7.30	Assumed P154 cost to be 20% lower than P208
Pavement Markings	sf	\$1.48	\$1.39	

**Appendix H3
Airport Category**

Region	City	FAA ID	Max Gross Weight (Thousand lbs)			Max GW	Category
			S	D	2D		
Birmingham	Reform	3M8	12.5	-	-	12.5	<= 12,500
	Fayette	M95	15.0	-	-	15.0	12,500-30,000
	Hamilton	HAB	15.0	-	-	15.0	12,500-30,000
	Scottsboro	4A6	15.0	-	-	15.0	12,500-30,000
	Alabaster	EET	16.0	-	-	16.0	12,500-30,000
	Centre-Piedmont	PYP	16.0	-	-	16.0	12,500-30,000
	Fort Payne	4A9	16.0	-	-	16.0	12,500-30,000
	Haleyville	1M4	20.0	-	-	20.0	12,500-30,000
	Hartselle	5M0	20.0	-	-	20.0	12,500-30,000
	Guntersville	8A1	24.0	-	-	24.0	12,500-30,000
	Cullman	CMD	30.0	-	-	30.0	12,500-30,000
	Russellville	M22	30.0	-	-	30.0	12,500-30,000
	Jasper	JFX	50.0	-	-	50.0	> 30,000
	Oneonta	20A	20.0	35.0	55.0	55.0	> 30,000
	Bessemer	EKY	60.0	60.0	-	60.0	> 30,000
	Albertville	8A0	60.0	90.0	130.0	130.0	> 30,000
	Madison	MDQ	60.0	75.0	140.0	140.0	> 30,000
	Decatur	DCU	75.0	125.0	150.0	150.0	> 30,000
	Tuscaloosa	TCL	61.0	87.0	168.0	168.0	> 30,000
	Gadsden	GAD	90.0	115.0	195.0	195.0	> 30,000
Montgomery	Florala	0J4	-	-	-	-	<= 12,500
	Elba	14J	4.0	-	-	4.0	<= 12,500
	Headland	0J6	12.0	-	-	12.0	<= 12,500
	Roanoke	7A5	12.0	-	-	12.0	<= 12,500
	Greenville	PRN	15.0	-	-	15.0	12,500-30,000
	Union Springs	07A	15.0	-	-	15.0	12,500-30,000
	Wetumpka	08A	15.0	-	-	15.0	12,500-30,000
	Atmore	0R1	16.0	-	-	16.0	12,500-30,000
	Clanton	02A	16.0	-	-	16.0	12,500-30,000
	Eufaula	EUF	16.0	-	-	16.0	12,500-30,000
	Geneva	33J	16.0	-	-	16.0	12,500-30,000
	Greensboro	7A0	16.0	-	-	16.0	12,500-30,000
	Centreville	0A8	18.0	-	-	18.0	12,500-30,000
	Ashland-Lineville	26A	20.0	-	-	20.0	12,500-30,000
	Sylacauga	SCD	20.0	-	-	20.0	12,500-30,000
	St. Elmo	2R5	23.0	-	-	23.0	12,500-30,000
	Ozark	71J	-	25.0	-	25.0	12,500-30,000
	Camden	61A	27.0	-	-	27.0	12,500-30,000
	Bay Minette	1R8	28.0	-	-	28.0	12,500-30,000
	Foley	5R4	28.0	-	-	28.0	12,500-30,000
Tuskegee	06A	28.5	-	-	28.5	12,500-30,000	

**Appendix H3
Airport Category**

Region	City	FAA ID	Max Gross Weight (Thousand lbs)			Max GW	Category
			S	D	2D		
Montgomery	Alexander City	ALX	30.0	-	-	30.0	12,500-30,000
	Dauphin Island	4R9	30.0	-	-	30.0	12,500-30,000
	Pell City	PLR	30.0	-	-	30.0	12,500-30,000
	Prattville	1A9	30.0	-	-	30.0	12,500-30,000
	Enterprise	EDN	-	-	-	-	> 30,000
	Evergreen	GZH	30.0	50.0	-	50.0	> 30,000
	Marion	A08	30.0	50.0	-	50.0	> 30,000
	Selma	SEM	33.0	54.0	-	54.0	> 30,000
	Fairhope	CQF	36.0	58.0	-	58.0	> 30,000
	Brewton	12J	40.0	60.0	-	60.0	> 30,000
	Demopolis	DYA	30.0	38.0	60.0	60.0	> 30,000
	Monroeville	MVC	70.0	-	-	70.0	> 30,000
	Auburn-Opelika	AUO	45.0	75.0	-	75.0	> 30,000
	Talladega	ASN	30.0	65.0	95.0	95.0	> 30,000
	Gulf Shores	JKA	80.0	100.0	-	100.0	> 30,000
	Troy	TOI	24.0	80.0	140.0	140.0	> 30,000
	Anniston	ANB	28.0	43.5	260.0	260.0	> 30,000
Andalusia-OPP	79J	98.0	160.0	275.0	275.0	> 30,000	

APPENDIX I

PAVEMENT CAPITAL IMPROVEMENT PROGRAM

I1: PCIP Summary

I2: Year 1 Maintenance Plan



Appendix I1
PCIP Summary
 Bill Pugh Field (M22)

Branch & Section	2021	2022	2023	2024	2025	2026	2027
A01-01	Preventive + Required Project Global MR \$82019.26 Before:86.32 After:92.95	Preventive \$894.6 Before:90.74 After:90.74	Preventive \$1141.17 Before:88.53 After:88.53	Preventive \$1401.73 Before:86.32 After:86.32	Preventive \$1677.86 Before:84.1 After:84.1	Preventive \$1968.31 Before:81.89 After:81.89	Preventive \$2271.61 Before:79.68 After:79.68
R0220-01	Preventive \$4518.1 Before:76.35 After:76.35	Required Project Major Above Critical \$836136 Before:73.16 After:100	Preventive \$267.23 Before:98.7 After:98.7	Preventive \$533.16 Before:97.48 After:97.48	Preventive + Required Project Global MR \$125909.18 Before:96.45 After:98.7	Preventive \$565.63 Before:97.48 After:97.48	Preventive \$820.27 Before:96.45 After:96.45
R0220-02	Preventive \$5403.56 Before:70.59 After:70.59	Required Project Major Below Critical \$816621.75 Before:69.86 After:100	Preventive \$260.99 Before:98.7 After:98.7	Preventive \$520.72 Before:97.48 After:97.48	Preventive + Required Project Global MR \$122970.64 Before:96.45 After:98.7	Preventive \$552.43 Before:97.48 After:97.48	Preventive \$801.12 Before:96.45 After:96.45
R0220-03	Preventive \$1061.94 Before:71.7 After:71.7	Required Project Major Above Critical \$166367.25 Before:70.23 After:100	Preventive \$53.17 Before:98.7 After:98.7	Preventive \$106.08 Before:97.48 After:97.48	Preventive + Required Project Global MR \$25052.34 Before:96.45 After:98.7	Preventive \$112.54 Before:97.48 After:97.48	Preventive \$163.21 Before:96.45 After:96.45

Appendix I1
PCIP Summary
 Bill Pugh Field (M22)

Branch & Section	2021	2022	2023	2024	2025	2026	2027
TA-01	Preventive \$145.19 Before:71.01 After:71.01	Required Project Major Below Critical \$22239.63 Before:67.92 After:100	Preventive \$5.57 Before:98.98 After:98.98	Preventive \$12.13 Before:97.85 After:97.85	Preventive + Required Project Global MR \$3349.68 Before:96.33 After:98.98	Preventive \$12.87 Before:97.85 After:97.85	Preventive \$22.6 Before:96.33 After:96.33
TA-02	Preventive + Required Project Global MR \$4242.72 Before:82.08 After:89.69	Preventive \$64.45 Before:87.04 After:87.04	Preventive \$79.51 Before:84.47 After:84.47	Preventive \$94.5 Before:82.08 After:82.08	Preventive \$109.09 Before:79.91 After:79.91	Preventive \$122.54 Before:77.91 After:77.91	Preventive \$136.43 Before:75.96 After:75.96
THANG01-01	Preventive + Required Project Global MR \$4749.37 Before:82.08 After:89.69	Preventive \$72.14 Before:87.04 After:87.04	Preventive \$89 Before:84.47 After:84.47	Preventive \$105.79 Before:82.08 After:82.08	Preventive \$122.12 Before:79.91 After:79.91	Preventive \$137.17 Before:77.91 After:77.91	Preventive \$152.72 Before:75.96 After:75.96
THANG01-02	Required Project Major Below Critical \$77547.48 Before:48.42 After:100	Preventive \$15.56 Before:98.98 After:98.98	Preventive \$33.92 Before:97.85 After:97.85	Preventive \$59.56 Before:96.33 After:96.33	Preventive \$94.45 Before:94.35 After:94.35	Preventive \$137.79 Before:91.99 After:91.99	Preventive \$188 Before:89.39 After:89.39
THANG01-03	Required Project Major Below Critical \$238747.6 Before:36.7 After:100	Preventive \$27.31 Before:98.98 After:98.98	Preventive \$59.52 Before:97.85 After:97.85	Preventive \$104.5 Before:96.33 After:96.33	Preventive \$165.72 Before:94.35 After:94.35	Preventive \$241.76 Before:91.99 After:91.99	Preventive \$329.86 Before:89.39 After:89.39

Appendix I1
PCIP Summary
 Bill Pugh Field (M22)

Branch & Section	2021	2022	2023	2024	2025	2026	2027
TTRW02-01	Preventive \$294.09 Before:75.62 After:75.62	Required Project Major Above Critical \$52920 Before:73.49 After:100	Preventive \$13.25 Before:98.98 After:98.98	Preventive \$28.87 Before:97.85 After:97.85	Preventive + Required Project Global MR \$7970.69 Before:96.33 After:98.98	Preventive \$30.63 Before:97.85 After:97.85	Preventive \$53.78 Before:96.33 After:96.33

Appendix I2
Localized Maintenance Plan
 Bill Pugh Field (M22)

Branch ID	Section ID	Policy	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
A01	01	Preventive	57	WEATHERING	Low	91,534	SqFt	99.77	No Localized M & R	0		\$0.00	\$0
A01	01	Preventive	48	L & T CR	Low	1,003	Ft	1.09	No Localized M & R	0		\$0.00	\$0
A01	01	Preventive	52	RAVELING	Low	212	SqFt	0.23	No Localized M & R	0		\$0.00	\$0
R0220	01	Preventive	48	L & T CR	Medium	148	Ft	0.08	Crack Sealing - AC	148	Ft	\$3.95	\$586
R0220	01	Preventive	57	WEATHERING	Low	74,829	SqFt	39.47	No Localized M & R	0		\$0.00	\$0
R0220	01	Preventive	48	L & T CR	Low	9,168	Ft	4.84	No Localized M & R	0		\$0.00	\$0
R0220	02	Preventive	52	RAVELING	Medium	1,097	SqFt	0.59	No Localized M & R	0		\$0.00	\$0
R0220	02	Preventive	48	L & T CR	Medium	357	Ft	0.19	Crack Sealing - AC	357	Ft	\$3.95	\$1,409
R0220	02	Preventive	50	PATCHING	Low	11	SqFt	0.01	No Localized M & R	0		\$0.00	\$0
R0220	02	Preventive	57	WEATHERING	Low	87,787	SqFt	47.41	No Localized M & R	0		\$0.00	\$0
R0220	02	Preventive	48	L & T CR	Low	12,647	Ft	6.83	No Localized M & R	0		\$0.00	\$0
R0220	03	Preventive	48	L & T CR	Medium	45	Ft	0.12	Crack Sealing - AC	45	Ft	\$3.95	\$179
R0220	03	Preventive	57	WEATHERING	Medium	4,695	SqFt	12.44	No Localized M & R	0		\$0.00	\$0
R0220	03	Preventive	57	WEATHERING	Low	13,581	SqFt	36	No Localized M & R	0		\$0.00	\$0
R0220	03	Preventive	48	L & T CR	Low	2,389	Ft	6.33	No Localized M & R	0		\$0.00	\$0
TA	01	Preventive	48	L & T CR	Low	338	Ft	6.7	No Localized M & R	0		\$0.00	\$0
TA	01	Preventive	57	WEATHERING	Low	1,009	SqFt	20	No Localized M & R	0		\$0.00	\$0
TA	01	Preventive	48	L & T CR	Medium	12	Ft	0.24	Crack Sealing - AC	12	Ft	\$3.95	\$48
TA	02	Preventive	48	L & T CR	Low	20	Ft	0.42	No Localized M & R	0		\$0.00	\$0
TA	02	Preventive	57	WEATHERING	Low	3,300	SqFt	69.87	No Localized M & R	0		\$0.00	\$0
TA	02	Preventive	48	L & T CR	Medium	20	Ft	0.42	Crack Sealing - AC	20	Ft	\$3.95	\$79
THANG01	01	Preventive	57	WEATHERING	Low	5,287	SqFt	100	No Localized M & R	0		\$0.00	\$0
THANG01	01	Preventive	48	L & T CR	Medium	10	Ft	0.19	Crack Sealing - AC	10	Ft	\$3.95	\$40
THANG01	01	Preventive	48	L & T CR	Low	23	Ft	0.44	No Localized M & R	0		\$0.00	\$0
THANG01	02	Safety	50	PATCHING	Medium	50	SqFt	0.34	No Localized M & R	0		\$0.00	\$0
THANG01	02	Safety	50	PATCHING	Low	2,415	SqFt	16.63	No Localized M & R	0		\$0.00	\$0
THANG01	02	Safety	41	ALLIGATOR CR	Medium	105	SqFt	0.72	No Localized M & R	0		\$0.00	\$0
THANG01	02	Safety	53	RUTTING	Low	80	SqFt	0.55	No Localized M & R	0		\$0.00	\$0
THANG01	02	Safety	57	WEATHERING	Low	2,000	SqFt	13.77	No Localized M & R	0		\$0.00	\$0

Appendix I2
Localized Maintenance Plan
 Bill Pugh Field (M22)

Branch ID	Section ID	Policy	Distress Code	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Work Qty	Work Unit	Unit Cost	Work Cost
THANG01	02	Safety	48	L & T CR	Medium	180	Ft	1.24	No Localized M & R	0		\$0.00	\$0
THANG01	02	Safety	48	L & T CR	Low	900	Ft	6.2	No Localized M & R	0		\$0.00	\$0
THANG01	03	Safety	50	PATCHING	High	28	SqFt	0.11	Patching - AC Full-Depth	53	SqFt	\$25.05	\$1,319
THANG01	03	Safety	57	WEATHERING	Low	9,695	SqFt	38.05	No Localized M & R	0		\$0.00	\$0
THANG01	03	Safety	50	PATCHING	Low	473	SqFt	1.86	No Localized M & R	0		\$0.00	\$0
THANG01	03	Safety	41	ALLIGATOR CR	Medium	866	SqFt	3.4	No Localized M & R	0		\$0.00	\$0
THANG01	03	Safety	41	ALLIGATOR CR	High	57	SqFt	0.23	Patching - AC Full-Depth	91	SqFt	\$25.05	\$2,301
THANG01	03	Safety	48	L & T CR	Medium	120	Ft	0.47	No Localized M & R	0		\$0.00	\$0
THANG01	03	Safety	48	L & T CR	Low	1,325	Ft	5.2	No Localized M & R	0		\$0.00	\$0
TTRW02	01	Preventive	48	L & T CR	Low	488	Ft	4.07	No Localized M & R	0		\$0.00	\$0
TTRW02	01	Preventive	50	PATCHING	Low	15	SqFt	0.12	No Localized M & R	0		\$0.00	\$0
TTRW02	01	Preventive	57	WEATHERING	Low	11,985	SqFt	99.88	No Localized M & R	0		\$0.00	\$0
TTRW02	01	Preventive	48	L & T CR	Medium	40	Ft	0.33	Crack Sealing - AC	40	Ft	\$3.95	\$158