

ALABAMA DEPARTMENT OF TRANSPORTATION

AERONAUTICS BUREAU 1409 COLISEUM BOULEVARD MONTGOMERY, ALABAMA 36110

PHONE (334) 242-6820 FAX (334) 353-6540 Internet: www.dot.state.al.us



December 12, 2022

Mr. Brian Kegley, P.E. Mobile County Engineer Public Works, Engineering Department Mobile, Alabama 36644

Subject: Annual Inspection Report Jeremiah Denton Airport

Dear Mr. Kegley:

An inspection of the Jeremiah Denton Airport was conducted by personnel of the Alabama Department of Transportation Aeronautics Bureau on November 2nd, 2022. The purpose of the inspection was to update the information currently on file regarding the airport and to ascertain compliance with the rules and regulations of the Alabama Department of Transportation governing licensed public-use airports within the State of Alabama.

Attached you will find a copy of the Annual Inspection Report. As noted in the report, the airport <u>meets</u> the requirements for the issuance of an operating license. A signed license document will be mailed separately within a few weeks.

If you should have any questions concerning the inspection or corrective actions, please do not hesitate to contact Mr. Jason Hare with the Aeronautics Bureau at (334) 353-6223.

Sincerely,

Frank Farmer

Chief, Aeronautics Bureau

Copy: Mr. Rans Black, FAA/ADO

Mr. Matt Mims, FAA/ADO

Mr. Bobby Odom, Michael Baker Mr. Bill Meredith, Airport Manager

November 2, 2022



ANNUAL INSPECTION REPORT



JEREMIAH DENTON AIRPORT DAUPHIN ISLAND, ALABAMA

Approach and Departure Paths—RUNWAY 12

Administrative Code 450-9-1-.12(1)



No ALDOT obstructions located in the Approach/Departure Path of Runway 12.

Approach and Departure Paths—RUNWAY 30

Administrative Code 450-9-1-.12(1)



No ALDOT obstructions located in the Approach/Departure Path of Runway 30.

Primary Surface

Administrative Code 450-9-1-.12(2)



<u>Maintenance Required:</u> Remove all debris from primary surface.

Primary Surface

Administrative Code 450-9-1-.12(2)



Maintenance Required: There is a small portion of the airfield that can only provide 119 feet of clear primary surface instead of the required 125 feet. Tall grass and brush are growing in this area near a bluff that slopes down to a beach. This area should be cleared if possible and monitored closely to ensure that the tall grass and brush do not encroach further.

Runway Safety Area

Administrative Code 450-9-1-.12(3)



<u>Maintenance Required</u>: Rocks should be gradated smooth and leveled.

Airport Markings

Administrative Code 450-9-1-.12(4)



Runway markings are in **GOOD** condition.

Wind Direction Indicator

Administrative Code 450-9-1-.12(5)



Wind direction indicator is in **GOOD** condition.

Airport Lighting

Administrative Code 450-9-1-.12(6)

An inspection of the lighting system had the following results:

Runway Lights	0 inoperable
Taxiway Lights	0 fixture broken
Threshold Lights	0 inoperable
PAPI	0 inoperable
REIL	N/A

MEETS State Licensing Standards for night-time operation.

Runway, Taxiway and Apron Conditions—RUNWAY Administrative Code 450-9-1-.12(7)



Runway surface is in **GOOD** condition.

Runway, Taxiway and Apron Conditions—TAXIWAY Administrative Code 450-9-1-.12(7)



Taxiway surface is in **GOOD** condition.


Runway, Taxiway and Apron Conditions—APRON Administrative Code 450-9-1-.12(7)



Apron surface is in **GOOD** condition.

Fueling Area Requirements

Administrative Code 450-9-1-.12(8)



N/A: There is no fuel service at this airport

Prohibited Activities

Administrative Code 450-9-1-.16



No prohibited activities were observed during this inspection.

Alabama Department of Transportation Aeronautics Bureau—Annual Airport Inspection Report

In accordance with the provisions of the Code of Alabama 23-1-357, an inspection of the <u>Jeremiah Denton Airport</u> was conducted by <u>Mr. Jason Hare and Mr. Bennett</u> Head with the Alabama Department of Transportation Aeronautics Bureau on November 2nd, 2022.

The inspection was conducted on the airport under the provisions of the Administrative Code Chapter 450-9-1 for the following areas:

Aeronautics Administrative Code	Inspection Results	Corrective Action	Notes
Approach & Departure Paths	In Compliance	N/A	N/A
Administrative Code 450-9-112 (1)			
Primary Surface	In Compliance	Remove all debris from primary surface	The ground of the primary surface was in
Administrative Code 450-9-112 (2)	Maintenance		good condition, but storm debris needs to be removed.
Runway Safety Area	In Compliance	Rocks need to be graded smooth and	Rocks on the approach end of Runway 12
Administrative Code 450-9-112 (3)	Maintenance	leveled	have been moved and piled up by storm surge over the seawall. The rocks just need to be leveled out.
Airport Markings	In Compliance	N/A	N/A
Administrative Code 450-9-112 (4)			
Wind Direction Indicator	In Compliance	N/A	N/A
Administrative Code 450-9-112 (5)			
Airport Lighting	In Compliance	N/A	N/A
Administrative Code 450-9-112 (6)			
Runway, Taxiway and Apron Conditions	In Compliance	N/A	N/A
Administrative Code 450-9-112 (7)			
Fueling Area Requirements	In Compliance	N/A	N/A
Administrative Code 450-9-112 (8)			
Prohibited Activities	In Compliance	N/A	N/A
Administrative Code 450-9-116			

License Status—COMPLIANCE

The corrective actions that may be prescribed in this inspection report do not relieve the airport sponsor from compliance with any other Federal, State or local laws, ordinances or regulations that may be applicable. It is the responsibility of the airport sponsor to be aware of and obey all Federal, State or local laws, ordinances or regulations that may have a bearing on the corrective actions that may be specified in this report.


Code of Alabama 23-1-357(a)... a person or municipality may not operate an airport, restricted landing area, or other navigation facility without a license issued by this Department.

JEREMIAH DENTON AIRPORT Dauphin Island, AL November 2, 2022 RWY 30 Obstruction Evaluation

- 4. Tree 34' Abv. RWY
 747' From Rwy End
 106' Left of CL
 20:1 Obst. Clnc. (FAA)
- 5. Tree 61' Abv. RWY End 979' From RWY End 216' Left of CL 15:1 Obst. Clnc. (FAA)
- 6. Pole 37' Abv. RWY End 771' From RWY End 290' Left of CL 19:1 Obst. Clnc. (FAA)



APPENDIX 1



END OF REPORT

-200'-