

ALABAMA DEPARTMENT OF TRANSPORTATION AERONAUTICS BUREAU 1409 COLISEUM BOULEVARD MONTGOMERY, ALABAMA 36110 PHONE (334) 242-6820 FAX (334) 353-6540 Internet: www.dot.state.al.us



John R. Cooper TRANSPORTATION DIRECTOR

Kay Ivey GOVERNOR

August 21, 2023

The Honorable Ed Beasley Mayor, City of Luverne P.O. Box 249 Luverne, Alabama 36049

Subject: Annual Inspection Report Frank Sikes Airport

Dear Mayor Beasley:

An inspection of the Luverne (Frank Sikes) Municipal Airport was conducted by personnel of the Alabama Department of Transportation Aeronautics Bureau on June 27, 2023. The purpose of the inspection was to update the information currently on file regarding the airport and to ascertain compliance with the rules and regulations of the Alabama Department of Transportation governing licensed public-use airports within the State of Alabama.

Attached you will find a copy of the Annual Inspection Report. As noted in the report, the airport **<u>does not meet</u>** the requirements for the issuance of an operating license. Once the trees have been removed, please contact this office to schedule a re-inspection.

If you should have any questions concerning the inspection or corrective actions, please do not hesitate to contact Mr. Jason Hare with the Aeronautics Bureau at (334) 353-6223.

Sincerely,

Frank Farmer Chief, Aeronautics Bureau

Copy: Mr. Rans Black, FAA/ADO Mr. Brian Hendry, FAA Mr. Steve L. Defee, Airport Board President

In accordance with the provisions of the Code of Alabama 23-1-357, an inspection of the *Frank Sikes Municipal Airport* was conducted by *Mr. Jason Hare and Mr. Mark Bowron* with the Alabama Department of Transportation Aeronautics Bureau on June 27, 2023.

The inspection was conducted on the airport under the provisions of the Administrative Code Chapter 450-9-1 for the following areas

Aeronautics Administrative Code	Inspection Results	Corrective Action	Notes
Approach & Departure Paths	VIOLATION	There are trees on both RWY 04 and 22	Remove the trees that violate the ALDOT
Administrative Code 450-9-112 (1)		that violate the ALDOT APP/DEP Path.	APP/DEP path of RWY 04 and 22.
Primary Surface	In Compliance	N/A	N/A
Administrative Code 450-9-112 (2)			
Runway Safety Area	VIOLATION	Fill in ruts that were found in the Run-	Ruts were found in the Runway Safety
Administrative Code 450-9-112 (3)		way Safety Area.	Area
Airport Markings	In Compliance	short marking to the taxiway. Additionally, there a	Taxiway markings are in Fair condition.
Administrative Code 450-9-112 (4)	Maintenance		Additionally, there are no hold short mark- ings on taxiway.
Wind Direction Indicator	In Compliance	N/A	N/A
Administrative Code 450-9-112 (5)	Maintenance		
Airport Lighting	In Compliance		During the inspection the lighting system
Administrative Code 450-9-112 (6)	Maintenance		was not able to be turned on via radio.
Runway, Taxiway and Apron Conditions	In Compliance		The Apron is in poor condition, certain areas of the apron are completely failing.
Administrative Code 450-9-112 (7)	Maintenance		
Fueling Area Requirements	VIOLATION	The leak should be repaired, and the	There is an active fuel leak, which is con-
Administrative Code 450-9-112 (8)		contaminated soil should be removed.	taminating the soil under the truck.
Prohibited Activities	In Compliance	Ensure that unauthorized people/	A business adjacent to the airport has been
Administrative Code 450-9-116	Maintenance	businesses are not accessing the airport. known to photograph custom runway.	known to photograph customers on the runway.
Additional Items	In Compliance	N/A	N/A

License Status—<u>SUSPENDED</u>

The corrective actions that may be prescribed in this inspection report do not relieve the airport sponsor from compliance with any other Federal, State or local laws, ordinances or regulations that may be applicable. It is the responsibility of the airport sponsor to be aware of and obey all Federal, State or local laws, ordinances or regulations that may have a bearing on the corrective actions that may be specified in this report.

Code of Alabama 23-1-357(a)... a person or municipality may not operate an airport, restricted landing area, or other navigation facility without a license issued by this Department.

June 27, 2023



ANNUAL INSPECTION REPORT



FRANK SIKES AIRPORT LUVERNE, ALABAMA

Frank Sikes Airport

Approach and Departure Paths—RUNWAY 04

Administrative Code 450-9-1-.12(1)



VIOLATION: There are penetrations to the ALDOT Approach/ Departure Path of Runway 04. Please see Appendix #2 for more information.

Note: Obstructions identified are representative and may not include all existing obstructions.

Frank Sikes Airport

Approach and Departure Paths—RUNWAY 22

Administrative Code 450-9-1-.12(1)



VIOLATION: There are penetrations to the ALDOT Approach/ Departure Path of Runway 22. Please see Appendix #3 for more information.

Note: Obstructions identified are representative and may not include all existing obstructions.

Primary Surface

Administrative Code 450-9-1-.12(2)



Primary Surface <u>meets</u> state licensing standards.

Runway Safety Area

Administrative Code 450-9-1-.12(3)



VIOLATION Runway Safety Area **Does Not Meet** state licensing standards. There are ruts located in the Runway Safety Area. Please repair ruts and ensure that the ground is level and smooth.

Frank Sikes Airport

Airport Markings—Runway

Administrative Code 450-9-1-.12(4)



Runway markings are in **FAIR** condition.

Airport Markings—Taxiway

Administrative Code 450-9-1-.12(4)



Taxiway markings are in **FAIR** condition. Hold short line is missing and should be marked in accordance with FAA AC 150-5300-13B.

Frank Sikes Airport

Airport Markings—Apron

Administrative Code 450-9-1-.12(4)



Apron markings are in **FAIR** condition.

Frank Sikes Airport

Wind Direction Indicator

Administrative Code 450-9-1-.12(5)



Wind direction indicator is in <u>FAIR</u> condition. Please ensure that the windsock is lit for night time operations.

Frank Sikes Airport

Airport Lighting

Administrative Code 450-9-1-.12(6)

An inspection of the lighting system had the following results:

Runway Lights	Inoperable
Taxiway Lights	Inoperable
Threshold Lights	Inoperable
PAPI	Inoperable
REIL	N/A

The airport lighting system **DOES NOT** meet State Licensing Standards for night-time operation. During inspection, the lighting system was not able to be turned on by ALDOT personnel and the airport should be opened for **Daytime VFR Operations Only**. The Runway lights are not placed according to the standards of AC 150/5340-1M.

Runway, Taxiway and Apron Conditions—RUNWAY Administrative Code 450-9-1-.12(7)




Runway surface is in **FAIR** condition.

Runway, Taxiway and Apron Conditions—TAXIWAY Administrative Code 450-9-1-.12(7)



Taxiway surface is in **<u>POOR</u>** condition.

Runway, Taxiway and Apron Conditions—APRON Administrative Code 450-9-1-.12(7)



Apron surface is **<u>POOR</u>** in condition. Extensive longitudinal and transverse cracking, with complete failures in certain places.

Fueling Area Requirements

Administrative Code 450-9-1-.12(8)



One of the fuel trucks is leaking fuel onto the ground contaminating the soil underneath. Also, the State of Alabama Department of Agriculture may have additional requirements for fueling systems that were not considered during this inspection.


Frank Sikes Airport

Prohibited Activities

Administrative Code 450-9-1-.16



There has been a pattern of trespassing on airport property. An airport should only be accessed by the airport personnel, pilots, and the tenants at the airport. There should <u>Never</u> be people trespassing on airport property to take photos on the runway.




APPENDIX 1

FRANK SIKES AIRPORT LUVERNE, AL JUNE 27, 2023 RWY 04 OBSTRUCTION EVALUATION

2. Tree 66' Abv. RWY 909' From Displaced Threshold 196'Right of CL 13:1 Obst. Clrne 7. Tree 71' Abv. RWY 997' From Displaced Threshold 160' Left of CL 14:1 Obst. Clrnc

8. Tree 55' Abv. RWY 813' From Displaced Threshold 185' Left of CL 14:1 Obst. Clrnc



ALDOT APP/DEP PATH

FRANK SIKES AIRPORT LUVERNE, AL JUNE 27, 2023 RWY 22 OBSTRUCTION EVALUATION

3. Tree 60' Abv. RWY
941' From Displaced Threshold
151' Right of CL
15:1 Obst. Clrnc

22

ALDOT APP/DEP Violation

ALDOT APP/DEP PATH

Controlling Obstruction