



- Site 6
- Andrew Rd Intersection Area
 - a. Re-align Andrew Rd and west service road crossing/intersection.
 - b. Install *Reduced Conflict U-Turn* (RCUT) intersection at Hall Mill Rd
 - c. Re-configure left turn lanes and close extra median crossings.
 - d. Install concrete island at service road on eastbound US-90 just pass Andrew Rd to right-in/right-out only.